

## JIRA Bug Creation Template

**Work Type:**

Bug

**Priority:**

Medium

**Severity:**

Minor

**Baseline Version:**

v1.1

**Summary:**

HDMI not detected when STB is powered on

**Description:**

Steps to Reproduce:

1. Power on the STB
2. Observe the HDMI output

Expected: HDMI signal should be detected and display video

Actual: No HDMI signal detected

**Platform Details:**

Amidala Cable DE

**Intermittency:**

Not Intermittent - 100% reproducible

**Customer Impact:**

Customer will not see any output on TV, appears as device not working

**Logs Available:**

Yes, logs captured and available in log repository

**Media Evidence:**

Yes, video attached showing the behavior

**Is Regression:**

Yes

**Is New Functionality:**

No

**Labels:**

Regression, DE TestAmberIssue

**Component:**

Defect\_scrub