

Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To: Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674

FAX: 636-530-9044

BIII To: SAMI ROCK COMPANY LTD

AL-SHATI DISTRICT, KING RD PO BOX 118500 JEDDAH, KSA 21352 SAUDI ARABIA

Account code: 18309A

Invoice number: HNG25-00594

P.O. number:

Due Date:

Registration #: VP-CAI

Invoice date:

8/14/2025 8/14/2025

Payment Type: CIA Terms: Due Upon Receipt

P.O. number:

INVOICE SUMMARY FOR WORK ORDER NUMBER: 43335

Labor: \$2,226.68 \$11.81 Parts: \$343.75 Services: Misc Charges: \$103.29 \$2,685.53 Total: \$2,685.53 Subtotal: Total:

Form 9703

¥204



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To:
Centurion Investments, Inc. d/b/a AVMATS
18377 Edison Avenue
Telephor

1837/ Edison Avenue Chesterfield, MO 63005-3628 (636) 532-2674 Phone Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

AL-SHATI DISTRICT, KING RD PO BOX 118500 JEDDAH, KSA 21352 SAUDI ARABIA Account code: 18309A

Invoice number: HNG25-00422

P.O. number:

Registration #: N1428N

Invoice date:

6/16/2025

Due Date:

6/16/2025

Payment Type: CIA Terms: Due Upon Receipt

P.O. number:

INVOICE SUMMARY FOR WORK ORDER NUMBER: 43190

 Labor:
 \$3,960.00

 Misc Charges:
 \$25,500.00

 Total:
 \$29,460.00

 Subtotal:
 \$29,460.00

 Progress Billing:
 -\$29,460.00

 Total:
 \$0.00

Page 1 of 3



Work Order Invoice

750 North Beechcraft United States

Please Remit To: Chesterfield, MISSOURI 63005 Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

WO #: 43190

Invoice Number: HNG25-00422

INVOICE SUMMARY FOR WORK ORDER NUMBER: 43190

	Time & Materials	Flat Rate	Total
Labor:	\$0.00	\$3,960.00	\$3,960.00
Misc Charges:	\$25,500.00		\$25,500.00
Total:	\$25,500.00	\$3,960.00	\$29,460.00
Subtotal:			\$29,460.00
Progress Billing:			-\$29,460.00
Total:			=====================================

* Credit, debit, and bank card transactions are subject to a convenience fee. AVMATS accepts all major credit cards, wire-transfer, ACH and Company Checks. Please use the link below to arrange or remit payment for this invoice:

> Pay with **AVHATS PAY** https://www.avmats.com/



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To: Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

AL-SHATI DISTRICT, KING RD PO BOX 118500 JEDDAH, KSA 21352 SAUDI ARABIA

18309A Account code:

Invoice number: HNG25-00282

P.O. number:

Registration #: N1428N

Invoice date:

4/22/2025

Due Date:

4/22/2025

Payment Type: CIA Terms: Due Upon Receipt

P.O. number:

INVOICE SUMMARY FOR WORK ORDER NUMBER: 43144

\$19,676.25 Labor: Parts: \$2,556.28 \$13,958.40 Services: \$36,190.93 Total: \$36,190.93 Subtotal: **Progress Billing:** -\$31,778.40



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To: Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

BIII To: SAMI ROCK COMPANY LTD

G-IV-SP

WO #: 43144

Invoice Number: HNG25-00282

Item: 1.

G-IV SP Part/Model #:

Team Leader: Time & Materials

\$36,190.93

Serial Number:

Discrepancy 1.1.

Comply with Preliminary Inspection

Resolution: Preliminary Inspection Completed

Discrepancy 1.2.

Work Order Miscellaneous Charges

Resolution: All shop consumables to include but not limited to drill bits, screw extractors, abrasive wheels and cloth, caps & plugs, brushes, masking materials, gloves, rags, masking tape, primer, adhesives, solvents, lubricants, greases, air gases, calibration, and EPA

disposal fee. Paragraph 11 of Standard Terms and Conditions.

Discrepancy 1.3.

Research aircraft records

Resolution: Performed by Avlation Technical Advisor

Time & Materials Total \$13,958.40 \$13,958.40 \$13,958.40 \$13,958.40

Services:

Services:

Total:

Quantity Sell Price Extended Ref. No. Description 1.00 \$13,958.40 \$13,958.40 Aircraft Pre-buy Logbook Review and Evaluation 1.3 #1



Work Order Invoice

750 North Beechcraft United States

Please Remit To: Chesterfield, MISSOURI 63005 Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

BIII To: SAMI ROCK COMPANY LTD

WO #: 43144

Invoice Number: HNG25-00282

Discrepancy	1.4.	Comply with customer selected PPI inspection tasks
Bassluktons	4T4 D	aulu Mau

Resolution:	ATA	Description
-------------	-----	-------------

231001 Avionics - Functional Ramp Test / Inspection

273003 Elevator Free Play - Inspection

291019 Filter Delta-P Buttons - Detailed Inspection

291093 Combined Hydraulic Filter (Engine-Driven Pump Bypass) - Inspection Flight Hydraulic Filter (Engine-Driven Pump Bypass) - Inspection 291097

Auxiliary System Differential Pressure Indicator (Pressure) - Detailed Inspection 293001 293002 Utility System Differential Pressure Indicator (Pressure) - Detailed Inspection

Wing Anti-Ice (Left) - Operational Test Wing Anti-Ice (Right) - Operational Test 301005 301006

302005 Cowl Anti-Ice (Left Engine) - Operational Test 302006 Cowl Anti-Ice (Right Engine) - Operational Test

Hydromechanical Analog Brake (Hmab) Antiskid Control System - Operational Test 324204

Hydromechanical Analog Brake Wear (Hmab) - Detailed Inspection 324206

324207 Parking / Emergency Brake - Operational Test

325001 Nose Wheel Steering - Functional Test

490002 APU - APU GTCP36-100(G) - Operational Test

APU - APU Fuel Filter GTCP36-100(G) - Detailed Inspection 493031

521009 Baggage Door Inflatable Seal System - Operational Test

532053 Torque Box, Main Landing Gear Door Support - Detailed Inspection

APU Enclosure FS 605 - FS 635 Internal - Zonal Inspection 532066

532071 External Lower Fuselage FS -4 Thru FS 596 Viewed from Ground - Zonal Inspection

External Upper Fuselage FS 44 - FS 596 Vlewed from Ground - Zonal Inspection 532073

532075 Aft Fuselage and Empennage FS 596 - FS 864 External (Viewed from Ground) - Zonal Inspection

Nose Gear Wheel Well FS 44 - FS 119 - Zonal Inspection 534021

534022 Main Gear Wheel Wells FS 452 - FS 496 - Zonal Inspection

535014 Aft Fuselage Above Floor FS 596 - FS 812 Internal - Zonal Inspection

541029 Pylon External View from Ground (Left) - Zonal Inspection 541030 Pylon External View from Ground (Right) - Zonal Inspection

551101 Horizontal Stabilizer General Skins - General Visual Inspection

553050 Vertical Stabilizer General Skins - General Visual Inspection

570003 Wing Lower Surface (Left) - Zonal Inspection

570004 Wing Lower Surface (Right) - Zonal Inspection

Wing Rear Beam (Left) - Zonal Inspection Wing Rear Beam (Right) - Zonal Inspection 571045

571046

573015 Winglet Blade View from Ground (Left) - Zonal Inspection

573016 Winglet Blade View from Ground (Right) - Zonal Inspection

Wing Leading Edge External Bi 35.80 - Rbs 433 Inboard of Nav Light (Left) - Zonal Inspection Wing Leading Edge External Bi 35.80 - Rbs 433 Inboard of Nav Light (Right) - Zonal Inspection 574007

574008

Lower Wing Trailing Edge (Left) - Zonal Inspection 575105

575106 Lower Wing Trailing Edge (Right) - Zonal Inspection

710007

Powerplant / Nacelle External (View from Ground, Left) - Zonal Inspection
Powerplant / Nacelle External (View from Ground, Right) - Zonal Inspection 710008

Powerplant Nose Cowls Internal (View from Ground, Left) - Zonal Inspection 711005 711006 Powerplant Nose Cowls Internal (View from Ground, Right) - Zonal Inspection

Oil Pressure Differential Electrical Circuit (Oil Filter Bypass Indication) - Operational Test 774927

No. 1 Engine - Engine Chip Detector - Visual Check 774955

774955 (774956) No. 2 Engine - Engine Chip Detector - Visual Check

	Time & Materials	Flat Rate	Total
Labor:	\$0.00	\$16,500.00	\$16,500.00
Parts:	\$2,556.28	\$0.00	\$2,556.28
Total:	\$2,556.28	\$16,500.00	\$19,056.28

Ref. No.	Part number:	Description	Quantity	Sell price	Extended
1.4 #1	MS28774-028	RETAINERS	1	\$0.65	\$0.65
1.4 #2	MS28774-024	RETAINER	1	\$2.33	\$2.33
1.4 #3	MS28774-138	O RING	1	\$1.84	\$1,84
1.4 #4	AC-B451F-8	FILTER	1	\$200.00	\$200.00
1.4 #5	AC-B451F-12	FILTER	1	\$391.75	\$391.75
1.4 #6	AC-B451F-16	FILTER	1	\$1,573.21	\$1,573.21



Work Order Invoice

750 North Beechcraft United States

Please Remit To: Chesterfield, MISSOURI 63005 Centurion Investments, Inc. d/b/a AVMATS

18377 Edison Avenue Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

WO #: 43144

Invoice Number: HNG25-00282

Ref. No.	Part number:	Description	Quantity	Sell price	Extended
1.4 #7	AS3582-112	O-RING	1	\$1.32	\$1.32
1.4 #8	AS43013-013	Seal Ring	1	\$8.00	\$8.00
1.4 #9	BR49120	RING	12	\$9.38	\$112.56
1.4 #10	3882440-1	FUEL FILTER	1	\$245.70	\$245.70
1.4 #11	S9412-138	O'RING	1	\$7.70	\$7.70
1.4 #12	S9412-212	O-RING	1	\$3.79	\$3.79
1.4 #13	MS9388-014	O RING	1	\$0.96	\$0.96
1.4 #14	M83248-1-124	O RING	1	\$3.47	\$3.47
1.4 #15	M83248-1-904	O RING	1	\$3.00	\$3.00

Discrepancy 1.5. Ground engine run and taxi check

- Resolution: Compiled with engine run and taxl: - Verification that engines make rated power of the day and all parameters are normal
 - Cabin pressurization system and temperature control checkout
 - AC and DC power generation system checkout
 - Cockpit, cabin and external lighting checkout
 - Wing, inlet and nacelle anti-ice checkout
 - Anti-skid and emergency braking checkout
 - APU operational checkout (bleed air and power generation)

	Flat Rate	Total
Labor:	\$1,320.00	\$1,320.00
Total:	\$1,320.00	\$1,320.00

Discrepancy 1.6.

Overtime to support requested out date

Resolution: TBD

	Flat Rate	Total
Labor:	\$1,856.25	\$1,856.25
Total:	\$1,856.25	\$1,856.25



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To:
Centurion Investments, Inc. d/b/a AVMATS
18377 Edison Avenue
Telephor

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

BIII TO: SAMI ROCK COMPANY LTD

WO #: 43144

Invoice Number: HNG25-00282

INVOICE SUMMARY FOR WORK ORDER NUMBER: 43144

	Time & Materials	Flat Rate	Total
Labor:	\$0.00	\$19,676.25	\$19,676.25
Parts:	\$2,556.28	\$0.00	\$2,556.28
Services:	\$13,958.40	\$0.00	\$13,958.40
Total:	\$16,514.68	\$19,676.25	
Subtotal:			\$36,190.93
Progress Billing:			-\$31,778.40
Total:			=====================================

* Credit, debit, and bank card transactions are subject to a convenience fee. AVMATS accepts all major credit cards, wire-transfer, ACH and Company Checks. Please use the link below to arrange or remit payment for this invoice:

Pay with **AVMATS PAY** https://www.avmats.com/

Form 9703



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To:
Centurion Investments, Inc. d/b/a AVMATS
18377 Edison Avenue
Telephor

18377 Edison Avenue Chesterfield, MO 63005-3628 (636) 532-2674 Phone Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

AL-SHATI DISTRICT, KING RD PO BOX 118500 JEDDAH, KSA 21352 SAUDI ARABIA Account code: 18309A

Invoice number: HNG25-00570

P.O. number:

Registration #: N1428N

Invoice date: 8/1/2025

Due Date:

8/1/2025

Payment Type: Wire Transfer / ACH Terms: Due Upon Receipt

P.O. number:

INVOICE SUMMARY FOR WORK ORDER NUMBER: 43252

 Labor:
 \$122,875.50

 Parts:
 \$38,350.79

 Services:
 \$48,962.53

 Misc Charges:
 \$5,000.00

 Total:
 \$215,188.82

 Freight:
 \$183.37

 Subtotal:
 \$215,372.19

Total: \$215,372.19

Form 9703



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To:
Centurion Investments, Inc. d/b/a AVMATS
18377 Edison Avenue
Telephore

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

WO #: 43252 Invoice Number: HNG25-00570 Bill To: SAMI ROCK COMPANY LTD G-IV SP Part/Model #: Item: 1. G-IV-SP Serial Number: Team Leader: Time & Materials \$215,372.19 Discrepancy 1.1. Comply with Preliminary Inspection Resolution: Preliminary Inspection Completed Work Order Miscellaneous Charges Discrepancy 1.2. Resolution: All shop consumables to include but not limited to drill bits, screw extractors, abrasive wheels and cloth, caps & plugs, brushes, masking materials, gloves, rags, masking tape, primer, adhesives, solvents, lubricants, greases, air gases, calibration, and EPA disposal fee. Paragraph 11 of Standard Terms and Conditions. Time & Materials Total Misc Charges: \$5,000.00 \$5,000.00 Total: \$5,000.00 \$5,000.00



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To:
Centurion Investments, Inc. d/b/a AVMATS
18377 Edison Avenue Telephor

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

WO #: 43252

Invoice Number: HNG25-00570

Discrepancy 1.3. Comply with Mechanic Sign Off Report dated 1 June 2025 pages 1 thru 28

Work Order Invoice

750 North Beechcraft

Please Remit To: Chesterfield, MISSOURI 63005
United States
Centurion Investments, Inc. d/b/a AVMATS
18377 Edison Avenue 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

WO #: 43252

Invoice Number: HNG25-00570

Resolution:	ATA Des	scription
	216097	AIR Cycle Machine Compressor Outlet Temperature (Overheat) Switch (Left) - Functional Test
	216098	AIR Cycle Machine Compressor Outlet Temperature (Overheat) Switch (Right) - Functional Test
	240160	Emergency Lighting / Power System - Operational Test
	232399	Cockpit Voice Recorder Underwater Locator Beacon (Ulb) - Cleaning
	232400	Cockpit Voice Recorder Underwater Locator Beacon (Ulb) - Operational Testing
	240160	Emergency Lighting / Power System - Operational Test
	240250	Emergency Securapiane Battery No. 1 (SELF-Test) - Operational Test
	240251	Emergency Securapiane Battery No. 2 (SELF-Test) - Operational Test
	240252	Emergency Securaplane Battery No. 3 (SELF-Test) - Operational Test
	240253	Emergency Securapiane Battery No. 4 (SELF-Test) - Operational Test
	243139	Hawker Lead ACID Battery No. 1 (Capacity Check) - Functional Test
	243140	Hawker Lead ACID Battery No. 2 (Capacity Check) - Functional Test
	250063	Protective Breathing Equipment (No. 1) - Detailed Inspection
	251020	Smoke Hoods - Detailed Inspection
	251036	Flashlight(S) - Operational Test
	251036	Flashlight(S) - Operational Test
	251115	Crew Seats Locking Mechanism and Seat Tracks - Detailed Inspection
	252555	Passenger Seat Attachments / Locking - Detailed Inspection
	256101	Emergency Locator Transmitter - Operational Test (FAR 91.207)
	256201	Life Vest(S) (Expiration Date) - Detailed Inspection
	256204	Life Vest(S) - Restore
	256266	Life Raft(S) Expiration Date - Detailed Inspection
	256312	First AID / Medical Kits - Detailed Inspection
	256313	First AID / Medical Kit(S) Time Limited Supply - Discard
	256341	Med-Alre Kit-Insp
	256358	Defibrillator Pads #2
	261201	Engine FIRE Extinguishing Firing Circuitry Integrity - Functional Check
	262065	FIRE Bottle (Left) - Weight Check
	262070	FIRE Bottle (Right) - Weight Check
	262116	Engine and APU FIRE Extinguishing Explosive Cartridges (Left Forward) - Discard (Manufactured Life)
	262118	Engine and APU FIRE Extinguishing Explosive Cartridges (Left Aft) - Discard (Manufactured Life)
	262120	Engine and APU FIRE Extinguishing Explosive Cartridges (Right Forward) - Discard (Manufactured Life)
	262122	Engine and APU FIRE Extinguishing Explosive Cartridges (Right Aft) - Discard (Manufactured Life)
	262153	FIRE Pull Handle (Fuel / Hydraulic Shutoff) (Left) - Operational Test
	262154	FIRE Pull Handie (Fuei / Hydraulic Shutoff) (Right) - Operational Test
	262621	Portable FIRE Extinguisher (Right Cockpit) - Weight Check
	262623	Portable FIRE Extinguisher (Aft Cabin) - Weight Check
	262625	Portable FIRE Extinguisher (Aft Lavatory) - Weight Check
	262631	Portable FIRE Extinguisher (Right Cockpit) - Detailed Inspection
	262633	Portable FIRE Extinguisher (Aft Cabin) - Detailed Inspection
	262635	Portable FIRE Extinguisher (Aft Lavatory) - Detailed Inspection
	262690	Trash Receptacle FIRE Extinguishing Bottle (Aft Lavatory) - Weight Check
	262691	Trash Receptacle FIRE Extinguishing Bottle (Aft Galley) - Weight Check
	262704	Ext, Entertainment-Insp
	262720	Trash Receptacle Enclosure (Aft Galley) - Detailed Inspection
	262722	Trash Receptacle Enclosure (Aft Lavatory) - Detailed Inspection
	262724	Trash Receptacie FIRE Extinguisher Nozzies (Aft Lavatory) - Detailed Inspection
	262726	Trash Receptacle FIRE Extinguisher Nozzies (Aft Galley) - Detailed Inspection
	271046	Alleron Control and Trim Cables In Main Wheel Wells and Wing Rear Beam - Detailed Inspection
	272026	Rudder Control and Trim Cables In Main Wheel Well - Detailed Inspection
	273038	
	275019	Wing Flap (Left) - Lubrication
	275020	Wing Flap (Right) - Lubrication
	275023	Wing Flap Traveling Nut (Left) - Lubrication
	275024	Wing Flap Traveling Nut (Right) - Lubrication
	276013	Spoller Hinges (Lh Inboard / Middle / Outboard) - Lubrication
	276014	Spoiler Hinges (Rh Inboard / Middle / Outboard) - Lubrication
	276088	Speed Brake Cable Assemblies In Main Wheel Well / Wing Rear Beam - Detailed Inspection
	277012	Throttle Lever Gust Lock Protection - Functional Test
	280008	Microbiological Contamination Test of Fuel Tank - Special Detailed Inspection
	282084	Engine / APU Fuel Feed Line Witness Port (Left) - Detailed Inspection
	282085	Engine / APU Fuel Feed Line Witness Port (Right) - Detailed Inspection
	312015	Pilot Clock Battery - Replacement
	312016	Copilot Clock Battery - Replacement
	313032	Flight Data Recorder Underwater Locator Beacon (DK120) - Operational Test
	316006	Electronic Display System Automatic Reconfiguration MODE - Operational Test (Spz-8400)
	316007	Electronic Display System Manual Reconfiguration MODE - Operational Test
	316009	Symbol Generator Switching - Operational Test
	320004	Main Landing Gear and Systems (Left) - Lubrication
	320005	Main Landing Gear and Systems (Right) - Lubrication
	320006	Nose Landing Gear and Systems - Lubrication
	320008	Nose and Main Landing Gear and Landing Gear Doors - Zonal Inspection



Work Order Invoice

750 North Beechcraft United States

Please Remit To: Chesterfield, MISSOURI 63005 Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

WO #: 43252

Invoice Number: HNG25-00570

320009	Main Landing Gear Corrosion Inhibiting Compound Reapplication - (Left)
320034	Nose Landing Gear Corrosion Inhibiting Compound Reapplication
322042	Nose Gear Axle Assembly - Detailed Inspection
322401	Brake Control System Hydraulic Fuse (Left, Outboard No. 1) - Operational Check
322402	Brake Control System Hydraulic Fuse (Left, Inboard No. 2) - Operational Check
322403	Brake Control System Hydraulic Fuse (Right, Inboard No. 3) - Operational Check
322404 322434	Brake Control System Hydraulic Fuse (Right, Inboard No. 4) - Operational Check Main Landing Gear Bungee (Left) - Lubrication
322435	Main Landing Gear Bungee (Right) - Lubrication
334062	Navigation Position Lights Lens - Detailed Inspection
340100	Reduced Vertical Separation Minimum (RVSM) Monitoring Policy
341014	Standby Altimeter - Calibration / Test
341074	Pilot Pitot / Static and Dadc - Functional / Leak Test
341075	Standby Pitot / Static System - Functional / Leak Test
341085	Dadc No. 1 - Calibration
341086	Dade No. 2 - Calibration Coollet Pitch / Static and Dade - Functional / Leak Test
341094 344051	Copilot Pitot / Static and Dadc - Functional / Leak Test Iru No. 1 Cooling Fan Filter - Inspection / Clean
344052	Iru No. 2 Cooling Fan Filter - Inspection / Clean
344055	Iru No. 3 Cooling Fan Filter - Inspection / Clean
344095	Inertial Reference Unit No. 1 Securaplane Battery (Bullt-In Test Equipment / Battery Level Test) - Operational Test
344096	Inertial Reference Unit No. 2 Securapiane Battery (Built-In Test Equipment / Battery Level Test) - Operational Test
345311	ATC No. 1 - Functional Test / Inspection (FAR 91.413)
351021	Crew Oxygen Mask / Regulator (Pilot) - Restore
353052	Portable Oxygen Bottle / Mask - Detailed Inspection
491301	Auxiliary Power Unit Drain Collectors GTCP36-100(G) - Operational Check APU - APU Turbine Plenum and Combustor Drain Orifice GTCP36-100(G) - Operational Test
492012 521003	Main Entrance Door - Lubrication
521003	Main and Baggage Door Inflatable Seals - Detailed Inspection
521016	Cabin Doors and Emergency Exits (View from Ground) - Zonal Inspection
521051	Door Seal Pressure Regulator - Functional Test
521055	Door Seal Regulator and System (Aircraft Not Having ASC 424) - Inspection
521080	Inflatable Door Seal - Purging Procedure
523004	Baggage Door - Lubrication
524016	Tail Compartment Door - Zonal Inspection
527005 527008	Main Entrance Door Warning System - Operational Test Baggage Door Warning System - Operational Test
532039	Baggage Compartment Below Floor FS 539 - FS 596 Internal - Zonal Inspection
532066	APU Enclosure FS 605 - FS 635 Internal - Zonal Inspection
532071	External Lower Fuselage FS -4 Thru FS 596 Viewed from Ground - Zonal Inspection
532073	External Upper Fuselage FS 44 - FS 596 Viewed from Ground - Zonal Inspection
532075	Aft Fuselage and Empennage FS 596 - FS 864 External (Viewed from Ground) - Zonal Inspection
532078	Upper Antenna Substructures FS 133 - FS 596 - Detailed Inspection
532903	Main Entrance Door Actuator Attach Fitting (Borescope) - Inspection
533010	Static Ports (Reduced Vertical Separation Minimums) - Inspection
534021 534022	Nose Gear Wheel Well FS 44 - FS 119 - Zonal Inspection Main Gear Wheel Wells FS 452 - FS 496 - Zonal Inspection
534202	Flat Pressure Bulkhead Forward and Aft Face Above Floor (FS 596) - Special Detailed Inspection
535013	Aft Cabin Below Floor FS 498 - FS 539 Internal - Zonal Inspection
535014	Aft Fuselage Above Floor FS 596 - FS 812 Internal - Zonal Inspection
539518	Upper Antenna and Penetration Interface - Detailed Inspection
	Pylon Internal (Left) - Zonal Inspection
541028	Pylon Internal (Right) - Zonal Inspection
541029	Pylon External View from Ground (Left) - Zonal Inspection
541030 554001	Pylon External View from Ground (Right) - Zonal Inspection Rudder Assembly Internal - Detailed Inspection
561101	Windshield Weather Seal (Hump Seal) (Left) - Detailed Inspection
561102	Windshield Weather Seal (Hump Seal) (Right) - Detailed Inspection
571027	Wing Tank Internal Inboard 3 Panels Each Wing - Detailed Inspection
571045	Wing Rear Beam (Left) - Zonal Inspection
571046	Wing Rear Beam (Right) - Zonal Inspection
575015	Wing Lower Cove Panel and Flap Well Drain Holes (Left) - Enhanced Zonal Inspection
575016	Wing Lower Cove Panel and Flap Well Drain Holes (Right) - Enhanced Zonal Inspection
711003	Powerplant Nose Cowls Internal (Left) - Zonal Inspection Powerplant Nose Cowls Internal (Right) - Zonal Inspection
711004 783033	Thrust Reverser Unlock (Left) - Operational Test
783034	Thrust Reverser Unlock (Right) - Operational Test
	ted (Mandatory)

	Time & Materials	Flat Rate	Total
			1
Labor:	\$0.00	\$80,355.00	\$80,355.00



Work Order Invoice

United States

750 North Beechcraft Chesterfield, MISSOURI 63005 Please Remit To: Centurion Investments, Inc. d/b/a AVMATS

18377 Edison Avenue Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

BIII TO: SAMI ROCK COMPANY LTD		WO #: 4325	2 Invoice Number: HNG25-00
Parts:	\$20,533.28	\$0.00	\$20,533.28
Services:	\$3,634.38	\$0.00	\$3,634.38
Freight:	\$87.06		\$87.06
Total:	\$24,254.72	\$80,355.00	\$104,609.72

Ref. No.	Part number:	Description	Qu	antity	Sell price	Extended
1.3 #1	ALLPRUS-0350-050-0025	AliProtect Nonwoven, 20" W rolls packaged in two		1.00	\$464.83	\$464.83
1.3 #2	MICROBMONITOR2	packs KIT, TEST, for aviation fuels		2	\$73.00	\$146,00
1.3 #3	BL171050-01 (SHEET)	GASKET MATERIAL, ANTENNA		2	\$8,229.66	\$16,486.80
			Freight:	27.4	48	
1.3 #4	S9026E-112	SEAL		2	\$1.21	\$2.42
1.3 #5	36152	TERMINAL #6 RED		2	\$0.33	\$0.66
1.3 #6	36154	TERMINAL		2	\$0.25	\$0.50
1.3 #7	31890	TERMINAL, RING, #8 Red		2	\$0.50	\$1.00
1.3 #8	1646B	FITTING, GREASE		2	\$176.40	\$412.38
			Freight:	59.	58	
1.3 #9	AEROSHELL 7	CARTRIDGE 14 OZ		1	\$33.63	\$33.63
1.3 #10	PR1422B2	SEALANT, 136 GRAM 6 OZ SEMKIT		4	\$109.68	\$438.72
1.3 #11	GAB511GA3-3	BOLT		4	\$13.47	\$53.88
1.3 #12	MS24694-S66	SCREW		6	\$1.05	\$6.30
1.3 #13	NAS1580C3T5	Bolt		1	\$2.19	\$2.19
1.3 #14	MS21060L3	NUTSELF LOCKING		1	\$2.64	\$2.64
1.3 #15	MICROBMONITOR2	KIT, TEST, for aviation fuels		1	\$73.00	\$73.00
1.3 #16	PR1422B2	SEALANT, 136 GRAM 6 OZ SEMKIT		3	\$109.68	\$329.04
1.3 #17	MS35214-29	SCREW, BRASS		1	\$0.47	\$0.47
1.3 #18	GAB511GA3-3	BOLT		4	\$13.47	\$53.88
1.3 #19	PR1422B2	SEALANT, 136 GRAM 6 OZ SEMKIT		1	\$109.68	\$109.68
1.3 #20	CR3213-4-2	RIVET		2	\$0.62	\$1.24
1.3 #21	PR1422B2	SEALANT, 136 GRAM 6 OZ SEMKIT		1	\$109.68	\$109.68
1,3 #22	5606	HYD FLUID/QT MIL-PRF-5606H (756), 12QTS/CS		1	\$19.22	\$19.22
1.3 #23	1728B	GREASE FITTING		1	\$0.75	\$0.75
1.3 #24	MS29512-06	O RING		1	\$0.99	\$0.99
1,3 #25	PR1422B1/2-2.5OZ	SEALANT, 136 GRAM 2.5 OZ SEMKIT		1	\$96.83	\$96.83
1.3 #27	P01074-101	LIFE VEST		15	\$104.33	\$1,564.95
1.3 #28	P01074-101	LIFE VEST		2	\$104.33	\$208.66

Ref. No.	Description	Quantity	Sell Price	Extended
1.3 #2	Overhaul	1.00	\$2,087.50	\$2,087.50
Part	Ref: MC10-15-157 O2 MASK			
1.3 #3	CAPACITY CHECK	1.00	\$618.75	\$618.75
Part	Ref: 9750W0370-3 BATTERY			
1.3 #4	CAPACITY CHECK	1.00	\$928.13	\$928.13
Part	Ref: 9750W0370-3 BATTERY			



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To:
Centurion Investments, Inc. d/b/a AVMATS
19277 Edison Avanua

18377 Edison Avenue Chesterfield, MO 63005-3628 (636) 532-2674 Phone Telephone 636-532-2674 FAX: 636-530-9044

BIII To: SAMI ROCK COMPANY LTD

WO #: 43252

Invoice Number: HNG25-00570

Discrepancy 1.4.

1.4. Change aircraft registration to VP-CAI

Painted on both engine cowlings and in Vinyl on the left lower wing

Resolution: Change alrcraft registration to VP-CAI

Painted on both engine cowlings and In Vinyl on the left lower wing

	Time & Materials	Flat Rate	Total
Labor:	\$0.00	\$14,850.00	\$14,850.00
Parts:	\$2,243.50	\$0.00	\$2,243.50
Services:	\$8,115.39	\$0.00	\$8,115.39
Total:	\$10,358.89	\$14,850.00	\$25,208.89

Parts:

Ref. No.	Part number:	Description	Quantity	Sell price	Extended
1,4 #1	PRD800X	8000IM06036CAQ11B PPG BLUE	1	\$520.80	\$520.80
1.4 #2	CA8800/I1050 GAL	PAINT, PPG MATTERHORN WHITE, GAL	1	\$667.80	\$667.80
1.4 #3	CA8800Z	ACTIVATOR, GALLON	1.00	\$689.19	\$689.19
1.4 #4	CT4 REDUCER	REDUCER	1	\$365.71	\$365.71
Services:					
Ref. No.	Description		Ouantity	Sell Price	Extended

Ref. No.	Description	Quantity	Sell Price	Extended
1.4 #1	SPRAY MASK, TEMP REG NUMBER & VINYL NUMBER	1.00	\$584.39	\$584.39
1.4 #2	Vinyl Name	1.00	\$31.00	\$31.00
1.4 #3	DAR SERVICES	1.00	\$7,500.00	\$7,500.00

Discrepancy 1.5. Replace the metal registration plate and cockpit registration placard with the new registration

Resolution: Replace the metal registration plate and cockpit registration placard with the new registration

	Flat Rate	Total
Labor:	\$990.00	\$990.00
Parts:	\$200.00	\$200.00
Total:	\$1,190.00	\$1,190.00

Discrepancy 1.6. Restrap Avionics to reflect the new registration VP-CAI

Resolution: Restrap Avionics to reflect the new registration VP-CAI

	Time & Materials	Flat Rate	Total
Labor:	\$0.00	\$4,950.00	\$4,950.00
Parts:	\$220.78	\$0.00	\$220.78
Total:	\$220.78	\$4,950.00	\$5,170.78

Ref. No.	Part number:	Description	Quantity	Sell price	Extended
1.6 #1	PL50-1	TPS COAXIAL CONNECTOR	1	\$220.78	\$220.78



Work Order Invoice

750 North Beechcraft United States

Please Remit To: Chesterfield, MISSOURI 63005 Centurion Investments, Inc. d/b/a AVMATS

18377 Edison Avenue Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

WO #: 43252

Invoice Number: HNG25-00570

Discrepancy 1.7.

Send out both the aircraft ELT and life rafts to to be reprogramed to the new registration VP-CAI, and UK country

Resolution: Send out both the aircraft ELT and life rafts to to be reprogramed to the new registration VP-CAI, and UK country code

	Time & Materials	Flat Rate	Total
Labor:	\$0.00	\$990.00	\$990.00
Services:	\$4,000.26	\$0.00	\$4,000.26
Total:	\$4,000.26	\$990.00	\$4,990.26

Services:

Ref. No.	Description	Quantity	Sell Price	Extended
1.7 #1	ReStrap & Reprogram	1.00	\$2,000.13	\$2,000.13
Part R	ef: 1218FAUL-330-1-127 LIFE RAFT			
1.7 #2	ReStrap & Reprogram	1.00	\$2,000.13	\$2,000.13
Part R	ef: 1218FAUL-330-1-12 LIFE RAFT			
1.7 #3	REPROGRAM N NUMBER	1.00	\$0.00	\$0.00
Part R	ef: 453-5000-366 EMERGENCY LOCATOR TRANSMITTER			
1.7 #4	REPROGRAM N NUMBER	1.00	\$0.00	\$0.00
Part R	ef: 453-5000-366 EMERGENCY LOCATOR TRANSMITTER			

Discrepancy 1.8. Welgh aircraft with new registration on documentation

Resolution: Weigh aircraft with new registration on documentation

	Flat Rate	Total
Labor:	\$4,290.00	\$4,290.00
Total:	\$4,290.00	\$4,290.00

Discrepancy 1.9.

Install customer logo on tall and next to door and clear coat edges

(Logo decal will be customer supplied)

Resolution: Hold per customer

Discrepancy 1.10. Comply with a compass swing and provide a new compass correction card with the new registration documented.

Resolution: Comply with a compass swing and provide a new compass correction card with the new registration documented.

	Flat Rate	Total
Labor:	\$660.00	\$660.00
Total:	\$660.00	\$660.00



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To: Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

BILL TO: SAMI ROCK COMPANY LTD

WO #: 43252

Invoice Number: HNG25-00570

Discrepancy 1.11.

Ceramic Coating, Exterior Clean & Buff Flaps

Brightwork

Resolution: Ceramic Coating, Exterior Clean & Buff Flaps

Brightwork

Fiat Rate Total Services: \$31,212.50 \$31,212.50 Total: \$31,212.50 \$31,212.50

Services:

Ref. No. Description Quantity 1.11 #1 CERAMIC COATING, EXTERIOR CLEAN & BUFF FLAPS 1.00 1.00 1.11 #2 **BRIGHTWORK**

Discrepancy 1.12. Provide customer with FMS software number (will begin with FMS) and DU Software number (SW)

Resolution: For the G-IV, s/n 1428 for Sami Rock, the FMS software version is NZ6.1.1. Five of the displays list software

K542584A00-03(2.0.2), and one display lists K542584A00-04(2.0.3)

Total **Time & Materials** \$153.45 Labor: \$153.45 Total: \$153.45 \$153.45

Discrepancy 1.13. MedAire Kit expires October 2025 (Advise Customer)

Resolution: provided new kit

Time & Materials Total Parts: \$812.00 \$812.00 Total: \$812.00 \$812.00

Parts:

Description Quantity Sell price Extended Ref. No. Part number: \$812.00 1.13 #1 AFAK 1.0 FIRST AID KIT, MEDAIRE \$812.00

Discrepancy 1.14. AED Pad Pak expires December 2025 (Advise Customer)

Resolution: Replace as required.

Total Time & Materials Parts: \$787.90 \$787.90 Total: \$787.90 \$787.90

Ref. No.	Part number:	Description	Quantity	Sell price	Extended
1.14 #1	989803139261	PHILLIPS FRX SMART PAD II	2	\$106.95	\$213.90
1.14 #2	M5070A	PHILIPS FRX AED REPLACEMENT BATTERY	2	\$287.00	\$574.00



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To:
Centurion Investments, Inc. d/b/a AVMATS
18377 Edison Avenue Telephor

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Invoice Number: HNG25-00570 WO #: 43252 Bill To: SAMI ROCK COMPANY LTD Discrepancy 1.15. Lay out all the log books in chronological order to be performed by AVMATS QC Resolution: Lay out all the log books in chronological order to be performed by AVMATS QC Total Flat Rate \$330.00 \$330.00 Labor: Total: \$330.00 \$330.00 Provide current interior components burn certifications to be completed by AVMATS QC Discrepancy 1.16. Resolution: Provided Flat Rate Total Labor: \$330.00 \$330.00 Total: \$330.00 \$330.00 Discrepancy 1.17. Place current weight and balance and equipment list on table next to log books to be performed by AVMATS QC Resolution: Provided. Flat Rate Total \$82.50 \$82.50 Labor: Total: \$82.50 \$82.50 Discrepancy 1.18. Provide a current AD report from CMP POC to provide Resolution: Provided Flat Rate Total Labor: \$82.50 \$82.50 Total: \$82.50 \$82.50 Verify all Interior and exterior placards are installed on the aircraft - MXS to complete Discrepancy 1.19. Resolution: Completed **Time & Materials** Total Labor: \$721.05 \$721.05 Total: \$721.05 \$721.05

Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To: Centurion Investments, Inc. d/b/a AVMATS

18377 Edison Avenue Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

BIII To: SAMI ROCK COMPANY LTD WO #: 43252 Invoice Number: HNG25-00570 Discrepancy 1,20. Standby Altimeter sticks at 5 and 6 O'Clock position with 100 Degree Needle. Ascending and Descending. Resolution: Replaced with overhauled unit. Time & Materials Total Parts: \$11,875.00 \$11,875.00 Freight: \$96.31 \$96.31 Total: \$11,971.31 \$11,971.31 Parts: Quantity Sell price Extended Ref. No. Part number: Description 64111-952-1 ALTIMETER \$0.00 \$96.31 1.20 #1 96.31 Freight: **ALTIMETER** \$11,875.00 \$11,875.00 1.20 #2 64111-952-1 Discrepancy 1.21. Water damage to floor board panel LTR69 in Baggage. Resolution: Repaired as required. **Time & Materials** Total \$1,031.25 \$1,031.25 Labor: Total: \$1,031.25 \$1,031.25 Discrepancy 1.22. #3 IRU filter disintegrating. P/N 26000790-101 Resolution: Replaced with new. Total **Time & Materials** Parts: \$509.24 \$509.24 Total: \$509.24 \$509.24 Parts: Quantity Sell price Extended Part number: Description Ref. No. \$509.24 \$509.24 26000790-101 FILTER, IRU BLOWER VENTILATION 1.22 #1 Discrepancy 1.24. LH fwd crew cabinet hardware loose. Resolution: Secured hardware as required. **Time & Materials** Total \$219.45 \$219,45 Labor:

Total:

Form 9703

\$219.45

\$219.45



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To: Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

BIII To: SAMI ROCK COMPANY LTD

WO #: 43252

Invoice Number: HNG25-00570

Comply with Mechanic Sign Off Report dated 1 July 2025 pages 1 thru 5 Discrepancy 1.25.

Resolution: ATA Description

Cabin Pressure Warning (Aneroid) Switch - Functional Test 213053 237004 Cockpit Voice Recorder System - Operational Test

240108 Standby Hydraulic Generator System - Operational Test

256347 Defibriliator, #1

Stall Barrier / Angle of Attack System - Operational Test 270101 Flight Powered Shutoff System - Operational Check

291020 313011 Flight Data Recorder - Functional Test

Main Landing Gear Corrosion Inhibiting Compound Reapplication - (Right) 320010

Crew Oxygen System (Pilot) - Operational Check 351005 570003 Wing Lower Surface (Left) - Zonal Inspection Wing Lower Surface (Right) - Zonal Inspection 570004

Wing Leading Edge External Bi 35.80 - Rbs 433 Inboard of Nav Light (Left) - Zonal Inspection 574007

574008 Wing Leading Edge External Bi 35.80 - Rbs 433 Inboard of Nav Light (Right) - Zonal Inspection

575015 Wing Lower Cove Panel and Flap Well Drain Holes (Left) - Enhanced Zonal Inspection Wing Lower Cove Panel and Flap Well Drain Holes (Right) - Enhanced Zonal Inspection 575016

Lower Wing Trailing Edge (Left) - Zonal Inspection Lower Wing Trailing Edge (Right) - Zonal Inspection 575105 575106

710007 Powerplant / Nacelle External (View from Ground, Left) - Zonal Inspection

Powerplant / Nacelle External (View from Ground, Right) - Zonal Inspection 710008 Powerplant Nose Cowls Internal (View from Ground, Left) - Zonal Inspection 711005 Powerplant Nose Cowls Internal (View from Ground, Right) - Zonal Inspection 711006

Time & Materials Flat Rate Total \$0.00 \$11,550.00 \$11,550.00 Labor: Services: \$2,000.00 \$0.00 \$2,000.00 Total: \$11,550.00 \$2,000.00 \$13,550.00

Services:

Ref. No.	Description	Quantity	Sell Price	Extended
1,25 #1	Rental Equipment, FDR Download and Analysis	1.00	\$2,000.00	\$2,000.00

Discrepancy 1.26. Multiple areas of missing paint on nose landing gear.

Resolution: touched up as required.

Discrepancy 1.27. Multiple areas of missing paint on LH and RH lower engine cowl.

Resolution: Touched up as required

Discrepancy 1.28. Lower beacon aft bulb inop.

Resolution: Replaced bulb op checks good.

	Time & Materials	Total	
Labor:	\$161.70	\$161.70	
Parts:	\$22.48	\$22.48	
Total:	\$184.18	\$184.18	

Parts:

Form 9703

Ref. No.	Part number:	Description	Quantity	Sell price	Extended
1.28 #1	7079-24	BULB	1	\$22.48	\$22.48

Page 12 of 14



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To: Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

WO #: 43252

Invoice Number: HNG25-00570

Discrepancy 1.29. Static air line to standby altimeter has excessive leak.

Resolution: Replaced several eroded hoses with new.

	Time & Materials	Total	
Labor:	\$1,128.60	\$1,128.60	
Parts:	\$1,146.61	\$1,146.61	
Total:	\$2,275.21	\$2,275.21	

Ref. No.	Part number:	Description	Quantity	Sell price	Extended
1.29 #1	36812-6-0180	HOSE	1	\$495.47	\$495.47
1.29 #3	36812-6-0160	HOSE ASSEMBLY	1	\$649.14	\$649.14
1.29 #4	MS28778-6	O RING	1	\$2.00	\$2.00



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To: Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

WO #: 43252

Invoice Number: HNG25-00570

INVOICE SUMMARY FOR WORK ORDER NUMBER: 43252

	Time & Materials	Flat Rate	Total
Labor:	\$3,415.50	\$119,460.00	\$122,875.50
Parts:	\$38,150.79	\$200.00	\$38,350.79
Services:	\$17,750.03	\$31,212.50	\$48,962.53
Misc Charges:	\$5,000.00	re in a	\$5,000.00
Total:	\$64,316.32	\$150,872.50	\$215,188.8 2
Freight:			\$183.37
Subtotal:			\$215,372.19
Total:			<u>=====================================</u>

* Credit, debit, and bank card transactions are subject to a convenience fee. AVMATS accepts all major credit cards, wire-transfer, ACH and Company Checks. Please use the link below to arrange or remit payment for this invoice:

Pay with **AWMATS PAY**

https://www.avmats.com/

Form 9703



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To: Centurion Investments, Inc. d/b/a AVMATS

18377 Edison Avenue Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

AL-SHATI DISTRICT, KING RD PO BOX 118500 JEDDAH, KSA 21352 SAUDI ARABIA

18309A Account code:

Invoice number: HNG25-00595

P.O. number:

Registration #: VP-CAI

Invoice date:

8/14/2025

Due Date:

8/14/2025

Payment Type: CIA Terms: Due Upon Receipt

P.O. number:

INVOICE SUMMARY FOR WORK ORDER NUMBER: 43343

\$3,300.00 Labor:

\$1,768.95 Parts:

Misc Charges: \$122.47

\$5,191.42 Total:

\$5,191.42 Subtotal:

Total: \$5,191.42



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To: Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

G-IV

WO #: 43343

Invoice Number: HNG25-00595

Item: 1.

G-IV Part/Model #:

Team Leader:

Serial Number:

Time & Materials

\$5,191.42

Discrepancy 1.1.

Comply with Preliminary Inspection

Resolution: Preliminary Inspection Completed

Discrepancy 1.2.

Work Order Miscellaneous Charges

Resolution: All shop consumables to include but not limited to drill bits, screw extractors, abrasive wheels and cloth, caps & plugs, brushes, masking materials, gloves, rags, masking tape, primer, adhesives, solvents, lubricants, greases, air gases, calibration, and EPA disposal fee. Paragraph 11 of Standard Terms and Conditions.

	Time & Materials	Total
Misc Charges:	\$122. 4 7	\$122.47
Total:		\$122.47

Discrepancy 1.3. RH landing light switch background light inop.

Resolution: Replaced with new. Operational checks good.

	Time & Materials	Flat Rate	Total
Labor:	\$0.00	\$990.00	\$990.00
Parts:	\$1,768.95	\$0.00	\$1,768.95
Total:	\$1,768.95	\$990.00	\$2,758.95

Parts:

Ref. No.	Part number:	Description	Quantity	Sell price	Extended
1.3 #1	4271-529	INDICATOR LIGHT ASSY	1	\$1,292.47	\$1,292.47
1.3 #2	ELED/682/A/GS/BE	Lamp	4	\$119.12	\$476.48

RH avionics rack upper door left latch not laching closed. Discrepancy 1.4.

Resolution: Adjusted for fitment. No further action required.

	Flat Rate	Total	
Labor:	\$330.00	\$330.00	
Total:	\$330.00	\$330.00	

Provide ground support for air crew Discrepancy 1.5.

Resolution: Provided as required

	Flat Rate	Total
Labor:	\$1,980.00	\$1,980.00
Total:	\$1,980.00	\$1,980.00



Work Order Invoice

750 North Beechcraft United States

Please Remit To: Chesterfield, MISSOURI 63005 Centurion Investments, Inc. d/b/a AVMATS

18377 Edison Avenue Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

WO #: 43343

Invoice Number: HNG25-00595

INVOICE SUMMARY FOR WORK ORDER NUMBER: 43343

	Time & Materials	Flat Rate	Total
Labor:	\$0.00	\$3,300.00	\$3,300.00
Parts:	\$1,768.95	\$0.00	\$1,768.95
Misc Charges:	\$122.47		\$122.47
Total:	\$1,891.42	\$3,300.00	
Subtotal:			\$5,191.42
Total:			

* Credit, debit, and bank card transactions are subject to a convenience fee. AVMATS accepts all major credit cards, wire-transfer, ACH and Company Checks. Please use the link below to arrange or remit payment for this invoice:

Pay with **AUMATS PAY**

Printed: 8/27/2025 12:25:15PM



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To:
Centurion Investments, Inc. d/b/a AVMATS
18377 Edison Avenue

18377 Edison Avenue Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

BIII To: SAMI ROCK COMPANY LTD

AL-SHATI DISTRICT, KING RD PO BOX 118500 JEDDAH, KSA 21352 SAUDI ARABIA Account code: 18309A

Invoice number: HNG25-00584

P.O. number:

Registration #: VP-CAI

Invoice date: 8/8/2025

Due Date: 8/8/2025

Payment Type: CIA Terms: Due Upon Receipt

P.O. number:

INVOICE SUMMARY FOR WORK ORDER NUMBER: SHOP-43317

Parts:

\$16,400.00

Total:

\$16,400.00

Subtotal:

\$16,400.00

Total:

\$16,400.00



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To: Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue Chesterfield, MO 63005-3628

FAX:

Telephone 636-532-2674 636-530-9044

BIII To: SAMI ROCK COMPANY LTD

WO #: SHOP-43317

(636) 532-2674 Phone

Invoice Number: HNG25-00584

G-IV SP

G-IV-SP Item: 1.

Part/Model #:

Team Leader:

Serial Number:

Time & Materials

\$16,400.00

Discrepancy 1.1.

Comply with Preliminary Inspection

Resolution: Preliminary Inspection Completed

Discrepancy 1.2.

Work Order Miscellaneous Charges

Resolution: All shop consumables to include but not limited to drill bits, screw extractors, abrasive wheels and cloth, caps & plugs, brushes, masking materials, gloves, rags, masking tape, primer, adhesives, solvents, lubricants, greases, air gases, calibration, and EPA

disposal fee. Paragraph 11 of Standard Terms and Conditions.

Discrepancy 1.3.

Remove name aft of MED.

Resolution: Removed name, Painted, blended and buffed as required.

Discrepancy 1.4.

Provide FDR download epidite fee for rule set ICAO Annex 6

Resolution: Provided as requested.

Parts:

Ref. No.	Part number:	Description	Quantity
1.4 #1	EXPEDITE FEE	EXPEDITE FEE	1.00
T.77 17 1	EXI EDITE LE	CAI COILCIE	2.00

Restrap Swift broad band system. Discrepancy 1.5.

Resolution: Restrap Swift broad band system.

Discrepancy 1.6. Both control yoke lower clamps bent

Resolution: Trimmed and reinstalled.

Discrepancy 1.7. LH Oxygen mask mic inop

Resolution: Found switches in incorrect positions. Ops check good

Discrepancy 1.8. Standby fuel quanity LH wing last digit inop

Resolution: Hold per customer.

The tail camera picture is not showing on the monitor. (Blue screen) Discrepancy 1.9.

Resolution: Removed camera and verified it is the failed part. Part is unavailable for purchase at this time. Hold per customer.

Ref. No.	Part number:	Description	Quantity	
1.9 #1	PS890B1/2	SEALER, 136 GRAM 6 OZ SEMKIT	1	



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 Please Remit To: Centurion Investments, Inc. d/b/a AVMATS 18377 Edison Avenue

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI RO	OCK COMPANY LTD		WO #: SHOP-43317 I	nvoice Numbe	r: HNG25-0058	1
Discrepancy 1.1	to. Assist customer with Cayman	registration requirements an	d Information			
Resolution: Assis	sted as requested.					
Discrepancy 1.1	11. Evaluate static port for damag	ge requirements.				•••
Resolution: Clear	ned and evaluated no defects noted	l.				
Discrepancy 1.1	i.2. Provide customer with GIV - N	4SG3 M/M, SRM, IPC, WM				
Resolution: Provi	lded as requested.					
	Time & Mater	rials	Total			
Parts:	\$16	,400.00	\$16,400.00	-)		
Total:	\$16,	400.00	\$16,400.00	=)		
Parts:						
Ref. No.	Part number:	Description		Quantity	Sell price	Extended
1.12 #1	GIV MSG3 MANUALS USB DELIVERY	Manuals & Delivery		1	\$16,400.00	\$16,400.00



Work Order Invoice

750 North Beechcraft Chesterfield, MISSOURI 63005 United States

Please Remit To:
Centurion Investments, Inc. d/b/a AVMATS
18377 Edison Avenue
Telephon

Chesterfield, MO 63005-3628 (636) 532-2674 Phone

Telephone 636-532-2674 FAX: 636-530-9044

Bill To: SAMI ROCK COMPANY LTD

WO #: SHOP-43317

Invoice Number: HNG25-00584

INVOICE SUMMARY FOR WORK ORDER NUMBER: SHOP-43317

Time & Materials

Parts: \$16,400.00

Total: \$16,400.00

Subtotal:

Total:

Total

\$16,400.00

\$16,400.00

\$16,400.00

\$16,400.00

* Credit, debit, and bank card transactions are subject to a convenience fee. AVMATS accepts all major credit cards, wire-transfer, ACH and Company Checks. Please use the link below to arrange or remit payment for this invoice:

Pay with **AVMATS PAY**

https://www.avmats.com/