Veikko Vikkelä Field Engineer · 09:14

Changed the SFP on transmission node TRN-042. Link is up and alarms cleared, but traffic is still not coming back.

Erkki Expert Network Expert · 09:22

That's it. Disable the interface, wait a little, then enable it again. Don't reboot the whole unit unless that fails.

Veikko Vikkelä 09:26

Is this documented somewhere?

Erkki Expert 09:27

Not that I know of. We've just learned it over the years.

---

a Teams thread · Elisa's example file, unchanged

The link came up. No traffic.

Erkki knew the fix.

It lives in one chat.

The next person starts from zero. The agent that is meant to help cannot see it at all.

THE ANSWER

Silent context remembers it.

READ AS WRITTEN

The chat and the email, exactly as they are.

PINNED TO THE UNIT

TRN-042, in Erkki's own words, and which units he said it covers.

WHO SAID IT, AND WHEN

Erkki · Teams · 14.10. Dated from the moment the part was changed.

ONE CALL FOR THE AGENT

What to do next, and where that came from. Or: check first. Or: I don't know, ask these people.

Nobody fills in anything for the system, and the system **never sends a message** itself. An unclear case waits with its reason.

Any source, any language: Elisa's Teams export and email, a ticket's worklog, a thread in Finnish. One reader, one kind of note, in the speaker's own words.

ONE CALL FOR THE AGENT, AND WHO ACTS

First the agent proposes. Once a success is on record, it acts.

PROPOSE **TRN-051** · same class as where it was seen · bounce the interface

Disable the interface, wait a little, then enable it again

Held back	**No reboot or hardware replacement before a failed bounce is reported.**
Counters	zero, read from the device by the agent itself
Why this unit	Observed on TRN-042. TRN-051 is the same class, but the scope "These old units" is undefined, so reaching this unit is an inference.
Who acts	A person. Reversible, but the agent's own log holds no proposal of this step on this class that a person carried out with a good outcome. After one, the policy lets the agent act.
What would change this	A report that this failed, which lifts the prohibition.

Once that success is on record, the policy lets the agent act. A third unit of the same model: the agent turns the port off and on itself, the device confirms. A reboot or a new part still waits for a person. The network here is synthetic; the decision is real.

THE AGENT ACTED **TRN-063** · under the policy, in the synthetic network

The agent proposed	Disable the interface, wait a little, then enable it again
The policy said	The agent itself. Reversible; proposed on TRN-051 on 21.10., carried out by a person, and the counters rose; no disagreement on record; the counters here read from the device by the agent itself.
The agent did	Disabled and enabled ge-0/0/1, seen on the device at 2026-10-25T09:42:00
The outcome	Counters rising afterwards
Still with a person	**A reboot or a hardware replacement: not reversible, so the policy never gives them to the agent.**

DOUBT

It knows when not to trust itself.

AFTER A FIRMWARE UPDATE

Check again, on that unit only. Nothing expires by a calendar.

WHERE THE FIX DID NOT HELP

Erkki narrowed the advice to the old units. It is no longer offered on the new one.

WHEN TWO EXPERTS DISAGREE

Both stay visible with their sources. No side is taken; the counters are read first.

WHEN IT DOES NOT KNOW AT ALL

It writes the question for the person on call, who sends it. A budget keeps the asking small.

CHECK FIRST `TRN-042` · seen on this unit · read something first

Check whether the traffic counters are actually increasing. The firmware on TRN-042 changed from 4.8 to 4.9 on 2026-10-28T13:00:00, after this advice, so it needs checking again on this unit.

NOT APPLICABLE On these older units, don't trust the green link status, sometimes after changing the SFP the interface comes up but forwarding doesn't recover. Usually the SFP is fine, so check whether traffic counters are increasing, and if they stay at zero while the interface is UP, disable the interface, wait a little, then enable it again, and don't reboot the whole unit unless that fails.

Not for this unit: the teller says it covers "These old units; the 4.x firmware ones", and TRN-100 is in another class.

CHECK FIRST `TRN-051` · same class as where it was seen · read something first

Read the traffic counters first. The recorded advice disagrees on what comes next, and this answer does not choose.

DRAFT FOR TRANSMISSION-ONCALL a person sends it, the system never does · question 1 of 3 this week

TRN-051: intermittent CRC errors on uplink. Nothing is recorded about this yet. Has anyone seen it, and what did you check first?

It shows where advice came from and what was reported about it, **not whether it is true.** It scores advice, **never people.**

MEASURED, AND THE LIMITS

Runs with no model and no key.

MEASURED, FROM THE RECORDED ANSWERS

160 tests pass

13 / 13 sources found in the truth set; merged 9/9, unit 5/5, time 9/9, evidence 8/8

1 of 16 wrong on sources the rule author never read; 0, 0, 0, 1, 1 in five repeats

Passed a clean install from the README, no key

No edits the graph export loads into Neo4j 5 as it is

WHAT IT DOES NOT CLAIM

01 It never sends a message itself. It drafts; a person sends.

02 It shows where advice came from, not whether it is true.

03 It scores advice, never people.

04 The network here is simulated, and so is every file but Elisa's two. The agent acts only in that synthetic stream.

LEFT OUT ON PURPOSE, EACH A CONNECTOR OR A MODEL AWAY

Live connectors to Teams and Slack · a chat with the agent · search by meaning · Elisa's real inventory graph

`github.com/pkorrrhonen-cmd/silent-context` · MIT · Petri Korhonen