HALLIBURTO	ON		FORMA	TION LOGGIN WELL: BDC-2-04		rT .		Report No: Corresponding	DDR	12 12	
COMPANY:	INPEX	Rig:		Last Survey Depth 2220.64 m							
DATE: Midnight Depth:	20-Sep-21 2261.0 m TVD:	TIME: 2400 hrs Last Casing Size: 26° TOL (7.0"): Liner Shoe: Inc (deg) 31.42° 2218.1 m TVD LAT: 218.6 m Shoe Depth: 689.0 m LOT/FIT: sg EMW Azi: 227.90°									
RIG OPERATIONS: REPORT BY:	Drilling 17.5" hole Shiva Hosmut / Robert Findlay REPORT RECEIVED BY: Greg Watkins / Jeremy Ellis										
DRILLING REPORT	Sniva Hositiut / Robert Findiay			REPOR	T RECEIVED BT:	Greg Watkins / Jeremy Elli	s				
Bit No:	3	Type / SL#:	Hybrid KTX633 / 5269224	Make:	Kymera	Size :	17.5"Je	ets: 3 x 14's, 6 x 15's	TFA (in ²):	1.487	
Total Bit Distance:	1566.0 m	Total onbtm Hrs(Tot / cmt):	59.88 0.99	Avg Bit ROP (m/hr):	26.2	Total Krevs(on btm)Total / Cmt				95.67	
24 hr Bit Distance:	m	Daily Bit Hours:	13.91	24hrs ROP (m/hr):	15.4		vs(on btm):	139.95 Daily Circ Hrs	:	22.83	
Total Sliding hrs for run Total bit rot hrs for run	hrs 59.88 hrs	Total drilling hrs for run Total bit rot hrs due to motor r	42.98 hrs	Jars hrs ON	btm (24hrs/Total)	8.01 42.98 hrs due to string 42.98	t hrs				
SPP (Min / Max):		GPM (Min / Max):	1148 / 1178 GPM	TQ (kft-lb) (Min / Max):	0 / 12.3		lin/max/AVG):	0 / 80 / 41 WOB (klb) (M	n / Max):	8.4 / 31.9	
SPP Avg:	2447 PSI	GPM Avg:	1164 GPM	TQ (kft-lb)Avg:	7.1	Bit RPM (Min/max/AVG):	126 / 209 / 169 WOB (klb) Av	g:	16.3	
SPM1 (Min/Max/Avg)	0 / 17 / 5 stk	SPM2 (Min/Max/Avg)	67 / 76 / 73	SPM3 (Min/Max/Avg)	55 / 68 / 63		n/Max/Avg)	56 / 76 / 62 stk			
SPM1 Flow (Max/Avg)	99 / 29 GPM	SPM2 Flow (Max/Avg)	445 / 427	SPM3 Flow (Max/Avg)	398 / 369	GPM SPM4 Flo	w (Max/Avg)	445 / 363 GPM			
Rotating hrs on bottom (24hrs/Total) :		ev on btm hrs/Total)	String Krev on btm (24hrs/Total)		_ Ditch Magnet 24	hr Wt:360	_gms	Section Ditch Magnet total Wt	3060	_gms	
HYDRAULICS REPOR	r T										
Mud Density In:	1.110sg	Mud Density Out:	1.110sg	ECD:		sg PV/YP:		12 / 29 cp // lbs/100ft2			
Gels: Hole Volume:		Chlorides: Annular Volume:	15000 mg/L bbl	Temp In: Tubing Volume:		°C Temp Ou bbl Calculate		39.3 °C stk			
							_				
Polymer Mud, stopped pump	7.5" hole from 2047 m to 2193 m, the ing after 30 bbls of SAPP pill exited the average. At 2241 m pumped another	ne bit and soaked for 30 minutes.	After 30 minutes pumped 5 bbls	until remaining 20 bbls of	SAPP pill exited the	bit, chased with another 50 bb	Is of SAPP pill followed	by 50 bbls of scouring pill from pit :	2 - more impro	ovement,	
GEOLOGY:											
Depth (m)				Lithology					ROP range	(Min / Max / Avg)	
2047 - 2261	100% Claystone								2.6 /	54.9 / 15.6	
BACKGROUND GAS C Depth Interv. 2047 - 2261	al Total Gas	% C1 33	C2 0	C3 0		C4 0	nC4 0	iC5 n(
BACKGROUND GAS II	N SUMMARY										
Depth Interv	al Total Gas	% C1	C2	C3	ì	C4	nC4	iC5 n0	5		
GAS OUT PEAKS											
Depth (m)	Total Gas %	C1	C2	C3	iC4	nC4	iC5	nC5	BG%	Gas type	
GAS IN PEAKS											
Depth (m)	Total Gas %	C1	C2	C3	iC4	nC4	iC5	nC5	BG%	Gas type	
FO: F	e Connection Gas, DC: Dummy Conr			Car CIMID Comb C	D. C f 225	WTO: Wind The Co.					
GAS SENSOR STATUS		iculon Gas, 1G: Trip Gas, PO: Pt	amp Oil Gas, FC: Flow Check (oas, SVVD: SWAD GAS, SC	n. Gas irom SCR,	vvio: wiper inp Gas. DFC: L	ynamic riow check Ga	10			
Sensor Type			Date of Calibration/Test		Status		Comment				
LEL Sensor (Pits, shaker & Drill floor area)			15-Aug-20		Bump Test		Working Working				
H2S Sensor (Pits, shaker & Header box, rigloor) Gas THA Out and IN Equipment no-11868472-001 and 12088033			15-Aug-20 14-Sep-21		Calibrated Calibrated with 1% & 10%		Working Working				
Gas Chromatograph In/ Equipment no- 11883509			14-Sep-21		Calibrated with 1000ppm & 500 ppm mix gas Calibrated with 1000ppm & 500 ppm mix gas		Working				
	Chromatograph Out/ Equipment no- A & Chromatograph B/U / Equipment		14-Sep 3-Aug		Calibrated with	1000ppm & 500 ppm mix gas Calibrated		Working 2 x Backup THA Working (Sta	ndby)		
EQUIPMENT STATUS											
	Item ductivity IN sensor, wired up to junction	Action Mud Weight IN ensor is not getting proper value.					Comment ensor master is not communicating with Slave. Troubleshooting is in progress.				
							Waiting suggestion from town technician. Conductivity IN is working OK				
Done function test on SDL shutdown system. On 09Sep2021					shutdown system		under investigation	nder investigation			
Fire sensor at wet end of unit	triggered resulting in the unit powering	Removed sensor and replace reinstating		Investigating pern	Investigating permanent solution						
SDL CREW STATUS											
	Name	Positi		Date Arrived			Expected Crew Change Date				
Shiva Prasad Hosmut Robert Findlay			DE DE		30-Aug-21 13-Sep-21		27-Sep-21 4-Oct-21				
Yenny Nino			ML		6-Sep-21		20-Sep-21				
James Cranfield Larry Pagana			ML ML		16-Sep-21 20-Sep-21		TBC TBC				
	cony i ogalia		ML			,		150			