			FORMA	TION LOGGIN WELL: BDC-2-04					Report No: Corresponding DDI	10 R 10
COMPANY:	INPEX		Rig: Maersk Deliverer	Field	: ICHTHYS			Last S		1525.61 m
DATE: Midnight Depth:	18-Sep-21 1581.0 <b>m</b> 1		IME: 2400 hrs 1548.2	Last Casing Size: m Shoe Depth:		_ (7.0"):	Liner Shoe	»:	Inc (deg) Azi:	1.00 ° 213.52 °
RIG OPERATIONS:	Drilling 17.5" hole			•						
EPORT BY:	Shiva Hosmut / Robert Findla	/		REPOR	T RECEIVED BY: Greg Wa	kins / Jeremy Elli	3			
RILLING REPORT										
it No: otal Bit Distance:	886.0 m	Type / SL#: Total onbtm Hrs(Tot / cm	Hybrid KTX633 / 5269224 29.03 0.99	Make: Avg Bit ROP (m/hr):	Kymera Total Kr	Size : evs(on btm)Total / Cmt	17.5" 277.06	3 6.45	X 14's, 6 x 15's Total Circ Hrs :	A (in²): 1.48
hr Bit Distance:	410.0 m	Daily Bit Hours:	9.60	24hrs ROP (m/hr):	42.7		rs(on btm):	93.57	Daily Circ Hrs:	22.9
otal Sliding hrs for run	hrs	Total drilling hrs for run	hrs	Jars hrs ON	btm (24hrs/Total) 9.60	26.92	-			
otal bit rot hrs for run	hrs	Total bit rot hrs due to mo			Total bit rot hrs due t	-		0 / 60 / 36		
PP (Min / Max): PP Avg:	1290 / 2114 PSI 1802 PSI	GPM (Min / Max): GPM Avg:	904 / 1158 GPM 1128 GPM	TQ (kft-lb) (Min / Max): TQ (kft-lb)Avg:	<u>0 / 11.4</u> 4.4		in/max/AVG): Min/max/AVG):	115 / 188 161	WOB (klb) (Min / l  WOB (klb) Avg :	Max ): 1 - 2 8.7
PM1 (Min/Max/Avg)	51 / 89 / 80 stk	SPM2 (Min/Max/Avg)	61 / 89 / 74	SPM3 (Min/Max/Avg)	0 / 60 / 15 stk		n/Max/Avg)	0 / 59 / 35	stk	
PM1 Flow (Max/Avg)	521 / 468 <b>GPM</b>	SPM2 Flow (Max/Avg)	521 / 433	SPM3 Flow (Max/Avg)	351 / 88 <b>GPM</b>	SPM4 Flo	w (Max/Avg)	345 / 205	GPM	
otating hrs on bottom 4hrs/Total) :	9.6 / 29.03	or Krev on btm (24hrs/Total) 70.8 / 205.22	String Krev on btm (24hrs/Total)		Ditch Magnet 24hr Wt:	1250	ams	Section Ditch	Magnet total Wt	2100 gms
YDRAULICS REPOR		(=,	(=							<u></u> 5
ud Density In:	1.090sg	Mud Density Out:	1.090sg	ECD:	1.090sg	PV/YP:		10 / 19 _ cp // lb	os/100ft2	
els:	5 / 8 / 12 lbs/100ft2	Chlorides:	13000mg/L - bbl	Temp In:	31.0 °C	Temp Ou		31.7°C		
ole Volume:	bbl	Annular Volume:	bbl	Tubing Volume:	bbl	Calculate	ı Lag:	stk		
	from 1171 m to 1372 m while lo		e shakers to eliminate sand from the rilling ahead and building additional S							
EOLOGY:	1									
Depth (m)				Lithology					RO	OP range (Min / Max
1171 - 1581	100% Sandstone									2.2 / 331.2 / 82.3
ACKGROUND GAS	OUT SUMMARY									
Depth Interv	val Tota	Gas % C1	C2	C3	iC4		nC4	iC5	nC5	
1171 - 157	1 (	02 8	0	0	0		0	0	0	
BACKGROUND GAS I	N SHMMADY									
Depth Interv		Gas % C1	C2	C3	iC4		nC4	iC5	nC5	
SAS OUT PEAKS										
Depth (m)	Total Gas %	C1	C2	C3	iC4	nC4	C4 iC5		nC5	BG% Gas
AS IN PEAKS		C1					iC5		nC5	BG% Gas
AS IN PEAKS  Depth (m)	Total Gas %	C1	C2	C3	iC4	nC4	105			
	Total Gas %	CI	C2	C3	iC4	nC4	105			
Depth (m)  3: Formation Gas, CG:Pip	ne Connection Gas, <b>DC</b> : Dummy		C2 D: Pump Off Gas, FC: Flow Check (							
Depth (m)  3: Formation Gas, CG:Pig	pe Connection Gas, <b>DC</b> : Dummy		D: Pump Off Gas, FC: Flow Check (	Gas, <b>SWB</b> : Swab Gas, <b>SC</b>	R: Gas from SCR, WTG: Wij					
Depth (m)  3: Formation Gas, CG:Pip  AS SENSOR STATU	ne Connection Gas, <b>DC</b> : Dummy	Connection Gas, TG: Trip Gas, Po		Gas, SWB: Swab Gas, SC		er Trip Gas. D <b>FC</b> : [			Comment Working	
Depth (m) 3: Formation Gas, CG:Pi <sub>F</sub> AS SENSOR STATU H:	De Connection Gas, DC: Dummy S Sensor Type LEL Sensor (Pits, shaker & Drill 2S Sensor (Pits, shaker & Heade	Connection Gas, TG: Trip Gas, Po	D: Pump Off Gas, FC: Flow Check (  Date of Calib  15-Au  15-Au	Gas, SWB: Swab Gas, SC ration/Test 1-20 1-20	R: Gas from SCR, WTG: Wij	er Trip Gas. D <b>FC</b> : E			Comment Working Working	
Depth (m)  3: Formation Gas, CG:Pip AS SENSOR STATU  H: Gas THA C	s Sensor Type LEL Sensor (Pits, shaker & Drill	Connection Gas, TG: Trip Gas, Policor area) box, rigloor) 72-001 and 12088033	D: Pump Off Gas, FC: Flow Check (  Date of Calib  15-Au,	Gas, <b>SWB</b> : Swab Gas, <b>SC</b> ration/Test 1-20 1-20 1-20	R: Gas from SCR, WTG: Wij Status Bump Te	er Trip Gas. D <b>FC</b> : E st d % & 10%			Comment Working	
Depth (m)  3: Formation Gas, CG:Pip  AS SENSOR STATU  H:  Gas THA C  Gas  Gas	be Connection Gas, DC: Dummy S Sensor Type LEL Sensor (Pits, shaker & Drill 25 Sensor (Pits, shaker & Heado but and IN Equipment no-11884 so Chromatograph In/ Equipment Chromatograph Out/ Equipment	Connection Gas, TG: Trip Gas, Policor area) box, rigloor) 72-001 and 12088033 no- 12088039	Date of Calib Date of Calib 15-Aug 14-Sep 14-Sep 14-Sep	Gas, <b>SWB</b> : Swab Gas, <b>SC</b> ration/Test †-20 †-20 *-21 *-21 *-21	R: Gas from SCR, WTG: Wij Status Bump Te Calibrated with 1 Calibrated with 1000ppm Calibrated with 1000ppm	st d % & 10% k 500 ppm mix gas & 500 ppm mix gas & 500 ppm mix gas		* Gas	Comment Working Working Working Working Working	
Depth (m)  E: Formation Gas, CG:Pip  AS SENSOR STATU  H:  Gas THAC  Gas  Gas  Gas  Gas THAC	S Sensor Type  LEL Sensor (Pits, shaker & Drill 28 Sensor (Pits, shaker & Irvil 28 Sensor (Pits, shaker & Heade Ust and IN Equipment no -1188& s Chromatograph In/ Equipment Chromatograph Out/ Equipment A & Chromatograph BIJ / Equip	Connection Gas, TG: Trip Gas, Policor area) box, rigloor) 72-001 and 12088033 no- 12088039	Depump Off Gas, FC: Flow Check (Inc.)  Date of Calib  15-Aug  14-Seg  14-Seg	Gas, <b>SWB</b> : Swab Gas, <b>SC</b> ration/Test †-20 †-20 *-21 *-21 *-21	R: Gas from SCR, WTG: Wij Status Bump Te Calibrated with 1 Calibrated with 1000ppm	st d % & 10% k 500 ppm mix gas & 500 ppm mix gas & 500 ppm mix gas		* Gas	Comment Working Working Working Working	
Depth (m)  s: Formation Gas, CG:Pip  AS SENSOR STATU  H:  Gas THAC  Gas  Gas  Gas  Gas THAC	se Connection Gas, DC: Dummy S Sensor Type LEL Sensor (Pits, shaker & Drill 25 Sensor (Pits, shaker & Heade Dut and IN Equipment no-118684 s Chromatograph In/ Equipment L'Chromatograph Out/ Equipment A & Chromatograph B/U / Equip	Connection Gas, TG: Trip Gas, Policor area) box, rigloor) 72-001 and 12088033 no- 12088039	Date of Calib  Date of Calib  15-Aug  14-Sep  14-Sep  3-Aug	Sas, SWB: Swab Gas, SC ration/Test +20 -220 -221 -221 -221	R: Gas from SCR, WTG: Wij Status Bump Te Calibrated with 100 Calibrated with 1000ppm Calibrated with 1000ppm Calibrated with 1000ppm	st d % & 10% k 500 ppm mix gas & 500 ppm mix gas & 500 ppm mix gas		* Gas	Comment Working Working Working Working Working THA Working (Standb)	
Depth (m)  3: Formation Gas, CG:Pig  AS SENSOR STATU  H: Gas THA C Ga Gas Gas Gas TH	S Sensor Type  LEL Sensor (Pits, shaker & Drill 28 Sensor (Pits, shaker & Irvil 28 Sensor (Pits, shaker & Heade Ust and IN Equipment no -1188& s Chromatograph In/ Equipment Chromatograph Out/ Equipment A & Chromatograph BIJ / Equip	Connection Gas, <b>TG</b> : Trip Gas, <b>P</b> i lloor area) box, rigloor) 72-001 and 12088033 no- 11883509 no- 12088039 nent no-12088032	Date of Calib Date of Calib 15-Aug 14-Sep 14-Sep 14-Sep	as, SWB: Swab Gas, SC ration/Test -20 -21 -21 -21	R: Gas from SCR, WTG: Wij Status Bump Te Calibrated with 1 Calibrated with 1000ppm Calibrated with 1000ppm	st d % & 10% k 500 ppm mix gas & 500 ppm mix gas & 500 ppm mix gas	ynamic Flow chec	2 x Backup	Comment Working Working Working Working Working THA Working (Standb)	y)
Depth (m)  3: Formation Gas, CG:Pip AS SENSOR STATU  H: Gas THAC Gas Gas Gas Gas Gas TH  QUIPMENT STATUS	S Sensor Type  LEL. Sensor (Pits, shaker & Drill 2S Sensor (Pits, shaker & Drill 2S Sensor (Pits, shaker & Drill 2S Sensor (Pits, shaker & Heade but and IN Equipment no-11888 s Chromatograph In/ Equipment . Chromatograph Out/ Equipment A & Chromatograph B/U / Equipment doubtilty in Sensor, wired up to j	Connection Gas, <b>TG</b> : Trip Gas, <b>P</b> i lloor area) box, rigloor) 72-001 and 12088033 no- 11883509 no- 12088039 nent no-12088032	Date of Calib  Date of Calib  15-Au  14-Se;  14-Se;  3-Aug  Actic	as, SWB: Swab Gas, SC ration/Test -20 -21 -21 -21	R: Gas from SCR, WTG: Wij  Status Bump Te Calibrated with 1000ppm Calibrated with 1000ppm Calibrated with 1000ppm Calibrated with 1000ppm Under investigation	st d w 10% a 500 ppm mix gas d d	ynamic Flow chec	2 x Backup s not communicating on from town technic	Comment Working Working Working Working Working THA Working (Standb)	y)
Depth (m)  B: Formation Gas, CG:Pip  AS SENSOR STATU  H:  Gas THAC  Gas  Gas  Gas  Gas  Gas TH  QUIPMENT STATUS	be Connection Gas, DC: Dummy S Sensor Type LEL Sensor (Pits, shaker & Drill 25 Sensor (Pits, shaker & Heade but and IN Equipment no-11884 s Chromatograph In/ Equipment 1 Chromatograph Out/ Equipment A & Chromatograph B/J / Equip	Connection Gas, <b>TG</b> : Trip Gas, <b>P</b> i lloor area) box, rigloor) 72-001 and 12088033 no- 11883509 no- 12088039 nent no-12088032	Date of Calib  Date of Calib  15-Au  14-Se;  14-Se;  3-Aug  Actic	as, SWB: Swab Gas, SC ration/Test -20 -21 -21 -21	R: Gas from SCR, WTG: Wij  Status Bump Te Calibrated with 1 Calibrated with 1000ppm Calibrated with 1000ppm Calibrated Status Status Status	st d w 10% a 500 ppm mix gas d d	ynamic Flow chec	2 x Backup s not communicating on from town technic	Comment Working Working Working Working Working THA Working (Standb)	y)
Depth (m)  I: Formation Gas, CG:Pig  AS SENSOR STATU  H: Gas THA C Ga Gas Gas TH  QUIPMENT STATUS  talled Mud weight IN, Cor	S Sensor Type  LEL. Sensor (Pits, shaker & Drill 2S Sensor (Pits, shaker & Drill 2S Sensor (Pits, shaker & Drill 2S Sensor (Pits, shaker & Heade but and IN Equipment no-11888 s Chromatograph In/ Equipment . Chromatograph Out/ Equipment A & Chromatograph B/U / Equipment doubtilty in Sensor, wired up to j	Connection Gas, <b>TG</b> : Trip Gas, <b>P</b> i licor area). t-box, rigloor) 72-001 and 12088033 no- 11883509 no- 12088039 nent no-12088032	Date of Calib  Date of Calib  15-Au  15-Au  14-Se  14-Se  3-Aug  Mud Weight IN ensor is not ge	Sas, SWB: Swab Gas, SC ration/Test +20 -22 -21 -21 -21 -21 -21	R: Gas from SCR, WTG: Wij  Status  Bump Te Calibrated with 1 Calibrated with 1000ppm Calibrated with 1000ppm Calibrated with 1000ppm Under investigation Calibrated with 1000pm	st d % 8.10% S500 ppm mix gas d d on PDC for	ynamic Flow chec	2 x Backup s not communicating on from town technic	Comment Working Working Working Working Working THA Working (Standb)	y)
Depth (m)  S: Formation Gas, CG:Pip  AS SENSOR STATU  H:  Gas THAC  Gas  Gas  Gas  Gas THAC  QUIPMENT STATUS  cuted Mud weight IN, Cor  one function test on SDL s  e sensor at wet end of un	De Connection Gas, DC: Dummy S Sensor Type LEL Sensor (Pits, shaker & Drill 25 Sensor (Pits, shaker & Porill 25 Sensor (Pits, shaker & Heade but and IN Equipment no-11884 s Chromatograph In/ Equipment A & Chromatograph Out/ Equipment A & Chromatograph Out/ Equipment Item adductivity IN sensor, wired up to j hutdown system. On 09Sep2021	Connection Gas, <b>TG</b> : Trip Gas, <b>P</b> i licor area). t-box, rigloor) 72-001 and 12088033 no- 11883509 no- 12088039 nent no-12088032	Date of Calib  Date of Calib  15-Aug  14-Sej  14-Sej  3-Aug  Actic  Mud Weight IN ensor is not ge	Sas, SWB: Swab Gas, SC ration/Test +20 -22 -21 -21 -21 -21 -21	R: Gas from SCR, WTG: Wij  Status Bump Te Calibrated with 1000ppm	st d % 8.10% S500 ppm mix gas d d on PDC for	ynamic Flow chec	2 x Backup s not communicating on from town technic	Comment Working Working Working Working Working THA Working (Standb)	y)
Depth (m)  3: Formation Gas, CG:Pip AS SENSOR STATU  H: Gas THAC Gas Gas Gas Gas THAC QUIPMENT STATUS stalled Mud weight IN, Cor	De Connection Gas, DC: Dummy S Sensor Type LEL Sensor (Pits, shaker & Drill 25 Sensor (Pits, shaker & Porill 25 Sensor (Pits, shaker & Heade but and IN Equipment no-11884 s Chromatograph In/ Equipment A & Chromatograph Out/ Equipment A & Chromatograph Out/ Equipment Item adductivity IN sensor, wired up to j hutdown system. On 09Sep2021	Connection Gas, <b>TG</b> : Trip Gas, <b>P</b> i licor area). t-box, rigloor) 72-001 and 12088033 no- 11883509 no- 12088039 nent no-12088032	Date of Calib  Date of Calib  15-Au  14-Se;  14-Se;  3-Aug  Mud Weight IN ensor is not ge  Removed sensor and repla	Sas, SWB: Swab Gas, SC ration/Test +20 -20 -21 -21 -21 -21 -21	R: Gas from SCR, WTG: Wij  Status  Bump Te Calibrated with 1000ppm Calibrated with 1000ppm Calibrated with 1000ppm Under investigation Observed no alram was set shutdown system Investigating permanent sol	st d w 8. 10% a 500 ppm mix gas d on PDC for ution	ynamic Flow chec	2 x Backup s not communicating on from town technic working OK	Comment Working Working Working Working Working THA Working (Standb) Comment with Slave. Troubleshootian.	y)
Depth (m)  3: Formation Gas, CG:Pip AS SENSOR STATU  H: Gas THAC Gas Gas Gas Gas THAU  QUIPMENT STATUS  stalled Mud weight IN, Cor	S Sensor Type  LEL Sensor (Pits, shaker & Drill SS Sensor (Pits, shaker & Drill SS Sensor (Pits, shaker & Drill SS Sensor (Pits, shaker & Heade but and IN Equipment no-11884 s Chromatograph Dut/ Equipment C hormatograph Dut/ Equipment A & Chromatograph Br/J / Equip  Item inductivity IN sensor, wired up to j hutdown system. On 09Sep2021 it triggered resulting in the unit po  Name Shiva Prasad Hosmu	Connection Gas, <b>TG</b> : Trip Gas, <b>P</b> i licor area). t-box, rigloor) 72-001 and 12088033 no- 11883509 no- 12088039 nent no-12088032	Date of Calib  Date of Calib  15-Aug  14-Seg  14-Seg  3-Aug  Actic  Mud Weight IN ensor is not ge  Removed sensor and repla reinstating  Positi	as, SWB: Swab Gas, SC ration/Test +20 +20 -21 -21 -21 -21 -21 -21 titing proper value.	R: Gas from SCR, WTG: Wij  Status Bump Tc Calibrated with 1000ppm Calibrated with 1000ppm Calibrated with 1000ppm Calibrated with 1000ppm Investigation Calibrated with 1000ppm Calibrated with 1000ppm Calibrated with 1000ppm Investigation Date Arrh  Date Arrh 30-Aug-	st d % 8.10% S 500 ppm mix gas d 500 ppm mix gas d d on PDC for utition	ynamic Flow chec	2 x Backup s not communicating on from town technic working OK	Comment Working Working Working Working Working THA Working (Standby Comment with Slave. Troubleshootian.	y)
G: Formation Gas, CG:Piip  AS SENSOR STATU  H:  Gas THA C  Ga  Gas  Gas THA C  Sating  Gas THA C  G	se Connection Gas, DC: Dummy S Sensor Type LEL Sensor (Pits, shaker & Drill 28 Sensor (Pits, shaker & North 28 Sensor (Pits, shaker & Head but and IN Equipment no-118684 so Chromatograph In // Equipment In & Chromatograph B/IJ // Equip Item ductivity IN sensor, wired up to j huldown system. On 09Sep2021 It triggered resulting in the unit po	Connection Gas, <b>TG</b> : Trip Gas, <b>P</b> i licor area). t-box, rigloor) 72-001 and 12088033 no- 11883509 no- 12088039 nent no-12088032	Date of Calib  Date of Calib  15-Aug  14-Seg  14-Seg  Actic  Mud Weight IN ensor is not ge  Removed sensor and repla reinstating  Posit  Des	Sas, SWB: Swab Gas, SC ration/Test +20 -20 -21 -21 -21 -21 -21	R: Gas from SCR, WTG: Wij  Status  Bump Te Calibrated with 1000ppm Calibrated with 1000ppm Calibrated with 1000ppm Index of the status Under investigation Observed no alram was set shutdown system Investigating permanent sol  Date Arrh 30-Aug- 13-Sep- 13-Sep-	st dd % & 10% & 500 ppm mix gas d on PDC for ution	ynamic Flow chec	2 x Backup s not communicating on from town technic working OK	Comment Working Working Working Working Working Working THA Working (Standb)  Comment with Slave. Troubleshootian.  ded Crew Change Date 27-Sep-21 4-Oct-21	y)
Depth (m)  3: Formation Gas, CG:Pip AS SENSOR STATU  H: Gas THAC Gas Gas Gas Gas THAU  QUIPMENT STATUS  stalled Mud weight IN, Cor	S Sensor Type  LEL Sensor (Pits, shaker & Drill SS Sensor (Pits, shaker & Drill SS Sensor (Pits, shaker & Drill SS Sensor (Pits, shaker & Heade but and IN Equipment no-11884 s Chromatograph Dut/ Equipment C hormatograph Dut/ Equipment A & Chromatograph Br/J / Equip  Item inductivity IN sensor, wired up to j hutdown system. On 09Sep2021 it triggered resulting in the unit po  Name Shiva Prasad Hosmu	Connection Gas, <b>TG</b> : Trip Gas, <b>P</b> i licor area). t-box, rigloor) 72-001 and 12088033 no- 11883509 no- 12088039 nent no-12088032	Date of Calib  Date of Calib  15-Aug  14-Seg  14-Seg  3-Aug  Actic  Mud Weight IN ensor is not ge  Removed sensor and repla reinstating  Positi	las, SWB: Swab Gas, SC ration/Test 1-20 1-20 1-21 1-21 1-21 1-21 1-21 1-21	R: Gas from SCR, WTG: Wij  Status Bump Tc Calibrated with 1000ppm Calibrated with 1000ppm Calibrated with 1000ppm Calibrated with 1000ppm Investigation Calibrated with 1000ppm Calibrated with 1000ppm Calibrated with 1000ppm Investigation Date Arrh  Date Arrh 30-Aug-	st d % 8.10% S00 ppm mix gas s 500 ppm mix gas d d on PDC for still on PDC	ynamic Flow chec	2 x Backup s not communicating on from town technic working OK	Comment Working Working Working Working Working THA Working (Standby Comment with Slave. Troubleshootian.	y)