

LAB SHEET 8

Q1. Draw the Top view and Section Front View of the given assembly as shown in Fig.1.




FIG. 1

Q2. Draw the Top view and Section Front View of the object as shown in Fig.2.




FIG. 2

Q3. Draw the Top view and Section Front View of the object as shown in Fig.3. Cutting Plane is shown by A-A.




FIG. 3