




DETAIL OPTION I-THREADED SPACER SCALE 5.000



WHICH METHOD IS CHEAPER FOR MANUFACTURING?

OPTION I-THREADED SPACER OR DIMPLE





DETAIL OPTION 2-DIMPLE SCALE 5.000

