




This source describes Open Hardware and is licensed under the CERN-OHL-S v2.


You may redistribute and modify this source and make products using it under the terms of the CERN-OHL-S v2 (<https://ohwr.org/cernohlsv2.txt>). This source is distributed WITHOUT ANY EXPRESS OR IMPLIED WARRANTY, INCLUDING OF MERCHANTABILITY, SATISFACTORY QUALITY AND FITNESS FOR A PARTICULAR PURPOSE.


Please see the CERN-OHL-S v2 for applicable conditions.

Source location: <https://github.com/ploopyco/>


As per CERN-OHL-S v2 section 4, should You produce hardware based on this source, You must where practicable maintain the Source Location visible on the external case of the products you make using this source.









Pick and Place Fiducials




Spark Gaps -- Case

Since the case has gaps in it, we expect ESD to worm its way in via creepage and perhaps other ways. To protect the board from this eventuality, we place spark gaps along the edges.







Alternately, use
BIR-HO033A-TRB for
diode.

The PAW should be
configured to run in
current source mode.



