Test Specification v 1.0 :

- 1 Test All Commands sequentially
- 2 Test All Commands after reset execution
- 3 Test Reset after each command execution
- 4 Test Every Command executed twice in a row
- 5 All zeros on input
- 6 All ones on input