

DRAWN BY: KEVIN HILL DATE: 5/29/17 REV: A



ENGINEERING PARTS LIST

CRUMPLE ZONE ASSEMBLY, DP-2003

ITEM #	PART #	DESCRIPTION	QTY
1	DP-1012	CRUMPLE ZONE COMPONENT TOP	2
2	DP-1014	CRUMPLE ZONE COMPONENT SHORT	4
3	DP-1011	CRUSH CONE	1
4	DP-1010	FOAM HEMISPHERE	1
5	DP 1015	ALIGNMENT STRIP	1