
Scan-order diagnostic — inspect for drift and structured residuals
CH1 + CH2 (Hz)
Measured total
Fitted total
Measured − fitted (Hz)
CH1
CH2
Acquisition row (scan order)