
Scan-order diagnostic — inspect for drift and structured residuals
Measured total
Fitted total
CH1 + CH2 (Hz)
6000
5000
4000
3000
0
200
400
600
800
CH1
CH2
Measured − fitted (Hz)
1000
500
0
−500
0
200
400
600
800
Acquisition row (scan order)