
Scan-order diagnostic — inspect for drift and structured residuals
CH1 + CH2 (Hz)
Measured total
Fitted total
1800
1600
1400
1200
1000
800
600
0
200
400
600
800
Measured − fitted (Hz)
CH1
CH2
400
200
0
−200
0
200
400
600
800
Acquisition row (scan order)