

VIKRAM PATIL

B.Sc., Dip. in Auto Engg.

INSURANCE SURVEYOR , LOSS ASSESSOR & VALUER

Lic. No. : SLA-34369/2025-2028.
Expiry on: : 27-11-2028.
IISLA No. : F/W/00200
E-mail : vikram.dhule9@gmail.com
CELL : 9518510366, 9423662250

MOTOR,MARINE,ENGG
62, Vighnaharta Colony,
Near Aakshwani, Deopur,
Dhule- 424005.

Report No. : MOTOR-788/2026	Note : (0% Dep. Policy)	Date : 08/02/2026
Private And Confidential Motor (Final) Survey Report This report is issued by us as licenced Surveyors without prejudice, in respect of cause, nature & extent of loss / damage and subject to the terms & conditions of the Insurance policy.		
Policy No. : 77000031250960034114 Claim No. : 77000031250390068241 Period From : 08-10-2025 To 07-10-2026 I.D.V. : 1,213,518.00		
TYPE OF POLICY : Private Car Package Policy 1. INSURER : The New India Assurance Co. Ltd. Address : 770000 Divisional Office Bridge Plaza,North Wings C Road, Banglore.-560009 Policy Issuing Office : 770000 Divisional Office Appointing office : Claim Hub,Aurangabad. 2. INSURED : Dadaji Gangaram Rathod Address : Visapur Tanda,PO: Londhe,Tal.Chalisgaon. 3. H. P. A. WITH : Indusind Bank Ltd.		
4. VEHICLE PARTICULARS : RC VERIFIED Registration Number : MH.52.B.1850 Date of Registration : 01-11-2025 Chassis No. : MZBGB813LSN287724 Engine No. : D4FASM523328 Cubic Capacity/HP : 1493 CC Make / Model / Year : KIA India Private Limited\CARENS D1.5 6MT PREMIUM 0 7\2025 Type of Body : Station Wagon Class of Vehicle : LMV Pre-accident Condition : New R. L. W. /Seating Capacity : 2020 KG Unladen Weight : 1417 KG Fitness Cert. No. : NA Permit No. : NA Type of Permit : N.A. Route /Area of Operation : INDIA Road Tax Details : LTT Fuel Used : Diesel. Colour Of Vehicle : Clear White		
5. DRIVER'S PARTICULARS : ORIGINAL MDL VERIFIED Name of Driver : Mr.Vinod Uda Rathod. Address : A/P Visapur,Tal.Chalisgaon. M. D. L. No. : MH1920110037018 Date Of Birth : 01-01-1986 Age : 40 Date of Issue : 05-07-2011 Validity : 04-07-2031(NT) Issuing Authority : RTO Jalgaon Type of License : MCWG, LMV,3W-NT Badge No. : N.A. Authorised To Drive : N.A.		

Ref. No. :- MOTOR-788/2026

Vehicle No. : MH.52.B.1850

6. DETAILS OF ACCIDENT & SURVEY :		
Date & Time of Accident	: 30-01-2026 5:45 a.m.	
Place of Accident	: Near Satyam Jinning, Chalisgaon, On Chalisgaon- Dhule road.	
Place of Survey	: M/s. Jakhete Ventures LLP, Dhule	
Date of Allotment of Survey	: 05-02-2026	
Date & Time of Survey	: 05-02-2026 AND SUBSEQUENT VISITS.	
Date of Receipt of Spot Report	: Spot Survey Not conducted,as learnt.	
TPPD & TPPI :-		
THIRD PARTY DETAILS	: Nil ,as per claim form.	
7. SUMMARY OF ASSESSMENT:	Original Estimate ₹	Assessed ₹
Labour Charges	84896.28	77101.20
Labour From Parts		0.00
Plus Total Cost of Parts	1270101.61	1107294.62
TOTAL ₹	1354997.89	1184395.82
Less Excess		1000.00
Less Salvage		0.00
NET LOSS ASSESSED . ₹		1183396.00
8. FOR INSURER'S INFORMATION ONLY		
Approx Value of Spare Parts at List Price	₹	1107294.62
9. CAUSE AND NATURE OF ACCIDENT		
As per the claim form, the insured vehicle (IV) was proceeding towards Dhule from Chalisgaon. On the way, near Satyam Ginning, Chalisgaon, a T.P. truck suddenly came in front of the IV. As a result, the IV driver could not control the vehicle, and it dashed heavily against the truck, causing severe frontal damage to the IV.		
10. DETAILS OF ASSESSMENT : As Per Sheets Attached Here with		

In accordance with the instructions received from The New India Assurance Co.Ltd, Claim Hub, Chhatrapati Sambhajanagar Office, I, the undersigned, surveyed the subject ill-fated vehicle at M/s. Jakhete Venture LLP, MIDC, Awdhan, Dhule, on 05th February 2026. Photographs of the vehicle were taken and are enclosed herewith. I have verified the original RC, RC particulars, valid MDL, and the Insurance Policy, RTO tax receipt, Vehicle purchase Tax Invoice and all documents were found to be in order and same were enclosed herewith.

The damages sustained by the vehicle are consistent with the nature and cause of the accident as described in the claim form. The loss has been assessed without prejudice and is subject to the terms, conditions, exceptions, and limitations of the insurance policy.

As per the claim form, the insured vehicle (IV) was proceeding towards Dhule from Chalisgaon. On the way, near Satyam Ginning, Chalisgaon, a T.P. truck suddenly came in front of the IV. As a result, the IV driver could not control the vehicle, and it dashed heavily against the truck, resulting in severe frontal damage to the IV.

Due to the impact, the following components were found crushed/damaged: front bumper and grille assembly, bumper absorber, fog lamps and covers, RH/LH headlamps, hood panel assembly, front-end top and bottom cross members, front windshield glass, RH/LH fender panels and linings, intercooler, radiator,

Ref. No. :- MOTOR-788/2026**Vehicle No. : MH.52.B.1850**

condenser, fan shroud assembly, battery, ECU assembly, front hood lock member, front bottom cross member, front lower suspension arms, RH/LH shock absorbers, RH/LH apron members, front stabilizer bar and its linkages, RH/LH front strut assemblies, steering gear assembly, catalytic converter, engine mounting brackets (A, B, and C), RH/LH drive shafts, wiring loom, inner driver seat and co-driver seat, airbags and their module assembly, crash pad assembly, etc.

The insured/repairer has submitted a repair estimate amounting to Rs. 13,54,998/-. Initially, I assessed the loss on a repair basis at Rs. 11,83,396/- (excluding kept-open parts). However, the repair liability may increase further after dismantling during the repair process. I have advised the insured and repairer not to dismantle the vehicle and to maintain it in its present condition. The insured has agreed and has requested settlement of the claim on a Total Loss basis.

The vehicle is a KIA India Pvt. Ltd. make, Model Carens D1.5 6MT. The Insured Declared Value (IDV) of the subject vehicle is Rs. 12,13,518/- as per the policy schedule. The assessed repair liability of Rs. 11,83,396/- (excluding kept-open parts) exceeds 75% of the IDV, thereby making the case eligible for settlement on a Constructive Total Loss (CTL) basis. Accordingly, the vehicle has not been dismantled and is being kept in its accidental condition.

I have also suggested alternative economical modes of settlement, including:

Total Loss basis

Net Loss basis with RTO papers

Net Loss basis without RTO papers

Further, I have obtained both online and offline salvage quotations from prospective buyers, copies of which are enclosed for your perusal.

NOTE:- The policy Covers Return to Invoice cover.

The loss has been assessed as follows:

Assessment Sheet

Sr. No.	Particulars	GST	Estimated ₹	Assessed ₹			
				Glass 0%	Nil Dep. Metal	Nil Dep. Plas./Rub.	Labour
	SPARE PARTS						
1	GASKET KIT-ENGINE OVERHAUL	18%	11873.73			11873.73	
2	ENGINE ASSY-SUB	18%	148629.70		148629.70		
3	CASE ASSY-TIMING CHAIN	18%	13653.39		13653.39		
4	BRACKET ASSY-ENGINE MTG	18%	1966.95		1966.95		
5	BRACKET-ENGINE MTG SUPPORT	18%	11239.00		11239.00		
6	BRACKET ASSY-TRANSMISSION MTG	18%	1640.68		1640.68		
7	BRACKET ASSY-ROLL ROD	18%	1372.03		1372.03		
8	COVER-ROCKER	18%	3461.02		3461.02		
9	PUMP ASSY-COOLANT	18%	1870.34		1870.34		
10	RIBBED BELT-V/	18%	659.32			659.32	
11	TENSIONER ASSY	18%	1796.61		1796.61		
12	RADIATOR ASSY	18%	4407.63			4407.63	
13	FILLER NECK & HOSE ASSY-RAD	18%	980.51			980.51	
14	INSULATOR-RADIATOR MTG,LWR	18%	227.12			227.12	
15	BRKT ASSY-RADIATOR UPR MTG.LH	18%	158.47		158.47		

Ref. No. :- MOTOR-788/2026

Vehicle No. : MH.52.B.1850

15	BRKT ASSY-RADIATOR UPR MTG.LH	18%	158.47		158.47		
16	BLOWER ASSY - K.O.	18%	5277.97	KO ----	----	----	----
17	HOSE ASSY-RADIATOR,UPR	18%	406.78			406.78	
18	TANK ASSY-RESERVOIR	18%	569.49			569.49	
19	HOSE-RADIATOR TO RESERVOIR	18%	206.78			206.78	
20	HOUSING ASSY-THERMOSTAT	18%	8939.83		8939.83		
21	PIPE ASSY-WATER RETURN	18%	4634.75			4634.75	
22	FILTER ASSY-OIL	18%	3899.15			3899.15	
23	COOLER ASSY-ENG OIL	18%	9627.97		9627.97		
24	CLEANER ASSY-AIR	18%	933.90			933.90	
25	HOSE ASSY-AIR INTAKE	18%	4194.92			4194.92	
26	SENSOR ASSY-AIR FLOW	18%	15454.24			15454.24	
27	DUCT ASSY-AIR	18%	266.10			266.10	
28	SHIELD-AIR INTAKE	18%	124.58			124.58	
29	TURBOCHARGER	18%	35805.08		35805.08		
30	PIPE-OIL RETURN	18%	5424.58		5424.58		
31	PIPE-OIL FEED	18%	1160.17		1160.17		
32	HOSE&PIPE ASSY-I/C INLET	18%	4486.44		4486.44		
33	HOSE-INTERCOOLER INLET	18%	1160.17		1160.17		
34	HOSE-I/C OUTLET	18%	1310.17		1310.17		
35	INTERCOOLER	18%	8782.20			8782.20	
36	MANIFOLD ASSY-INTAKE	18%	26541.53		26541.53		
37	VALVE ASSY-EGR	18%	11082.20		11082.20		
38	EGR COOLER	18%	23721.19		23721.19		
39	PIPE-EGR	18%	4726.27		4726.27		
40	PROTECTOR-HEAT	18%	41.53			41.53	
41	CONVERTER ASSY-CATALYTIC - K.O.	18%	131398.30	KO ----	----	----	----
42	PANEL ASSY-UNDER COVER	18%	1007.63		1007.63		
43	GUARD-AIR	18%	2217.80			2217.80	
44	COVER ASSY-ENGINE	18%	4433.05			4433.05	
45	PEDAL ASSY-ACCELERATOR	18%	1906.78		1906.78		
46	PEDAL ASSY-BRAKE	18%	2648.31		2648.31		
47	INJECTOR ASSY-FUEL	18%	11142.37		11142.37		
48	VALVE ASSY-AIR CONTROL	18%	11677.12		11677.12		
49	STARTER ASSY	18%	7584.75		7584.75		
50	PLUG-GLOW	18%	804.24		804.24		
51	WIRING-GLOW PLUG	18%	1295.76	----	----	----	----
52	INSULATION PAD-BATTERY	18%	194.07			194.07	
53	TRAY ASSY-BATTERY	18%	467.80			467.80	
54	ELECTRONIC CONTROL UNIT	18%	48870.34			48870.34	
55	TRANSMISSION ASSY-MANUAL	18%	92593.22		92593.22		
56	ARM COMPLETE-FR LWR,LH	18%	3042.37		3042.37		

Ref. No. :- MOTOR-788/2026

Vehicle No. : MH.52.B.1850

57	STRUT ASSY-FR,LH	18%	3978.81		3978.81		
58	STRUT ASSY-FR,RH	18%	3978.81		3978.81		
59	COLUMN ASSY-STEERING	18%	32682.20		32682.20		
60	JOINT ASSY-STRG	18%	3028.81		3028.81		
61	MEMBER ASSY-RADIATOR SUPT.UPR	18%	2861.86		2861.86		
62	MEMBER ASSY-RADIATOR SUPT.LWR	18%	1250.85		1250.85		
63	PANEL COMPLETE-DASH	18%	16459.32		16459.32		
64	PANEL ASSY-FNDR APRON.LH	18%	3245.76		3245.76		
65	MEMBER ASSY-FRT SIDE INR COMPT.1	18%	2935.59		2935.59		
66	MEMBER ASSY-FRT SIDE INR COMPT.I	18%	2944.07		2944.07		
67	MEMBER ASSY-FRONT SIDE OTR,LH	18%	1155.93		1155.93		
68	MEMBER ASSY-FRONT SIDE OTR,RH	18%	1152.54		1152.54		
69	BEAM COMPLETE-FR BUMPER	18%	4035.59		4035.59		
70	PANEL-FENDER.LH	18%	1911.86		1911.86		
71	PANEL-FENDER.RH	18%	1912.71		1912.71		
72	PANEL ASSY-HOOD	18%	9101.69		9101.69		
73	HINGE ASSY-HOOD,RH	18%	511.02		511.02		
74	PANEL ASSY-FRONT DOOR.RH	18%	13731.36		13731.36		
75	BLACK TAPE-FR DR FRAME UPR,RH	18%	67.80			67.80	
76	BLACK TAPE-FR DR RR,RH	18%	78.81			78.81	
77	HINGE ASSY-FRONT DOOR,RH	18%	812.71		812.71		
78	HINGE ASSY-DOOR LOWER,RH	18%	1305.93		1305.93		
79	MODULE ASSY-STRG WHEEL AIR BAC	18%	5813.56		5813.56		
80	AIR BAG ASSY-PASSENGER	18%	5864.41			5864.41	
81	CURTAIN AIR BAG MODULE,LH	18%	6991.53		6991.53		
82	PAD-HOOD INSULATING	18%	974.58			974.58	
83	LATCH ASSY-HOOD	18%	1133.05		1133.05		
84	GLASS ASSY-FRONT DOOR,RH	18%	1064.41	1064.41			
85	INSULATOR: FENDER LH	18%	120.34			120.34	
86	GLOVE BOX ASSY	18%	1183.90			1183.90	
87	TRAY-STORAGE BOX	18%	52.54			52.54	
88	ARMREST ASSY-CONSOLE	18%	3594.07			3594.07	
89	STORAGE BOX-CONSOLE	18%	424.58			424.58	
90	CRASH PAD ASSY-MAIN	18%	6688.14			6688.14	
91	PANEL ASSY-LOWER CRASH PAD,RH	18%	390.68			390.68	
92	PANEL ASSY-CLUSTER FACIA	18%	444.92			444.92	
93	GLASS ASSY-WINDSHIELD	18%	4118.64	4118.64			
94	COVER ASSY-COWL TOP	18%	2497.46			2497.46	
95	GARNISH ASSY-FRT.LH	18%	2473.73			2473.73	
96	GARNISH ASSY-FR,RH	18%	2473.73			2473.73	
97	GRILLE ASSY-RADIATOR	18%	3990.68			3990.68	
98	COVER-RADIATOR GRILLE UPR	18%	294.92			294.92	

Ref. No. :- MOTOR-788/2026

Vehicle No. : MH.52.B.1850

99	COVER-FR BUMPER,LWR	18%	2161.86			2161.86	
100	ABSORBER-FRONT BUMPER ENERGY	18%	1538.98			1538.98	
101	BRACKET-FR BUMPER SIDE,LH	18%	80.51			80.51	
102	BRACKET-FR BUMPER SI	18%	80.51			80.51	
103	COVER-BLANKING FR FOG LH	18%	149.15			149.15	
104	COVER-BLANKING FRT FOG,RH	18%	110.17			110.17	
105	CAP-TOWING HOOK	18%	20.34			20.34	
106	LIP-FR BUMPER	18%	256.78			256.78	
107	PIECE-BUMPER GRILLE	18%	2934.75			2934.75	
108	GUARD ASSY-FRONT WHEEL,LH	18%	555.93			555.93	
109	GUARD ASSY-FRONT WHEEL,RH	18%	555.93			555.93	
110	GARNISH ASSY-FNDR SIDE.LH	18%	655.93			655.93	
111	GARNISH ASSY-FNDR SIDE,RH	18%	655.93			655.93	
112	GARNISH ASSY-FR DR SIDE RH	18%	1525.42			1525.42	
113	CUSHION ASSY-FR SEAT,,LH	18%	10145.76			10145.76	
114	CUSHION ASSY-FR SEAT,RH	18%	12437.29			12437.29	
115	BACK ASSY-FR SEAT,RH	18%	20382.20			20382.20	
116	S/BELT ASSY-FR LH	18%	3655.93			3655.93	
117	S/BELT ASSY-FR RH	18%	3252.54			3252.54	
118	CUSHION ASSY-2ND SEAT,LH	18%	23790.68			23790.68	
119	WIRING ASSY-MAIN	18%	7425.42			7425.42	
120	WIRING ASSY-FRT	18%	18822.03			18822.03	
121	LAMP ASSY-HEAD,LH	18%	9617.80			9617.80	
122	LAMP ASSY-HEAD,RH	18%	9617.80			9617.80	
123	LAMP ASSY-REAR COMB OUTSIDE,RH	18%	2022.03			2022.03	
124	SWITCH ASSY-MULTIFUNCTION	18%	2559.32			2559.32	
125	CONTACT ASSY-CLOCK SPRING	18%	5107.63			5107.63	
126	CLUSTER ASSY-INSTRUMENT	18%	24176.27			24176.27	
127	MODULE ASSY-AIR BAG CONTROL	18%	16113.56			16113.56	
128	SENSOR ASSY-A TYPE RASH	18%	1580.51			1580.51	
129	HORN ASSY-LOW PITCH	18%	901.69		901.69		
130	(CONDENSER ASSY-COOLER	18%	7457.63		7457.63		
131	HOSE & TUBE ASSY	18%	6282.20			6282.20	
132	PIPE & TUBE ASSY	18%	874.58			874.58	
133	HOSE-DISCHARGE	18%	1269.49			1269.49	
134	MOTOR ASSY-WINDSHIELD WIPER	18%	3823.73		3823.73		
135	LINKAGE ASSY-WINDSHIELD WIPER	18%	2886.44			2886.44	
136	BLADE ASSY-WIPER	18%	456.78			456.78	
137	BLADE ASSY-WIPER PASSENGER	18%	403.39			403.39	
138	RESERVOIR & PUMP ASSY-WASHER	18%	1165.25			1165.25	
139	BODY SELANT	18%	2318.64			2318.64	
140	SELANTS	18%	2796.22			2796.22	

Ref. No. :- MOTOR-788/2026

Vehicle No. : MH.52.B.1850

	SUB TOTAL SPARE PARTS	₹	1076357.29	5183.05	587299.19	345903.03	
	LABOUR						
1	SHORT ENGINE ASSY. R&R	18%	7130.00				7130.00
2	ROCKER COVER ASSY AND/OR GASKET. R&R	18%	682.00				682.00
3	RADIATOR ASSY, R&R	18%	1054.00				1054.00
4	RADIATOR RESERVOIR ASSY, R&R	18%	186.00				186.00
5	AIR CLEANER COVER ASSY, R&R	18%	124.00				124.00
6	AIR CLEANER BODY ASSY, R&R	18%	186.00				186.00
7	AIR CLEANER FILTER, R&R	18%	124.00				124.00
8	TURBOCHARGER ACTUATOR, R&R	18%	186.00				186.00
9	Accelerator Pedal Assy. R&R	18%	124.00				124.00
10	BRAKE PEDAL. R&R	18%	372.00				372.00
11	CRDI FUEL SYSTEM, INSPECTION	18%	124.00				124.00
12	STARTER MOTOR ASSY. R&R	18%	434.00				434.00
13	BATTERY ASSY, R&R	18%	124.00				124.00
14	FUEL TANK PROTECTOR ASSY, R&R	18%	558.00	----	----	----	----
15	FRONT LOWER ARM BALL JOINT ASSY. BOTH SIDES, R&R	18%	682.00				682.00
16	FRONT STRUT INSULATOR ASSY. BOTH SIDES. R&R	18%	868.00				868.00
17	STEERING COLUMN HOUSING, R&R	18%	558.00				558.00
18	FENDER PANEL ASSY. BOTH SIDES, R&R	18%	558.00				558.00
19	HOOD PANEL ASSY, R&R	18%	496.00				496.00
20	FRONT DOOR PANEL ASSY. BOTH SIDES, R&R	18%	1860.00				1860.00
21	CRASH PAD MAIN FRAME. R&R	18%	2356.00				2356.00
22	WINDSHIELD GLASS MOLDING, R&R	18%	1426.00				1426.00
23	FRONT WHEEL GUARD, BOTH SIDES. R&R	18%	372.00				372.00
24	FRONT BUMPER (COLOR-COAT)	18%	1116.00				1116.00
25	FRONT SEAT CUSHION PAD ASSY, BOTH SIDES, R&R	18%	744.00				744.00
26	FRONT SEAT BACK PANEL ASSY, ONE SIDE, R&R	18%	124.00				124.00
27	FRONT SEAT BELT, BOTH SIDES, R&R	18%	434.00				434.00
28	MAIN WIRING ASSY, R&R	18%	3038.00				3038.00
29	HEAD LAMP LED DRIVER MODULE, BOTH SIDES, R&R	18%	372.00				372.00
	SUB TOTAL LABOUR	₹	26412.00				25854.00
	PAINTING CHARGES						
1	Bonnet Painting (Pearl)	18%	10992.00				10992.00
2	Front Bumper Painting (Pcarl)	18%	5766.00				5766.00
3	Front Door Painting - LH (Pearl)	18%	8340.00				8340.00
4	Front Door Painting - RH (Pearl)	18%	8340.00				8340.00
5	Fender Painting - LH (Pearl) - NA	18%	6048.00	----	----	----	----

Ref. No. :- MOTOR-788/2026

Vehicle No. : MH.52.B.1850

5	Fender Painting - LH (Pearl) - NA	18%	6048.00	----	----	----	----
6	Fender Painting - RH (Pearf)	18%	6048.00				6048.00
	SUB TOTAL PAINTING CHARGES	₹	45534.00				39486.00
	Total Labour	₹	71946.00		--		65340.00
	GRAND TOTAL		1148303.29	5183.05	587299.19	345903.03	65340.00

SUMMARY OF ASSESSMENT				Estimate	Glass 0% Dep	Metal 0%	Nil Dep. Plas./Rub.	Labour
TOTAL FOR 18 %				1076357.29	5183.05	587299.19	345903.03	0.00
ADD CGST	9 %	₹	96872.16	466.47	52856.93	31131.27	0.00	0.00
ADD SGST	9 %	₹	96872.16	466.47	52856.93	31131.27	0.00	0.00
TOTAL PARTS		₹	1270101.61	6116.00	693013.04	408165.57		
TOTAL FOR 18 %			71946.00					65340.00
ADD CGST :	9 %	₹	6475.14					5880.60
ADD SGST	9 %	₹	6475.14					5880.60
TOTAL LABOUR		₹	84896.28					
Grand Total		₹	1354997.89	6116.00	693013.04	408165.57		77101.20
TOTAL		₹		6116.00	693013.04	408165.57		77101.20
TOTAL ASSESSED PARTS		₹	1107294.62					
TOTAL ASSESSED LABOUR		₹	77101.20					
TOTAL ASSESSED		₹	1184395.82					
Less Salvage		₹	0.00					
Less Excess		₹	1000.00					
NET ASSESSED LOSS		₹	1183396.00					
Total Kept Open Item		₹	136676.27					

(RUPEES ELEVEN LAKH EIGHTY THREE THOUSAND THREE HUNDRED NINETY SIX ONLY)

Sr. No.	Heading	₹	Grand Total
ASSESSMENT ON REPAIR BASIS			
1	Total (Refer assessment sheet attached)	1183396.00	
2	ADD: Provision for concealed Damages approx Rs-if any	136676.30	
3	NET LIABILITY OF INSURERS ON REPAIR BASIS	1320072.00	1320072.00
II. TOTAL LOSS BASIS:			
1	IDV (Insured declared value) AS PER POLICY	1213518.00	
2	Less Missing Parts	0.00	
3	ADD: Advt. Expenses	0.00	
4	ADD: Work Shop Rent	0.00	
5	Add Towing	0.00	
6	LESS: Compulsory Excess as per Policy	1000.00	

Ref. No. :- MOTOR-788/2026

Vehicle No. : MH.52.B.1850

6	LESS: Compulsory Excess as per Policy	1000.00	
7	LESS : Imposed Excess as per Policy	0.00	
8	NET LIABILITY OF INSURERS ON TOTAL LOSS BASIS	1212518.00	1212518.00
III. SALVAGE LOSS BASIS WITH RC:			
1	I D V AS PER POLICY	1213518.00	
2	LESS: Estimated SLAVAGE VALUE of the I.V. on "as is where is condition" (as on date of report) With R. C.	515000.00	
3	ADD: Towing expenses	0.00	
4	LESS: Compulsory Excess as per the Policy	1000.00	
5	LESS : Imposed Excess as per Policy	0.00	
6	NET LIABILITY ON NET OF SALVAGE BASIS:	697518.00	697518.00
IV. SALVAGE LOSS BASSIS WITHOUT RC:			
1	I D V AS PER POLICY	1213518.00	
2	LESS: Estimated SLAVAGE VALUE of the I.V. on "as is where is condition" (as on date of report) Without R.C.	180000.00	
3	ADD: Towing expenses	0.00	
4	LESS: Compulsory Excess as per the Policy	1000.00	
5	LESS : Imposed Excess as per Policy	0.00	
6	NET LIABILITY ON NET OF SALVAGE BASIS:	1032518.00	1032518.00

INSURER`S LIABILITY

A] REPAIRS BASIS : Rs1320072 /-. (Without Kept Open Parts)

C] NET LOSS BASIS WITH RTO VEHICLE PAPER : Rs. 697518/-.

D] NET LOSS BASIS WITHOUT RTO VEHICLE PAPER : Rs. 1032518/-.

Since the Liability is on Net Loss Basis with RTO Vehicle Paper at Rs.697518/-, is most economical from the underwriter's Point of view ,the underwriter may consider this mode of settlement & take suitable course of action as deemed fit to them.**(Insured has taken RTI cover in the policy).**

The damages sustained by the vehicle were concurrent with the cause and nature of the accident.

"ISSUED WITHOUT PREJUDICE"
VIKRAM PATIL**Enclose**

CLAIM FORM,ESTIMATE,DIGITAL PHOTOS & MY BILL FOR SURVEY.