




l2_bridging_cnf0_mbit4793hires.histogram.csv: tx: 9.39mpps, 0.05stdDev; rx: 9.40mpps, 0.00stdDev




l2_bridging_cnf0_mbit4803hires.histogram.csv: tx: 9.39mpps, 0.04stdDev; rx: 9.36mpps, 0.00stdDev





l2_bridging_cnf0_mbit4823hires.histogram.csv: tx: 9.46mpps, 0.05stdDev; rx: 9.35mpps, 0.03stdDev








l2_bridging_cnf0_mbit4843hires.histogram.csv: tx: 9.46mpps, 0.05stdDev; rx: 9.34mpps, 0.00stdDev


















l2_bridging_cnf1_mbit4326hires.histogram.csv: tx: 8.49mpps, 0.04stdDev; rx: 8.43mpps, 0.00stdDev











l2_bridging_cnf1_mbit4376hires.histogram.csv: tx: 8.55mpps, 0.04stdDev; rx: 8.53mpps, 0.00stdDev










l2_bridging_cnf1_mbit9000.histogram.csv: tx: 14.86mpps, 0.07stdDev; rx: 8.49mpps, 0.00stdDev



















l2_bridging_cnf2_mbit4803hires.histogram.csv: tx: 9.39mpps, 0.05stdDev; rx: 9.38mpps, 0.00stdDev




l2_bridging_cnf2_mbit4813hires.histogram.csv: tx: 9.46mpps, 0.04stdDev; rx: 9.36mpps, 0.00stdDev






l2_bridging_cnf2_mbit4833hires.histogram.csv: tx: 9.46mpps, 0.05stdDev; rx: 9.39mpps, 0.00stdDev



l2_bridging_cnf2_mbit4843hires.histogram.csv: tx: 9.46mpps, 0.05stdDev; rx: 9.41mpps, 0.00stdDev





l2_bridging_cnf2_mbit4853hires.histogram.csv: tx: 9.53mpps, 0.05stdDev; rx: 9.40mpps, 0.00stdDev





l2_bridging_cnf2_mbit9000.histogram.csv: tx: 14.86mpps, 0.07stdDev; rx: 9.38mpps, 0.00stdDev


















l2_bridging_cnf3_mbit4361hires.histogram.csv: tx: 8.55mpps, 0.04stdDev; rx: 8.54mpps, 0.00stdDev



















l2_bridging_cnf3_mbit9000.histogram.csv: tx: 14.86mpps, 0.07stdDev; rx: 8.52mpps, 0.04stdDev













l2_bridging_cnf4_mbit4776hires.histogram.csv: tx: 9.32mpps, 0.05stdDev; rx: 9.33mpps, 0.00stdDev




l2_bridging_cnf4_mbit4786hires.histogram.csv: tx: 9.39mpps, 0.05stdDev; rx: 9.38mpps, 0.00stdDev




l2_bridging_cnf4_mbit4796hires.histogram.csv: tx: 9.39mpps, 0.05stdDev; rx: 9.37mpps, 0.00stdDev






l2_bridging_cnf4_mbit4816hires.histogram.csv: tx: 9.46mpps, 0.05stdDev; rx: 9.39mpps, 0.00stdDev




l2_bridging_cnf4_mbit4826hires.histogram.csv: tx: 9.46mpps, 0.05stdDev; rx: 9.40mpps, 0.00stdDev



l2_bridging_cnf4_mbit4836hires.histogram.csv: tx: 9.46mpps, 0.04stdDev; rx: 9.28mpps, 0.00stdDev











l2_bridging_cnf4_mbit9000.histogram.csv: tx: 14.86mpps, 0.08stdDev; rx: 9.37mpps, 0.00stdDev


0.075 0.050 0.025 0.000














l2_bridging_cnf5_mbit4780hires.histogram.csv: tx: 9.39mpps, 0.05stdDev; rx: 9.37mpps, 0.00stdDev





l2_bridging_cnf5_mbit4810hires.histogram.csv: tx: 9.39mpps, 0.05stdDev; rx: 9.38mpps, 0.00stdDev







l2_bridging_cnf5_mbit4830hires.histogram.csv: tx: 9.46mpps, 0.05stdDev; rx: 9.38mpps, 0.00stdDev





l2_bridging_cnf5_mbit4840hires.histogram.csv: tx: 9.46mpps, 0.05stdDev; rx: 9.25mpps, 0.00stdDev





















































l2_bridging_mbit5100.histogram.csv: tx: 9.99mpps, 0.05stdDev; rx: 9.32mpps, 0.00stdDev




l2_bridging_mbit5400.histogram.csv: tx: 10.58mpps, 0.05stdDev; rx: 9.35mpps, 0.00stdDev





















l2_multimac_00000100_mbit3565hires.histogram.csv: tx: 6.97mpps, 0.04stdDev; rx: 6.97mpps, 0.00stdDev







l2_multimac_00000100_mbit3575hires.histogram.csv: tx: 6.97mpps, 0.04stdDev; rx: 6.88mpps, 0.00stdDev



l2_multimac_00000100_mbit3585hires.histogram.csv: tx: 7.01mpps, 0.04stdDev; rx: 6.96mpps, 0.00stdDev



l2_multimac_00000100_mbit3595hires.histogram.csv: tx: 7.01mpps, 0.05stdDev; rx: 6.94mpps, 0.00stdDev






l2_multimac_00000100_mbit3605hires.histogram.csv: tx: 7.05mpps, 0.05stdDev; rx: 6.97mpps, 0.03stdDev







l2_multimac_00000100_mbit9000.histogram.csv: tx: 10.16mpps, 0.06stdDev; rx: 6.94mpps, 0.00stdDev


0.025









l2_multimac_00001000_mbit3441hires.histogram.csv: tx: 6.75mpps, 0.04stdDev; rx: 6.74mpps, 0.00stdDev









l2_multimac_00001000_mbit3471hires.histogram.csv: tx: 6.78mpps, 0.04stdDev; rx: 6.79mpps, 0.00stdDev

l2_multimac_00001000_mbit3481hires.histogram.csv: tx: 6.82mpps, 0.04stdDev; rx: 6.76mpps, 0.00stdDev



l2_multimac_00001000_mbit3491hires.histogram.csv: tx: 6.82mpps, 0.04stdDev; rx: 6.79mpps, 0.00stdDev




l2_multimac_00001000_mbit3501hires.histogram.csv: tx: 6.86mpps, 0.04stdDev; rx: 6.81mpps, 0.00stdDev





l2_multimac_00001000_mbit3511hires.histogram.csv: tx: 6.86mpps, 0.04stdDev; rx: 6.78mpps, 0.00stdDev








l2_multimac_00001000_mbit9000.histogram.csv: tx: 10.12mpps, 0.05stdDev; rx: 6.78mpps, 0.00stdDev
























l2_multimac_00010000_mbit3482hires.histogram.csv: tx: 6.82mpps, 0.05stdDev; rx: 6.77mpps, 0.00stdDev

0.50

l2_multimac_00010000_mbit3492hires.histogram.csv: tx: 6.82mpps, 0.04stdDev; rx: 6.79mpps, 0.00stdDev




l2_multimac_00010000_mbit3502hires.histogram.csv: tx: 6.86mpps, 0.04stdDev; rx: 6.81mpps, 0.00stdDev





l2_multimac_00010000_mbit3512hires.histogram.csv: tx: 6.86mpps, 0.04stdDev; rx: 6.79mpps, 0.00stdDev







l2_multimac_00010000_mbit9000.histogram.csv: tx: 10.13mpps, 0.05stdDev; rx: 6.78mpps, 0.03stdDev








l2_multimac_00100000_mbit3391hires.histogram.csv: tx: 6.64mpps, 0.04stdDev; rx: 6.64mpps, 0.00stdDev





















l2_multimac_00100000_mbit3471hires.histogram.csv: tx: 6.78mpps, 0.04stdDev; rx: 6.75mpps, 0.00stdDev







l2_multimac_00100000_mbit3491hires.histogram.csv: tx: 6.82mpps, 0.04stdDev; rx: 6.75mpps, 0.00stdDev





l2_multimac_00100000_mbit9000.histogram.csv: tx: 10.12mpps, 0.05stdDev; rx: 6.72mpps, 0.00stdDev









































l2_multimac_01000000_mbit9000.histogram.csv: tx: 10.11mpps, 0.05stdDev; rx: 6.50mpps, 0.01stdDev




























l2_multimac_10000000_mbit3083hires.histogram.csv: tx: 6.03mpps, 0.04stdDev; rx: 5.96mpps, 0.04stdDev









l2_multimac_10000000_mbit3103hires.histogram.csv: tx: 6.06mpps, 0.04stdDev; rx: 5.97mpps, 0.03stdDev





l2_multimac_10000000_mbit9000.histogram.csv: tx: 10.18mpps, 0.05stdDev; rx: 5.96mpps, 0.00stdDev


0.075
















l2_xconnect_mbit5291hires.histogram.csv: tx: 10.41mpps, 0.05stdDev; rx: 10.30mpps, 0.00stdDev





l2_xconnect_mbit5311hires.histogram.csv: tx: 10.41mpps, 0.05stdDev; rx: 10.36mpps, 0.00stdDev




l2_xconnect_mbit5321hires.histogram.csv: tx: 10.41mpps, 0.05stdDev; rx: 10.36mpps, 0.00stdDev



l2_xconnect_mbit5331hires.histogram.csv: tx: 10.41mpps, 0.05stdDev; rx: 10.22mpps, 0.00stdDev



l2_xconnect_mbit5341hires.histogram.csv: tx: 10.49mpps, 0.05stdDev; rx: 10.35mpps, 0.00stdDev



l2_xconnect_mbit9000.histogram.csv: tx: 14.87mpps, 0.07stdDev; rx: 10.33mpps, 0.00stdDev

