




The BMOW: Big Mess O' Wires

Credit: Steve Chamberlain, BigMessOWires.com


























OP 0000






OP S 0000 1






OP	S	CTRL 1
0000	1	0011






ОР	S	CTRL 1	CTRL 2
0000	1	0011	0111





OP	S	CTRL 1	CTRL 2	CTRL 3
0000	1	0011	0111	0001





OP	S	CTRL 1	CTRL 2	CTRL 3								
0000	1	0011	0111	0001	•	•	•	•	•	•	•	

