

## RETURN/PARTS ORDER

SHIP TO: Jonathan Medefind

1210 R St NW Apt B9 Washington, DC 20009

[Phone]

jmedefind@gmail.com

WORK ORDER NO. 113

DATE: February 19, 2016

STEAK LOCKER ORDER ID: SL0002101

SUPPORT DESK JOB NUMBER: 564

REPLACEMENT STEAK LOCKER REQUEST:			
QUANTITY	DESCRIPTION	UNIT PRICE PAID	LINE TOTAL
Description of Damage or Defect:			
Atomizer/Controller is leaking out of the bottom of the case. Please have forwarding address to Gustavo Aguirre			
1431 N Melrose Dr #105, Vista CA 92083			
REPLACEMENT PARTS ORDER:			
QUANTITY	DESCRIPTION		
1	Atomizer/Controller	n/a	0
INTERNAL USE/AUTHORIZATION:			
DATE RECIVED TRACKING NUMBER SHIPMENT SERVICE			
DATE RECIVED	TRIORITO TONIDER	SHII WERT SERVICE	
		SUBTOTAL	
		DELIVERY	
		TOTAL	
THANK YOU FOR YOUR BUSINESS!			
TIMUR TOUTOR TOUR BUSINESS:			