

RETURN/PARTS ORDER

SHIP TO:

John Watts 66 Bayou Circle Gulfport, MS 39507 [Phone] WORK ORDER NO. 109

DATE: February 9, 2016

STEAK LOCKER ORDER ID: SL0001785

jwats4golf@cs.com

SUPPORT DESK JOB NUMBER: 522

REPLACEMENT STEAK LOCKER REQUEST:			
QUANTITY	DESCRIPTION	UNIT PRICE PAID	LINE TOTAL
Description of Damage or Defect:			
New device needed due to extreme variance in humidity. Please have forwarding address to Gustavo Aguirre			
1431 N Melrose Dr #105, Vista CA 92083			
DEDLACEMENT DADTE ODDED			
REPLACEMENT PARTS ORDER:			
QUANTITY	DESCRIPTION DESCRIPTION	- /-	
1	Atomizer/Controller	n/a	0
INTERNAL USE/AUTHORIZATION:			
DATE RECIVED	TRACKING NUMBER	SHIPMENT SERVICE	
		SUBTOTAL	
		DELIVERY	
		TOTAL	
THANK YOU FOR YOUR BUSINESS!			