

## RETURN/PARTS ORDER

SHIP TO:

Tom Clendenin 10713 20th AVE NE Seattle, WA 98125 [Phone]

 $tom\_clendenin@yahoo.com$ 

WORK ORDER NO. 116

DATE: February 25, 2016

STEAK LOCKER ORDER ID: SL0000307

SUPPORT DESK JOB NUMBER: 557

REPLACEMENT STEAK LOCKER REQUEST:			
QUANTITY	DESCRIPTION	UNIT PRICE PAID	LINE TOTAL
Description of Damage or Defect:			
Atomizer/Controller is reading humidity over 100%. Please have forwarding address to Gustavo Aguirre			
1431 N Melrose Dr #105, Vista CA 92083			
DEDLA CENTENTE DA DESCONDED			
REPLACEMENT PARTS ORDER:			
QUANTITY	DESCRIPTION		-
1	Atomizer/Controller	n/a	0
INTERNAL USE/AUTHORIZATION:			
DATE RECIVED TRACKING NUMBER SHIPMENT SERVICE			
DATE RECIVED	TRIORITO TONIDER	SHII MENT SERVICE	
		SUBTOTAL	
		DELIVERY	
		TOTAL	
THANK YOU FOR YOUR BUSINESS!			
THAINK TOU FOR TOUR BUSHINESS:			