





## 3-AXIS ACCELEROMETER







## AMBIENT LIGHT SENSOR




J1 > 4×


SWDCLK


C6 100n

Pickit 5 Conn

## TEMPERATURE & HUMIDITY SENSOR







TODO: USB-C connector has mounting pins. The footprint should be updated accordingly.