data a db 12 db 25 db ? code mov ax,@data mov ds,ax mov al, a add al,b mov c,al mov ah,4ch int 21h end

1=Help


Line:1 Col:1








DOSBox 0.74 3. Cpu speed max 100% cycles, Fr.





mov ax,a
add ax,b
mov c,ax
mov ah,4ch
int 21h
end

