



Automation I...

/storage/emulate...



sensor_simulation.py

Automation logic.py

```
1 import random
2 from datetime import datetime
3
4 print("=== IoT Automation System ===")
5 print()
6
7 for i in range(5):
8     temperature = round(random.
9         uniform(20.0, 45.0), 2)
10    humidity = round(random.uniform(30.0,
11        90.0), 2)
12    motion = random.choice(["Detected",
13        "Not Detected"])
14    timestamp = datetime.now().
15        strftime("%Y-%m-%d %H:%M:%S")
16
17    print(f"Reading {i+1}: [{timestamp}]")
18    print(f"Temperature : {temperature}°C")
19    print(f"Humidity : {humidity}%")
20    print(f"Motion : {motion}")
21
22    # Automation Rules
23    print(">> Alerts:")
24    if temperature > 35:
25        print(" 🚫 HIGH TEMP ALERT! Turn
26        on AC!")
27    else:
28        print(" ✅ Temperature Normal")
29
30    if humidity > 70:
31        print(" 🚫 HIGH HUMIDITY
32        Turn on Fan!")
```

Tab

:

;

'

#





sensor_simulation.py

Automation logic.py

```
18 # Automation Rules
19 print(">> Alerts:")
20 if temperature > 35:
21     print(" 🚫 HIGH TEMP ALERT! Turn
on AC!")
22 else:
23     print(" ✅ Temperature Normal")
24
25 if humidity > 70:
26     print(" 🚫 HIGH HUMIDITY ALERT!
Turn on Fan!")
27 else:
28     print(" ✅ Humidity Normal")
29
30 if motion == "Detected":
31     print(" 🚫 MOTION ALERT! Security
triggered!")
32 else:
33     print(" ✅ No Motion")
34
35 print("-" * 35)
36
37 print()
38 print("Automation Complete!")
```





TAB



=== IoT Automation System ===

Reading 1: [2026-06-03 16:24:03]

Temperature : 21.16°C

Humidity : 57.66%

Motion : Not Detected

>> Alerts:

✓ Temperature Normal

✓ Humidity Normal

✓ No Motion

Reading 2: [2026-06-03 16:24:03]

Temperature : 24.45°C

Humidity : 77.31%

Motion : Not Detected

>> Alerts:

✓ Temperature Normal

● HIGH HUMIDITY ALERT! Turn on Fan!

✓ No Motion

Reading 3: [2026-06-03 16:24:03]

Temperature : 22.01°C

Humidity : 64.63%

Motion : Not Detected

>> Alerts:

✓ Temperature Normal

✓ Humidity Normal

✓ No Motion

Reading 4: [2026-06-03 16:24:03]

Temperature : 35.09°C

Humidity : 39.71%

Motion : Not Detected

>> Alerts:

● HIGH TEMP ALERT! Turn on AC!

✓ Humidity Normal

✓ No Motion

Reading 5: [2026-06-03 16:24:03]

Temperature : 23.6°C

Humidity : 87.63%

Motion : Detected

>> Alerts:

✓ Temperature Normal

● HIGH HUMIDITY ALERT! Turn on Fan!

● MOTION ALERT! Security triggered!

Automation Complete!

[Program finished]

