Zachowanie	Funkcja przejścia	lt	rt	tq	th	te	ls	rs	tsq	tse	tsh
idle	passive	X	X								
safe	enableAndHome				X	X				X	X
	passive	X	X	X							
	errorHandling						X	X	X		
jntImp	jntMove	X	X	X					X		
	errorHandling						X	X	X		
cartImp	cartMove	X	X	X					X		
	errorHandling				X	X	X	X	X		
safeCol	safeColMove	X	X	X							
	errorHandling				X	X	X	X	X		