```
Successfully connected to 10.242.18.107
______
222222MSP SANSWITCH HARDWARE STATUS2222
______
Cisco Nexus Operating System (NX-OS) Software
TAC support: http://www.cisco.com/tac
Documents: http://www.cisco.com/en/US/products/ps9372/tsd_products_support_series_home.html
Copyright (c) 2002-2011, Cisco Systems, Inc. All rights reserved.
The copyrights to certain works contained herein are owned by
other third parties and are used and distributed under license.
Some parts of this software are covered under the GNU Public
License. A copy of the license is available at
http://www.gnu.org/licenses/gpl.html.
Software
  BIOS:
           version 1.0.19
  loader:
           version N/A
  kickstart: version 5.2(2)
  system: version 5.2(2)
  BIOS compile time:
                        02/01/10
  kickstart image file is: bootflash:///m9100-s3ek9-kickstart-mz.5.2.2.bin
  kickstart compile time: 12/25/2020 12:00:00 [01/17/2012 23:12:32]
 system image file is: bootflash://m9100-s3ek9-mz.5.2.2.bin
system compile time: 12/30/2011 14:00:00 [01/18/2012 00:47:06]
Hardware
  cisco MDS 9148 FC (1 Slot) Chassis ("1/2/4/8 Gbps FC/Supervisor-3")
  Motorola, e500v2 with 1036300 kB of memory.
  Processor Board ID JAF1639BBGK
 Device name: shnetwpfcsw902
  bootflash:
             1000944 kB
Kernel uptime is 1261 day(s), 15 hour(s), 4 minute(s), 17 second(s)
Last reset at 537259 usecs after Tue Nov 20 12:55:18 2012
  Reason: Reset due to upgrade
  System version: 5.0(1a)
 Service:
```

Switch hardware ID information

Switch is booted up Switch type is: MDS 9148 FC (1 Slot) Chassis Model number is DS-C9148-16P-K9 H/W version is 1.1 Part Number is 73-11862-06 Part Revision is A0 Manufacture Date is Year 16 Week 35 Serial number is AMS16350905 CLEI code is CMMFV00ARA

_____ Chassis has 1 Module slots

Module1 ok Module type is: 1/2/4/8 Gbps FC/Supervisor-3 0 submodules are present Model number is DS-C9148-K9-SUP H/W version is 1.1

Part Number is 73-11862-06 Part Revision is A0

```
Manufacture Date is Year 16 Week 39
 Serial number is JAF1639BBGK
 CLEI code is CMMFV00ARA
Chassis has 2 PowerSupply Slots
-----
PS1 ok
 Power supply type is: 300.00W 110v/220v AC
 Model number is DS-C48-300AC
 H/W version is 160.0
 Part Number is 341-0320-01
 Part Revision is A0
 Manufacture Date is Year 16 Week 28
 Serial number is QCS1628K140
 CLEI code is
PS2 ok
 Power supply type is: 300.00W 110v/220v AC
 Model number is DS-C48-300AC
 H/W version is 160.0
 Part Number is 341-0320-01
 Part Revision is A0
 Manufacture Date is Year 16 Week 27
 Serial number is QCS1627K0AZ
 CLEI code is
_____
Chassis has 4 Fan slots
Fan1 ok
Fan2 ok
Fan3 ok
Fan4 ok
_______
222222MSP SANSWITCH ENVIRONMET STATUS2222
______
Clock:
_____
          Model
                          Hw
                                 Status
Clock
          Clock Module --
                                  NotSupported/None
Fan:
          Model
                          Hw
-----
ChassisFan1 FAN Module 1 --
ChassisFan2 FAN Module 2 --
ChassisFan3 FAN Module 3 --
                                  0k
                                  0k
ChassisFan4 FAN Module 4
                          --
Fan_in_PS1
                                  0k
```

0k

Temperature:

Fan_in_PS2

Fan Air Filter : NotSupported

Module	Sensor	MajorThresh (Celsius)	MinorThres (Celsius)	CurTemp (Celsius)	Status
1	Outlet	75	60	35	0k
1	Outlet	75	60	38	0k
1	Intake	65	50	35	0k
1	Intake	65	50	36	0k

Power Supply: Voltage: 12 Volts

PS	Model	Power (Watts)	Power (Amp)	Status
1	DS-C48-300AC DS-C48-300AC	300.00 300.00	25.00 25.00	0k 0k

	Status ted	
(Watts) (Amp) (Watts) (Amp)	 Powered-U	- ว

Power Usage Summary:

Power Supply redundancy mode: Redundant Power Supply redundancy operational mode: Redundant

Total Power Capacity 2222 300.00 W

Power reserved for Supervisor and Fan Module(s) № 120.00 W

??????------

Total Power Available 180.00 W

222222------

222222MSP SANSWITCH INTERFACE STATUS2222

Interface	Vsan	Admin Mode	Admin Trunk Mode	Status	SFP	Oper Mode	Oper Speed (Gbps)	Port Channel
fc1/1	1	 Е	on	trunking	swl	TE	8	1
fc1/2	1	Е	on	trunking	swl	TE	8	1
fc1/3	200	F	on	up	swl	F	8	
fc1/4	200	F	on	up	swl	F	8	
fc1/5	200	F	on	up	swl	F	8	
fc1/6	200	F	on	up	swl	F	8	
fc1/7	200	F	on	up	swl	F	8	
fc1/8	200	F	on	up	swl	F	8	
fc1/9	200	F	on	up	swl	F	8	
fc1/10	200	F	on	up	swl	F	8	
fc1/11	200	F	on	up	swl	F	8	
fc1/12	200	F	on	up	swl	F	8	
fc1/13	200	F	on	notConnected	swl			
fc1/14	200	F	on	notConnected	swl			
fc1/15	200	F	on	up	swl	F	8	
fc1/16	200	F	on	up	swl	F	8	
fc1/17	200	F	on	down	swl			

1 (1/10	200	'	OII	·	OWIT	SWI			
fc1/19	200	F	on	C	lown	swl			
fc1/20	200	F	on	c	lown	swl			
fc1/21	200	F	on	ι	ıp	swl	F	8	
fc1/22	200	F	on		ip	swl	F	8	
fc1/23	200	F	on		ip	swl	F	8	
fc1/24	200	F	on		ip	swl	F	8	
								O	
fc1/25	200	F	on		lown	swl			
fc1/26	200	F	on		lown	swl			
fc1/27	200	F	on	C	lown	swl			
fc1/28	200	F	on	C	lown	swl			
fc1/29	200	F	on	c	lown	swl			
fc1/30	200	F	on	c	lown	swl			
fc1/31	200	F	on		lown	swl			- -
fc1/32	200	F	on		lown	swl			
fc1/33	200	F			lown	swl			
			on						
fc1/34	200	F	on		lown	swl			
fc1/35	200	F	on		lown	swl			
fc1/36	200	F	on		lown	swl			
fc1/37	200	F	on	c	lown	swl			
fc1/38	200	F	on	c	lown	swl			
fc1/39	200	F	on		lown	swl			
fc1/40	200	F	on		lown	swl			
fc1/40 fc1/41	200	F	on		lown	swl			
fc1/42	200	F	on		lown	swl			
fc1/43	200	F	on		lown	swl			
fc1/44	200	F	on		lown	swl			
fc1/45	200	F	on	C	lown	swl			
fc1/46	200	F	on	c	lown	swl			
fc1/47	200	F	on	c	lown	swl			
fc1/48	200	F	on		lown	swl			
 Interface				 atus			Spe		
Incernace	;		30	acus					
							(Gb	hə)	
cun fco							1		
sup-fc0			ир				1		
Interface					IP Address				
ngmt0					10.242.18.10				
 [ntonface			Vean	 Admin	Status		0non		
THEFT	;		v Sdi i						-
				irunk			Speed		5
				Mode			(Gbps)		
ort-chan	nel 1		1	on	trunking	TE	16		
					-				
	:======	=====	=====	======	========	=====	======	======	=======================================
222222MSP	SANSWT	TCH I	OG STA	TUSER]				
						=====	:======	======	=======================================
					2 last message				
					2 last message				
7016 Anr					2 last message				
	28 15:5				2 last message				
2016 Apr		9:40	shnetw	pfcsw90	2 last message	repea	ited 1 ti	me	
2016 Apr					2 last message				
2016 Apr 2016 Apr	28 21:5	9:40	SIIIIecw						
2016 Apr 2016 Apr 2016 Apr	28 21:5 29 03:5				2 last message	renea	iteu i i	IIIC	
2016 Apr 2016 Apr 2016 Apr 2016 Apr	28 21:5 29 03:5 29 09:5	9:39	shnetw	pfcsw90	2 last message 2 last message				
2016 Apr 2016 Apr 2016 Apr 2016 Apr 2016 Apr	28 21:5 29 03:5 29 09:5 29 15:5	9:39 9:40	shnetw shnetw	pfcsw90 pfcsw90	2 last message	repea	ted 1 ti	me	
2016 Apr 2016 Apr 2016 Apr 2016 Apr 2016 Apr 2016 Apr	28 21:5 29 03:5 29 09:5 29 15:5 29 21:5	9:39 9:40 9:40	shnetw shnetw shnetw	pfcsw90 pfcsw90 pfcsw90	2 last message 2 last message	repea repea	ted 1 ti ted 1 ti	me me	
2016 Apr 2016 Apr 2016 Apr 2016 Apr 2016 Apr 2016 Apr 2016 Apr	28 21:5 29 03:5 29 09:5 29 15:5 29 21:5 30 03:5	9:39 9:40 9:40 9:40	shnetw shnetw shnetw shnetw	pfcsw90 pfcsw90 pfcsw90 pfcsw90	2 last message 2 last message 2 last message	repea repea repea	ted 1 ti ted 1 ti ted 1 ti	me me me	
2016 Apr 2016 Apr 2016 Apr 2016 Apr 2016 Apr 2016 Apr 2016 Apr 2016 Apr	28 21:5 29 03:5 29 09:5 29 15:5 29 21:5 30 03:5 30 09:5	9:39 9:40 9:40 9:40 9:40	shnetw shnetw shnetw shnetw shnetw	pfcsw90 pfcsw90 pfcsw90 pfcsw90 pfcsw90	2 last message 2 last message 2 last message 2 last message	repea repea repea repea	ted 1 ti ted 1 ti ted 1 ti ted 1 ti	me me me me	
016 Apr 016 Apr 016 Apr 016 Apr 016 Apr 016 Apr 016 Apr	28 21:5 29 03:5 29 09:5 29 15:5 29 21:5 30 03:5 30 09:5	9:39 9:40 9:40 9:40 9:40	shnetw shnetw shnetw shnetw shnetw	pfcsw90 pfcsw90 pfcsw90 pfcsw90 pfcsw90	2 last message 2 last message 2 last message	repea repea repea repea	ted 1 ti ted 1 ti ted 1 ti ted 1 ti	me me me me	

fc1/18

200 F

on

down

swl

```
2016 Apr 30 21:59:40 shnetwpfcsw902 last message repeated 1 time
2016 May 1 03:59:40 shnetwpfcsw902 last message repeated 1 time
2016 May 1 09:59:40 shnetwpfcsw902 last message repeated 1 time
2016 May 1 15:59:40 shnetwpfcsw902 last message repeated 1 time
2016 May 1 21:59:39 shnetwpfcsw902 last message repeated 1 time
2016 May 2 03:59:39 shnetwpfcsw902 last message repeated 1 time
2016 May 2 09:59:40 shnetwpfcsw902 last message repeated 1 time
2016 May 2 15:59:40 shnetwpfcsw902 last message repeated 1 time
2016 May 2 21:59:47 shnetwpfcsw902 last message repeated 1 time
2016 May 3 03:59:44 shnetwpfcsw902 last message repeated 1 time
2016 May 3 09:59:52 shnetwpfcsw902 last message repeated 1 time
2016 May 3 15:14:45 shnetwpfcsw902 %CALLHOME-2-EVENT: PERIODIC_CONFIGURATION
2016 May 3 15:59:44 shnetwpfcsw902 %LIBIFMGR-5-ALL_COUNTERS_CLEARED: All interface counters cleared by user
2016 May 3 21:59:39 shnetwpfcsw902 last message repeated 1 time
2016 May 4 03:59:39 shnetwpfcsw902 last message repeated 1 time
2016 May 4 09:59:39 shnetwpfcsw902 last message repeated 1 time
2016 May 4 15:59:39 shnetwpfcsw902 last message repeated 1 time
2016 May 4 21:59:40 shnetwpfcsw902 last message repeated 1 time
```

222222MSP SANSWITCH LOG CLEAR STATUS2222

10.242.18.107 should now be disconnected and disposed.