Install firmware - Tag proximity

- 1. install mplab x ipe & ide
- 2. make a project in ide env. add source and header files.
- 3. fix the */ in all files
- 4. add the main.c as default source file not the main-ISI-original.c as mentioned in Makefile
- 5. Add define _LEGACY_HEADERS in config.h to resolve OPTION_REG = CONFIG_CPU_OPTION. but problem didn't resolve. so commented out to make progress.