

## FIRST INSPECTION REPORT

INSURED/POLICYHOLDER: MICHAEL LEE

ADDRESS: MISSISSAUGA, ON L5N 3T4

**INSURER:** GUARDIAN CO.

**CLAM #: PR2145** 

ADJUSTER/ CLAIM REP: TOP GUN

DATE OF INSPECTION: MARCH 21, 2025

DATE OF LOSS: MARCH 19, 2025

DATE OF REPORT: MARCH 22, 2025

**TYPE OF LOSS: FIRE** 

Front Photo:




Image 1

## **CAUSE OF LOSS:**

The loss was caused by a kitchen fire that spread to the living room before being contained.

## **SCOPE OF WORK:**

The following is a brief outline of the work to be completed on the contents portion of this claim.

- 1. Pack out salvageable items.
- 2. Clean soot from surfaces.
- 3. Remove damaged cabinetry and appliances.
- 4. Restore interior walls and ceiling.
- 5. Reinstall fixtures and fittings.

### RECOMMENDED RESERVES FOR TRINITY'S INVOLVEMENT:

The estimated cost for Trinity's involvement is as follows:

• Indemnity Work: Should not exceed \$21,116.00 plus HST

Our actual cost will be adjusted once the exact scope of approved work is known. The recommended estimate is only based on visual inspection for reserves setting purposes.

• Trinity Listing & Pricing Expense Reserve: Should not exceed \$3,782.00 plus HST

## RECOMMENDED RESERVES FOR THE TOTAL CONTENTS LOSS:

Based on a visual inspection of the extent of non-salvageable items on the main floor, we believe that the total replacement cost for the non-salvageable items should not exceed \$11,400.00 plus HST.

## **CONCLUSION:**

Once our scope of work is approved, we can attend and begin the pack out process.

Thank You,

#### Mo Waez

Trinity Contents Management mo@trinitycontents.com (647) 613-2246

# **BEDROOM1 AREA**





Image 2 Image 3





# **BEDROOM2 AREA**






Image 2 Image 3





Image 2 Image 3

# **KITCHEN AREA**





Image 2 Image 3





# **LIVING AREA**





Image 2 Image 3





# **STORAGE AREA**







Image 2