Individual Printer Performance and Anomaly Report

EPR-001

Offset Press A · HeidelPress XL-106 · Plant 1 - Hall A

PRINTER INFORMATION

Printer ID	EPR-001
Printer name	Offset Press A
Model	HeidelPress XL-106
Machine type	Offset
Location	Plant 1 - Hall A
Installed	2019-01-10
Last recorded status	IDLE
Status mix over period	IDLE 415, PRINTING 424, MAINTENANCE 12, ERROR 13
Total telemetry readings	864
Monitoring period	2026-10-15 00:00:00 to 2026-10-17 23:55:00
Report generated	2026-10-26 13:54:50.605

CONFIGURED SENSOR THRESHOLD LIMITS

SENSOR	LOWER LIMIT	UPPER LIMIT	SEVERITY
Temperature (°C)	—	75.0	CRITICAL
Humidity (%)	30.0	70.0	WARNING
Ink level (%)	15.0	—	WARNING
Paper stock (%)	10.0	—	INFO
Motor RPM (rpm)	—	13500.0	WARNING
Vibration (mm/s)	—	5.5	CRITICAL
Power (kW)	—	51.3	WARNING
Paper jams (count)	—	2.0	CRITICAL

SENSOR PERFORMANCE SUMMARY

SENSOR (UNIT)	MIN	AVG	MAX	LAST VALUE	BREACH READINGS
Temperature (°C)	38.7	45.92	53.5	39.4	0
Humidity (%)	36.9	49.65	85.0	53.1	40
Ink level (%)	17.8	36.99	79.6	17.8	0
Paper stock (%)	22.1	41.00	62.9	22.1	0
Motor RPM (rpm)	0.0	5473.73	11439.0	195.0	0
Vibration (mm/s)	0.1	1.18	2.4	0.2	0
Power (kW)	3.0	21.73	66.3	4.0	14
Throughput (ppm)	0.0	76.81	168.0	0.0	0
Paper jams (count)	0.0	0.05	5.0	0.0	8

ANOMALY DETECTION SUMMARY

Labelled anomalous readings	75 of 864 readings (8.7%)
Raw threshold-breach readings	62 readings with at least one sensor out of bounds
Anomaly types	INK_LEAK_DROP: 8 · PAPER_JAM_BURST: 13 · POWER_SURGE: 14 · HUMIDITY_SPIKE: 40
Detected anomaly events	236 fired by the live detector (window=3 consecutive readings), last at 2026-10-16 00:55:00
Alerts in alerts.csv	62 total · 8 CRITICAL

Counts intentionally differ: labelled readings are dataset ground-truth episodes; breach readings are raw out-of-bounds values; detected events are spawned only after one metric stays out of bounds for 3 consecutive readings.

SENSOR PERFORMANCE GRAPHS

TEMPERATURE OVER TIME (°C)



173 plotted readings · red dots = labelled anomaly also breaching this sensor's limit

VIBRATION OVER TIME (MM/S)



173 plotted readings · red dots = labelled anomaly also breaching this sensor's limit

MOTOR RPM OVER TIME (RPM)



173 plotted readings · red dots = labelled anomaly also breaching this sensor's limit

ALERT HISTORY

TIMESTAMP	METRIC	VALUE	THRESHOLD	SEVERITY	MESSAGE
2026-10-16 15:15	humidity_pct	85.0	70.0	WARNING	Humidity above limit
2026-10-16 15:10	humidity_pct	81.4	70.0	WARNING	Humidity above limit
2026-10-16 15:05	humidity_pct	84.1	70.0	WARNING	Humidity above limit
2026-10-16 15:00	humidity_pct	81.5	70.0	WARNING	Humidity above limit
2026-10-16 14:55	humidity_pct	82.0	70.0	WARNING	Humidity above limit
2026-10-16 14:50	humidity_pct	82.6	70.0	WARNING	Humidity above limit
2026-10-16 14:45	humidity_pct	79.9	70.0	WARNING	Humidity above limit
2026-10-16 14:40	humidity_pct	80.4	70.0	WARNING	Humidity above limit
2026-10-16 14:35	humidity_pct	78.3	70.0	WARNING	Humidity above limit
2026-10-16 14:30	humidity_pct	79.1	70.0	WARNING	Humidity above limit
2026-10-16 14:25	humidity_pct	77.8	70.0	WARNING	Humidity above limit
2026-10-16 14:20	humidity_pct	78.0	70.0	WARNING	Humidity above limit
2026-10-16 14:15	humidity_pct	77.6	70.0	WARNING	Humidity above limit
2026-10-16 14:10	humidity_pct	76.6	70.0	WARNING	Humidity above limit
2026-10-16 14:05	humidity_pct	77.1	70.0	WARNING	Humidity above limit
2026-10-16 14:00	humidity_pct	75.2	70.0	WARNING	Humidity above limit
2026-10-16 13:55	humidity_pct	75.5	70.0	WARNING	Humidity above limit
2026-10-16 09:50	humidity_pct	84.0	70.0	WARNING	Humidity above limit
2026-10-16 09:45	humidity_pct	84.4	70.0	WARNING	Humidity above limit
2026-10-16 09:40	humidity_pct	83.5	70.0	WARNING	Humidity above limit
2026-10-16 09:35	humidity_pct	82.1	70.0	WARNING	Humidity above limit
2026-10-16 09:30	humidity_pct	81.8	70.0	WARNING	Humidity above limit

Showing latest 22 of 62 alerts, newest first. The full history is available in alerts.csv.

SUMMARY & RECOMMENDATIONS

This printer shows an elevated labelled-anomaly rate of 8.7% against a fleet-wide 6.0%.

Power draw exceeded its limit on 14 reading(s) (limit 51.3 kW, max seen 66.3 kW). Recommend checking electrical load and supply stability.

Humidity fell outside the 30–70% band on 40 reading(s). Recommend reviewing site climate control.

Paper jams exceeded 2 per interval on 8 reading(s). Recommend checking feed rollers and media quality.

Note: recommendations are rule-based responses to threshold breaches present in the monitored data. They are maintenance suggestions, not confirmed diagnoses.