Individual Printer Performance and Anomaly Report

EPR-002

Offset Press B · HeidelPress XL-106 · Plant 1 - Hall A

PRINTER INFORMATION

Printer ID	EPR-002
Printer name	Offset Press B
Model	HeidelPress XL-106
Machine type	Offset
Location	Plant 1 - Hall A
Installed	2020-02-11
Last recorded status	IDLE
Status mix over period	IDLE 442, PRINTING 413, OFFLINE 9
Total telemetry readings	864
Monitoring period	2026-10-15 00:00:00 to 2026-10-17 23:55:00
Report generated	2026-10-26 13:43:37.774

CONFIGURED SENSOR THRESHOLD LIMITS

SENSOR	LOWER LIMIT	UPPER LIMIT	SEVERITY
Temperature (°C)	—	75.0	CRITICAL
Humidity (%)	30.0	70.0	WARNING
Ink level (%)	15.0	—	WARNING
Paper stock (%)	10.0	—	INFO
Motor RPM (rpm)	—	13500.0	WARNING
Vibration (mm/s)	—	5.5	CRITICAL
Power (kW)	—	50.6	WARNING
Paper jams (count)	—	2.0	CRITICAL

SENSOR PERFORMANCE SUMMARY

SENSOR (UNIT)	MIN	AVG	MAX	LAST VALUE	BREACH READINGS
Temperature (°C)	40.0	46.79	54.7	40.9	0
Humidity (%)	36.5	47.96	59.5	51.9	0
Ink level (%)	9.1	70.35	92.8	86.8	2
Paper stock (%)	39.3	56.92	77.9	39.3	0
Motor RPM (rpm)	0.0	5514.16	15519.0	299.0	23
Vibration (mm/s)	0.1	1.20	2.5	0.2	0
Power (kW)	3.0	20.14	40.5	4.2	0
Throughput (ppm)	0.0	74.59	165.8	0.0	0
Paper jams (count)	0.0	0.01	1.0	0.0	0

ANOMALY DETECTION SUMMARY

Labelled anomalous readings	44 of 864 readings (5.1%)
Raw threshold-breach readings	25 readings with at least one sensor out of bounds
Anomaly types	MOTOR_OVERSPEED: 23 · INK_LEAK_DROP: 12 · OFFLINE: 9
Detected anomaly events	133 fired by the live detector (window=3 consecutive readings), last at 2026-10-17 20:35:00
Alerts in alerts.csv	34 total · 9 CRITICAL

Counts intentionally differ: labelled readings are dataset ground-truth episodes; breach readings are raw out-of-bounds values; detected events are spawned only after one metric stays out of bounds for 3 consecutive readings.

SENSOR PERFORMANCE GRAPHS

TEMPERATURE OVER TIME (°C)



171 plotted readings · red dots = labelled anomaly also breaching this sensor's limit

VIBRATION OVER TIME (MM/S)



171 plotted readings · red dots = labelled anomaly also breaching this sensor's limit

MOTOR RPM OVER TIME (RPM)



171 plotted readings · red dots = labelled anomaly also breaching this sensor's limit

ALERT HISTORY

TIMESTAMP	METRIC	VALUE	THRESHOLD	SEVERITY	MESSAGE
2026-10-17 20:35	heartbeat	—	—	CRITICAL	Device offline — no telemetry received
2026-10-17 20:30	heartbeat	—	—	CRITICAL	Device offline — no telemetry received
2026-10-17 20:25	heartbeat	—	—	CRITICAL	Device offline — no telemetry received
2026-10-17 20:20	heartbeat	—	—	CRITICAL	Device offline — no telemetry received
2026-10-17 20:15	heartbeat	—	—	CRITICAL	Device offline — no telemetry received
2026-10-17 20:10	heartbeat	—	—	CRITICAL	Device offline — no telemetry received
2026-10-17 20:05	heartbeat	—	—	CRITICAL	Device offline — no telemetry received
2026-10-17 20:00	heartbeat	—	—	CRITICAL	Device offline — no telemetry received
2026-10-17 19:55	heartbeat	—	—	CRITICAL	Device offline — no telemetry received
2026-10-17 05:55	ink_level_pct	9.1	15.0	WARNING	Ink level low
2026-10-17 05:50	ink_level_pct	13.9	15.0	WARNING	Ink level low
2026-10-16 09:30	motor_rpm	13988.0	13500.0	WARNING	Motor speed above limit
2026-10-16 09:25	motor_rpm	14072.0	13500.0	WARNING	Motor speed above limit
2026-10-16 09:20	motor_rpm	14453.0	13500.0	WARNING	Motor speed above limit
2026-10-16 09:15	motor_rpm	13909.0	13500.0	WARNING	Motor speed above limit
2026-10-16 09:10	motor_rpm	15192.0	13500.0	WARNING	Motor speed above limit
2026-10-16 09:05	motor_rpm	14998.0	13500.0	WARNING	Motor speed above limit
2026-10-16 09:00	motor_rpm	14789.0	13500.0	WARNING	Motor speed above limit
2026-10-16 08:55	motor_rpm	15155.0	13500.0	WARNING	Motor speed above limit
2026-10-16 08:50	motor_rpm	15120.0	13500.0	WARNING	Motor speed above limit
2026-10-16 08:45	motor_rpm	13919.0	13500.0	WARNING	Motor speed above limit
2026-10-16 08:40	motor_rpm	14677.0	13500.0	WARNING	Motor speed above limit

Showing latest 22 of 34 alerts, newest first. The full history is available in alerts.csv.

SUMMARY & RECOMMENDATIONS

This printer shows a labelled-anomaly rate of 5.1%, in line with the fleet-wide 6.0%.

Motor speed exceeded its limit on 23 reading(s) (limit 13500 rpm, max seen 15519 rpm). Recommend verifying drive settings and motor load.

Ink level dropped below the 15.0% floor on 2 reading(s) (min seen 9.1%). Recommend scheduling ink replenishment.

9 reading(s) were logged with the machine OFFLINE. Recommend investigating connectivity or power availability during those windows.

Note: recommendations are rule-based responses to threshold breaches present in the monitored data. They are maintenance suggestions, not confirmed diagnoses.