Individual Printer Performance and Anomaly Report

EPR-006

Cover Press · HeidelPress CD-74 · Plant 2 - Hall A

PRINTER INFORMATION

Printer ID	EPR-006
Printer name	Cover Press
Model	HeidelPress CD-74
Machine type	Offset
Location	Plant 2 - Hall A
Installed	2019-06-15
Last recorded status	IDLE
Status mix over period	IDLE 427, PRINTING 437
Total telemetry readings	864
Monitoring period	2026-10-15 00:00:00 to 2026-10-17 23:55:00
Report generated	2026-10-26 13:43:38.261

CONFIGURED SENSOR THRESHOLD LIMITS

SENSOR	LOWER LIMIT	UPPER LIMIT	SEVERITY
Temperature (°C)	—	72.0	CRITICAL
Humidity (%)	30.0	70.0	WARNING
Ink level (%)	15.0	—	WARNING
Paper stock (%)	10.0	—	INFO
Motor RPM (rpm)	—	11000.0	WARNING
Vibration (mm/s)	—	5.0	CRITICAL
Power (kW)	—	37.8	WARNING
Paper jams (count)	—	2.0	CRITICAL

SENSOR PERFORMANCE SUMMARY

SENSOR (UNIT)	MIN	AVG	MAX	LAST VALUE	BREACH READINGS
Temperature (°C)	37.0	44.70	80.1	38.0	14
Humidity (%)	34.9	47.98	60.4	52.2	0
Ink level (%)	53.9	69.19	86.9	53.9	0
Paper stock (%)	54.0	72.33	92.9	54.0	0
Motor RPM (rpm)	1.0	4378.76	9353.0	230.0	0
Vibration (mm/s)	0.1	1.13	9.6	0.3	19
Power (kW)	2.3	15.61	49.1	4.1	20
Throughput (ppm)	0.0	61.23	136.5	0.0	0
Paper jams (count)	0.0	0.00	1.0	0.0	0

ANOMALY DETECTION SUMMARY

Labelled anomalous readings	61 of 864 readings (7.1%)
Raw threshold-breach readings	53 readings with at least one sensor out of bounds
Anomaly types	POWER_SURGE: 20 · OVERHEAT: 20 · VIBRATION_SPIKE: 21
Detected anomaly events	220 fired by the live detector (window=3 consecutive readings), last at 2026-10-15 12:35:00
Alerts in alerts.csv	53 total · 33 CRITICAL

Counts intentionally differ: labelled readings are dataset ground-truth episodes; breach readings are raw out-of-bounds values; detected events are spawned only after one metric stays out of bounds for 3 consecutive readings.

SENSOR PERFORMANCE GRAPHS

TEMPERATURE OVER TIME (°C)



173 plotted readings · red dots = labelled anomaly also breaching this sensor's limit

VIBRATION OVER TIME (MM/S)



173 plotted readings · red dots = labelled anomaly also breaching this sensor's limit

MOTOR RPM OVER TIME (RPM)



173 plotted readings · red dots = labelled anomaly also breaching this sensor's limit

ALERT HISTORY

TIMESTAMP	METRIC	VALUE	THRESHOLD	SEVERITY	MESSAGE
2026-10-17 13:25	vibration_mm_s	9.1	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 13:20	vibration_mm_s	9.6	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 13:15	vibration_mm_s	8.5	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 13:10	vibration_mm_s	8.6	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 13:05	vibration_mm_s	7.8	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 13:00	vibration_mm_s	8.6	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 12:55	vibration_mm_s	8.4	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 12:50	vibration_mm_s	8.0	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 12:45	vibration_mm_s	7.3	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 12:40	vibration_mm_s	7.5	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 12:35	vibration_mm_s	7.1	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 12:30	vibration_mm_s	6.7	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 12:25	vibration_mm_s	6.9	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 12:20	vibration_mm_s	6.2	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 12:15	vibration_mm_s	6.5	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 12:10	vibration_mm_s	5.7	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 12:05	vibration_mm_s	5.4	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 12:00	vibration_mm_s	5.1	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 11:55	vibration_mm_s	5.1	5.0	CRITICAL	Excessive vibration - inspect bearings
2026-10-17 00:05	temperature_c	80.1	72.0	CRITICAL	Temperature above threshold
2026-10-17 00:00	temperature_c	79.9	72.0	CRITICAL	Temperature above threshold
2026-10-16 23:55	temperature_c	79.6	72.0	CRITICAL	Temperature above threshold

Showing latest 22 of 53 alerts, newest first. The full history is available in alerts.csv.

SUMMARY & RECOMMENDATIONS

This printer shows a labelled-anomaly rate of 7.1%, in line with the fleet-wide 6.0%.

Temperature was out of bounds on 14 reading(s) (limit 72.0 °C, max seen 80.1 °C). Recommend checking the cooling system and ventilation of Plant 2 - Hall A.

Vibration was out of bounds on 19 reading(s) (limit 5.0 mm/s, max seen 9.6 mm/s). Recommend inspecting mechanical components such as bearings, mounts and drive belts.

Power draw exceeded its limit on 20 reading(s) (limit 37.8 kW, max seen 49.1 kW). Recommend checking electrical load and supply stability.

Note: recommendations are rule-based responses to threshold breaches present in the monitored data. They are maintenance suggestions, not confirmed diagnoses.