## Thayer/Smith Residence 1510 Martha Ave. Ann Arbor



Photos on next pages



Muddy area



North wall, east side



North wall



East wall



South wall



West wall