



TWO-FRAME SURVEY TELEMETRY

Defect ID: 948b727f-fdee-4d2e-8e4e-75991f1e2908

Current Scan: 2026-09-15 12:00:00 UTC

Coordinates: 28.613928, 77.209021

Time Delta: Initial Scan (Base Frame)

Two-Frame Spatial-Temporal Comparative Metrics

CURRENT DEFECT AREA

0.4500 m²

Prev: None (Base Frame)

AREA DELTA %

+0.0%

State: New

MUNICIPAL PRIORITY

Rank 8 / 10

Severity: High

Civil Engineering Advisory (Gemini 1.5 Flash)

Root Cause Analysis

Severe asphalt fatigue and moisture seepage under heavy axle loading.

Recommended Remediation

Full-depth asphalt patching and edge drainage restoration.