Bill of Materials

<Parameter Title not found>

Source Data From: DRV8844.PrjPcb

Project: DRV8844.PrjPcb

Variant: None

 Creation Date:
 22-03-2021
 20:35:22

 Print Date:
 22-Mar-21
 8:35:34 PM

Footprint	Comment	LibRef	Designator	Description	Quantity
PCB-	AVX	CMP-126400-3	C1, C3	0805 10nF 100V ±10 % Tol. X7R Surface	
yxmcrvfmg46l	08051C103K4T2		,	Mount Multilayer Ceramic Capacitor	
6n035uvh-1	Α			,	
CAPC1608X	AVX	CMP-175023-2	C4	Cap Ceramic 0.1uF 16V X7R 10% SMD	
90X35LL15T1	Interconnect /			0603 125C Paper T/R	
5	Elco			·	
	0603YC104K4T				
	2A				
CAPC1608X	AVX	CMP-176977-2	C VP3	CAP CER 0.47UF 6.3V 10% X5R 0603	
90X35LL15T1	Interconnect /		_		
5	Elco				
	06036D474KAT				
	2A				
PCB-	Diode	CMP-	D2	Rectifier Diode 1300V 3A DO201AD THT	
7kukp7vedbe		55059cc3e5848			
d875dt9uo-1		ac2-1			
PCB-	Texas	CMP-	DRV8844	5A Brushed DC motor or Quad 1.75A	
0xtv3mcdbyxs	Instruments	e907217fead636		Solenoid/Relay Driver with +/-30V split	
		c0-2		supply support (PWM Ctrl) 28-HTSSOP -40	
				to 85	
PCB-	Molex 22-28-	CMP-	Ground Pins	SERVAL TRIJUMPER	
8kup8qw5vsm	4033	b995709ba24d6			
kearo8v0b-1		652-18			
PCB-	Molex 22-03-	CMP-	IN, JLeft 2	Connector Unshrouded Header 7 Position	
z56b2rsb9v6v		da4b1345c3c30	, 0231_2	2.54mm Solder Straight Thru-Hole Bag	
32i09oxr-1	2011	58c-6, CMP-		2.0 mm Soldor Sudigita mila Holo Bag	
02100074		da4b1345c3c30			
		58c-1			
RESC1608X5	Panasonic ERJ-	CMP-3656259-2	R2	3.3k	
5X30LL15T15	_	0000200 2	142	o.ok	
OXCOLL TOT TO	002100021				
A		Natas			1
Approved		Notes			

Approved Notes





