

AI-Powered Meeting Assistant

Generated Meeting Record

1. Meeting Summary & Minutes

Weekly Hardware Sync Summary

Discussion Points

- * New Sensor Board and UART Module: The team discussed issues with the UART module dropping packets during serial communication.
- * Microcontroller Migration: Speaker 1 proposed switching the main microcontroller to the STM32 model to resolve communication issues, which the team agreed upon.
- * I2C Bus Noise: The team noted noise on the I2C bus and discussed the pull-up resistors.
- * Prototype Demo: The upcoming prototype demo and the need to schedule it and send out calendar invites were briefly discussed.

2. Key Decisions

- Migrate the main microcontroller to the STM32 model to resolve UART packet dropping issues.

3. Action Items

Task 1: Finalize the UART baud rate configuration and set it to 115200

Owner: Sarah

Deadline: This Friday

Task 2: Look into the I2C pull-up resistors to address noise on the I2C bus

Owner: David

Deadline: unspecified

Task 3: Schedule the client demo and send out the calendar invites

Owner: unspecified

Deadline: unspecified