
```
clc
clear screen
close all
```

Plotting the traces of the planes

```
crys_symm=crystalSymmetry('432');
M=Miller(1,0,0,crys_symm);
figure
plot(M,'plane','linecolor','r','linewidth',2)
hold all
startValue = -10;
increment = .5;
% Define the number of iterations
numIterations = 40;
% Initialize the second variable
x = startValue;
% Loop over the specified number of iterations
for i = 1:numIterations
N=Miller(1,0,x,crys symm);
x = x + increment;
plot(N,'plane','linecolor','b','linewidth',2)
hold off
end
```




1. ORIENTATION A (110)[1-12]

```
crys_symm=crystalSymmetry('432');
```

Define orientation using Miller indices

```
n=Miller(1,1,0,'hkl',crys_symm); % plane normal || ND
b=Miller(1,-1,2,'uvw',crys_symm); % rolling direction || RD
ori=orientation.byMiller(n,b);
%%(111) pole figure
m=Miller(1,1,1,crys_symm);
m1=ori*m;
m11=Miller(m1.x,m1.y,m1.z,crys_symm);
%plotx2north
figure
% the normal direction
plot(m,'upper','labeled')
hold on
plot(m11,'upper','labeled')
hold off
```




```
figure
m11=Miller(m1.x,m1.y,m1.z,crys_symm);
plot(m11.symmetrise,'labeled')
```



```
%%(220) pole figure
l=Miller(2,2,0,crys_symm);
l1=ori*1;
```

```
l11=Miller(l1.x,l1.y,l1.z,crys_symm);
%plotx2north
figure
% the normal direction
plot(l,'upper','labeled')
hold on
plot(l11,'upper','labeled')
hold off
```




```
figure
l11=Miller(l1.x,l1.y,l1.z,crys_symm);
plot(l11.symmetrise,'labeled')
```



```
%%(200) pole figure
o=Miller(2,0,0,crys_symm);
o1=ori*o
```

```
o11=Miller(o1.x,o1.y,o1.z,crys_symm);
%plotx2north
figure
```

```
% the normal direction
plot(o,'upper','labeled')
hold on
plot(o11,'upper','labeled')
hold off
```



```
figure
o11=Miller(o1.x,o1.y,o1.z,crys_symm);
plot(o11.symmetrise,'labeled')
```




2. ORIENTATION B (110)[001]

```
crys_symm=crystalSymmetry('432');
```


Define orientation using Miller indices

```
n1=Miller(1,1,0,'hkl',crys_symm); % plane normal || ND
b1=Miller(0,0,1,'uvw',crys_symm); % rolling direction || RD
ori1=orientation.byMiller(n1,b1);
%%(111) pole figure
m=Miller(1,1,1,crys_symm);
m2=ori1*m;
m21=Miller(m2.x,m2.y,m2.z,crys_symm);
%plotx2north
figure
% the normal direction
```


```
plot(m,'upper','labeled')
hold on
plot(m21,'upper','labeled')
hold off
```



```
figure
m21=Miller(m2.x,m2.y,m2.z,crys_symm);
plot(m21.symmetrise,'labeled')
```



```
%%(220) pole figure
l=Miller(2,2,0,crys_symm);
l2=ori1*1;
l21=Miller(l2.x,l2.y,l2.z,crys_symm);
%plotx2north
figure
% the normal direction
plot(1,'upper','labeled')
hold on
plot(l21,'upper','labeled')
hold off
```



```
figure
l21=Miller(l2.x,l2.y,l2.z,crys_symm);
plot(l21.symmetrise,'labeled')
```




```
%%(200) pole figure
o=Miller(2,0,0,crys_symm);
o2=ori1*o
```

```
o2 = vector3d

x y z

0 1.41421 1.41421
```

```
o21=Miller(o2.x,o2.y,o2.z,crys_symm);
%plotx2north
figure
% the normal direction
plot(o,'upper','labeled')
hold on
plot(o21,'upper','labeled')
hold off
```



```
figure
o21=Miller(o2.x,o2.y,o2.z,crys_symm);
plot(o21.symmetrise,'labeled')
```




3. ORIENTATION C (634)[12-3]

```
crys_symm=crystalSymmetry('432');
```

Define orientation using Miller indices


```
n2=Miller(6,3,4,'hkl',crys_symm); % plane normal || ND
b2=Miller(1,2,-3,'uvw',crys_symm); % rolling direction || RD
ori2=orientation.byMiller(n2,b2);
%%(111) pole figure
m=Miller(1,1,1,crys_symm);
m3=ori2*m;
m31=Miller(m3.x,m3.y,m3.z,crys_symm);
%plotx2north
figure
% the normal direction
plot(m,'upper','labeled')
hold on
plot(m31,'upper','labeled')
hold off
```



```
figure
m31=Miller(m3.x,m3.y,m3.z,crys_symm);
plot(m31.symmetrise,'labeled')
```



```
%%(220) pole figure
l=Miller(2,2,0,crys_symm);
l3=ori2*1;
l31=Miller(l3.x,l3.y,l3.z,crys_symm);
%plotx2north
figure
% the normal direction
plot(l,'upper','labeled')
hold on
plot(l31,'upper','labeled')
hold off
```




```
figure
l31=Miller(l3.x,l3.y,l3.z,crys_symm);
plot(l31.symmetrise,'labeled')
```



```
%%(200) pole figure
o=Miller(2,0,0,crys_symm);
o3=ori2*o
```

```
o31=Miller(o3.x,o3.y,o3.z,crys_symm);
%plotx2north
figure
% the normal direction
plot(o,'upper','labeled')
hold on
plot(o31,'upper','labeled')
hold off
```



```
figure
o31=Miller(o3.x,o3.y,o3.z,crys_symm);
```

```
plot(o31.symmetrise, 'labeled')
```




4. ORIENTATION D (001)[100]

```
crys_symm=crystalSymmetry('432');
```

Defining orientation using Miller indices


```
n3=Miller(0,0,1,'hkl',crys_symm); % plane normal || ND
b3=Miller(1,0,0,'uvw',crys_symm); % rolling direction || RD
ori3=orientation.byMiller(n3,b3);
%%(111) pole figure
m=Miller(1,1,1,crys_symm);
m4=ori3*m;
m41=Miller(m4.x,m4.y,m4.z,crys_symm);
%plotx2north
figure
% the normal direction
plot(m,'upper','labeled')
hold on
plot(m41,'upper','labeled')
hold off
```



```
figure
m41=Miller(m4.x,m4.y,m4.z,crys_symm);
plot(m41.symmetrise,'labeled')
```



```
%%(220) pole figure
l=Miller(2,2,0,crys_symm);
l4=ori3*1;
l41=Miller(14.x,14.y,14.z,crys_symm);
%plotx2north
figure
% the normal direction
plot(1,'upper','labeled')
hold on
plot(141,'upper','labeled')
hold off
```




```
figure
l41=Miller(l4.x,l4.y,l4.z,crys_symm);
plot(l41.symmetrise,'labeled')
```



```
%%(200) pole figure
o=Miller(2,0,0,crys_symm);
o4=ori3*o
```

```
o4 = vector3d
x y z
2 0 0
```

```
o41=Miller(o4.x,o4.y,o4.z,crys_symm);
%plotx2north
figure
% the normal direction
plot(o,'upper','labeled')
hold on
plot(o41,'upper','labeled')
hold off
```



```
figure
o41=Miller(o4.x,o4.y,o4.z,crys_symm);
plot(o41.symmetrise,'labeled')
```

