LDR Sensor		
Signal	A0	
VCC	VCC	
GND	GND	
Relay		
VCC	VCC	
GND	GND	
Input	D0	