

Package #35

increase the sensing threshold of the leadless pacemaker to suppress oversensing

Technology Maturity: ENGINEERING_DEFINITION

Transfer Posture: Sponsored Validation

Problem: Pacemaker battery depletion requiring surgical replacement

Mechanism: mechanically mediated device-device interaction causing intermittent oversensing

Contents:

- 01 - Executive Technology Brief
- 02 - Engineering Technology-Transfer Dossier
- 03 - Buyer Decision Card
- 04 - Evidence Summary
- 05 - Transfer Manifest

Status: ENGINEERING_DEFINITION. Not physically validated.