

Package #108

Design hip prosthesis with integrated microchannels that allow for controlled fluid drainage from the bone-implant interface

Technology Maturity: ENGINEERING_DEFINITION

Transfer Posture: Sponsored Validation

Problem: Documented recurring problem 'explanted___loose' for hip prosthesis: 9 MAUDE reports across 8 distinct devices (20090225 to 20090902); root-cause evidence from 20 recall records and 9 event narratives (custody attached in the campaign report). MAUDE limitations: incidence UNKNOWN, causation UNVERIFIED (Art. XXI.5). Existing solutions fail because: Why existing solutions fail, per retrieved evidence: 20 recall root-cause descriptions (FDA enforcement records, custody attached); 9 MAUDE event narratives from this mechanism cluster (mdr_text, custody attached). Statements are the providers' own words, cust Unresolved gap: Across the 0 relevant retrieved attempts (a bounded, non-exhaustive set), none measurably addresses: conditions, devices, events, explanted, failure, function, injury, intervention, introducing, loose, maintain, matching, modes, must, problem, producing, prost

Mechanism: Passive fluid drainage through microchannels in the implant interface

Contents:

- 01 - Executive Technology Brief
- 02 - Engineering Technology-Transfer Dossier
- 03 - Buyer Decision Card
- 04 - Evidence Summary
- 05 - Transfer Manifest

Status: ENGINEERING_DEFINITION. Not physically validated.