

Package #121

Implement multimodality imaging integration (TEE, cardiac CT, [18F]-FDG PET/CT) into the heart valve prosthesis monitoring protocol

Technology Maturity: ENGINEERING_DEFINITION

Transfer Posture: Sponsored Validation

Problem: Documented recurring problem 'insufficient_device_problem_information' for heart valve prosthesis: 18 MAUDE reports across 4 distinct devices (20171025 to 20250513); root-cause evidence from 0 recall records and 10 event narratives (custody attached in the campaign report). MAUDE limitations: incidence UNKNOWN, causation UNVERIFIED (Art. XXI.5). Existing solutions fail because: Why existing solutions fail, per retrieved evidence: 10 MAUDE event narratives from this mechanism cluster (mdr_text, custody attached). Statements are the providers' own words, custody-attached; the aggregation across records is AI_INFERENCE (bounded by the r Unresolved gap: Across the 6 relevant retrieved attempts (a bounded, non-exhaustive set), none measurably addresses: conditions, devices, events, failure, function, injury, insufficient, intervention, introducing, maintain, matching, modes, must, problem, producing, recurring

Mechanism: Diagnostic challenges due to acoustic shadowing on echocardiography

Contents:

- 01 - Executive Technology Brief
- 02 - Engineering Technology-Transfer Dossier
- 03 - Buyer Decision Card
- 04 - Evidence Summary
- 05 - Transfer Manifest

Status: ENGINEERING_DEFINITION. Not physically validated.