

Package #124

Incorporate electrical impedance tomography sensors in venous filter to detect increased pulsatility as an early indicator of flow obstruction

Technology Maturity: ENGINEERING_DEFINITION

Transfer Posture: Sponsored Validation

Problem: Documented recurring problem 'obstruction_of_flow' for venous filter: 9 MAUDE reports across 8 distinct devices (20161117 to 20260505); root-cause evidence from 0 recall records and 9 event narratives (custody attached in the campaign report). MAUDE limitations: incidence UNKNOWN, causation UNVERIFIED (Art. XXI.5). Existing solutions fail because: Why existing solutions fail, per retrieved evidence: 9 MAUDE event narratives from this mechanism cluster (mdr_text, custody attached). Statements are the providers' own words, custody-attached; the aggregation across records is AI_INFERENCE (bounded by the re Unresolved gap: Across the 7 relevant retrieved attempts (a bounded, non-exhaustive set), none measurably addresses: conditions, devices, events, failure, function, injury, intervention, introducing, maintain, matching, modes, must, problem, producing, recurring, reported, un

Mechanism: Regional pulsatility amplitude increases with downstream flow obstruction

Contents:

- 01 - Executive Technology Brief
- 02 - Engineering Technology-Transfer Dossier
- 03 - Buyer Decision Card
- 04 - Evidence Summary
- 05 - Transfer Manifest

Status: ENGINEERING_DEFINITION. Not physically validated.