

Package #111

Implement a reinforced protective sheath around the flow diverter device during manufacturing, handling, and deployment to prevent damage prior to use

Technology Maturity: ENGINEERING_DEFINITION

Transfer Posture: Sponsored Validation

Problem: Documented recurring problem 'device_damaged_prior_to_use' for flow diverter: 15 MAUDE reports across 1 distinct devices (20150722 to 20190110); root-cause evidence from 3 recall records and 10 event narratives (custody attached in the campaign report). MAUDE limitations: incidence UNKNOWN, causation UNVERIFIED (Art. XXI.5). Existing solutions fail because: Why existing solutions fail, per retrieved evidence: 3 recall root-cause descriptions (FDA enforcement records, custody attached); 10 MAUDE event narratives from this mechanism cluster (mdr_text, custody attached). Statements are the providers' own words, cust Unresolved gap: Across the 3 relevant retrieved attempts (a bounded, non-exhaustive set), none measurably addresses: conditions, devices, events, failure, function, intervention, introducing, maintain, malfunction, matching, modes, must, prior, problem, producing, recurring,

Mechanism: Flow diverter placement to redirect blood flow away from aneurysm

Contents:

- 01 - Executive Technology Brief
- 02 - Engineering Technology-Transfer Dossier
- 03 - Buyer Decision Card
- 04 - Evidence Summary
- 05 - Transfer Manifest

Status: ENGINEERING_DEFINITION. Not physically validated.