

Package #109

Incorporate precisely engineered microstructures on intraocular lens surface that manipulate light patterns to promote natural tear film distribution and meibomian gland function

Technology Maturity: ENGINEERING_DEFINITION

Transfer Posture: Sponsored Validation

Problem: Documented recurring problem 'adverse_event_without_identified_device_' for intraocular lens: 17 MAUDE reports across 4 distinct devices (20200512 to 20201224); root-cause evidence from 14 recall records and 10 event narratives (custody attached in the campaign report). MAUDE limitations: incidence UNKNOWN, causation UNVERIFIED (Art. XXI.5). Existing solutions fail because: Why existing solutions fail, per retrieved evidence: 14 recall root-cause descriptions (FDA enforcement records, custody attached); 10 MAUDE event narratives from this mechanism cluster (mdr_text, custody attached). Statements are the providers' own words, cus Unresolved gap: Across the 5 relevant retrieved attempts (a bounded, non-exhaustive set), none measurably addresses: conditions, devices, event, events, failure, function, injury, intervention, introducing, maintain, matching, modes, must, producing, recurring, reported, unde

Mechanism: Passive light manipulation through microstructured surface to enhance tear film stability without active pharmaceutical intervention

Contents:

- 01 - Executive Technology Brief
- 02 - Engineering Technology-Transfer Dossier
- 03 - Buyer Decision Card
- 04 - Evidence Summary
- 05 - Transfer Manifest

Status: ENGINEERING_DEFINITION. Not physically validated.