#### CONTENTS

1	Components	1			
2	2 Software Setup				
	2.1 Icoboard	1			
3 Hardware Setup					
	3.1 4 bit binary input	1			
	3.2 Seven segment display .	2			
	Abstract—This manual provides an introdu	ıction			
to	to Verilog programming using the Icoboard-Lattice				

Download the manual and codes from below link

https://github.com/pratibha444/icoboard

#### 1 Components

The necessary components for this manual are listed in Table

Component	Quantity
Icoboard	1
Raspberry Pi 4	1
Male-Male Jumper Wires	20
Breadboard	1
Seven segment dispaly	1

TABLE I

### 2 Software Setup

### 2.1 Icoboard

FPGA.

For installing icoboard Open a terminal and execute the following commands.

git clone https://github.com/WiringPi/WiringPi
.git
cd WiringPi && ./build
sudo apt install build-essential clang bison
flex libreadline-dev gawk tcl-dev libffidev mercurial graphviz xdot pkg-config
libftdi-dev

#Icoprog

#On termuxarch run as root user

#With termuxarch and pizero, this is the only tool required at the pi

svn co http://svn.clifford.at/handicraft/2015/icoprog

cd icoprog && make install

#Icestorm

#On termuxarch run as normal user without sudo

git clone https://github.com/cliffordwolf/icestorm

cd icestorm && make -j4 && sudo make install

#arachne-pnr

#On termuxarch run as normal user without sudo

git clone https://github.com/cseed/arachne-pnr cd arachne-pnr && make -j4 && sudo make install

**#Yosys** 

#On termuxarch run as normal user without sudo

git clone https://github.com/cliffordwolf/yosys cd yosys && make -j4 && sudo make install

#### 3 Hardware Setup

## 3.1 4 bit binary input

- The hardware connections between the Icoboard and Rasberry Pi 4 are available in below figures.
- In figure 2 and 3 the Icoboard and rasberry pi connections are shown. And fig 4 shows the Rasberry Pi pin configuration.
- Place icoboard on Raspberry Pi 4 and make the connections according to following steps:
- Take the wires and connect them to A5,A2,C3,B4 of the icoboard . These

pins are used to give input manually.

- Similarly make connection to GND pin and 3.3V pin of Icoboard
- Connect GND and 3.3V pin on the bread board
- Give the binary input using input pins .
- For example connect all the input pins to GND pin on bread board
- Now open the terminal give the following commands

cd ICOBOARD
cd codes
cd Binary
make v fname=binary
python binary.py

- The output is displayed on termianal as 0
- Similarly you can change the values.
- If 1 is to be given as input connect it to 3.3V pin and if 0 is to be given as input then connect it to GND pin.

# 3.2 Seven segment display

Make the connections according to the Tabel II.

The pin configuration of seven segment display is shown in fig 1.

• Open the terminal and execute the following commands

cd ICOBOARD
cd codes
cd seven
make v_fname=seven
python seven.py

Seven segment display	Icoboard
a	A5
b	A2
С	C3
d	B4
е	В7
f	В6
g	В3
COM	3.3v

TABLE II




Fig. 1: SSD pin configuration




Fig. 4: RasberryPi pin configuration