Aira3D: 3D Printing Business Mastery

Summary Lecture Companion & Resource Guide

Generated by Aira3D Online Learning Platform | aira3d.com

---

1. Executive Summary & Core Objectives

Welcome to the official reference guide for 3D Printing Business Mastery.
This module consolidates the principles covered across Lesson 1 and Lesson 2,
specifically targeting high-margin desktop manufacturing and prototyping.

2. Slicing Parameters & Quality Benchmarks

Optimal initial layer height: 0.20mm for structural integrity.
Infill settings: 15% to 25% Gyroid infill for maximum strength-to-weight ratio.
Wall loops: 3 perimeters for functional parts; 4 perimeters for pressure tolerance.
Cooling: 100% part fan for PLA after layer 3; 20-30% for PETG.

3. Cost Calculation & Pricing Formula

Unit Selling Price = (Material Cost + Machine Depreciation + Electricity) x 3.5 + Labor.
Target gross margin: Minimum 65% for custom on-demand architectural and mechanical prints.
Client quote turnaround time: Under 4 hours to maximize conversion rates.

4. Next Steps & Recommended Actions

Download the provided slicing templates in the classroom discussion forum.
Proceed to Module 2 to configure advanced multicolor print profiles.
For instructor inquiries, submit your questions under the Discussion & Q&A tab.