②ご請求明細

サービス作業報告書

2022 年 03 月 14 日

No. 2-77251

下記の通り、作業した事を認める。(フルネーム)

御担当者氏名 ㊞

作業区分 [✓ 1 出張作業] 2 出張納品 3 社内作業

有無区分 1 受注 [✓ 2 有償] 3 無償

指図書No.・対策No. ~

訪問先会社名 (コードNo.)		所属部署	
PRICON MICROELECTRONICS, INC. 殿		御担当者	MR. RAFFY ANITAYA 様
請求先会社名 (コードNo.)		所属部署	
Ditto 殿		御担当者	様

出張区域: PHILIPPINES 都道府県 / CABUYAO 郡市区町 / LAGUNA 市

コードNo.	作業担当	営業担当
00124	LIBRADILLA, R	YAMASHITA, K

機種	製造番号	製造年月日
TWIN HOP-G 550	3607616001	2009 年 03 月 02 日

作業内容 再訪問 機種区分 機種 TROUBLESHOOTING / FIXING

- SWING ROBOT TWIN HOP-G 550 EMERGENCY ERROR AND CONTROLLER HARNESS MALFUNCTION
- CONDUCT TROUBLESHOOTING AND FOUND-OUT M-ARM PRODUCT CHUCK SIGNAL WIRE SHORT CIRCUIT
- RE-WIRING CONNECTION AND FIXING -OKAY
- CONTROLLER HARNESS SOME WIRES SHORT CIRCUIT
- FIXING SHORT CIRCUIT - OK
- TRIAL CHECK, CONFIRMATION SIGNAL CHECK-OKAY AND ONE CYCLE CHECK -OKAY

結果 FINISHED

見積りNo. 無償理由

MEMO

NOTE: CONTROLLER HARNESS TEMPORARY FIXING

使用部品内訳 払出部門 001980

受払	No.	部品コードNo.	品名	型式	数量	単価	金額
無	1						
無	2						
無	3						
無	4						
無	5						
無	6						
無	7						
無	8						
無	9						
無	10						
無	11						
無	12						
無	13						
無	14						
無	15						

Emailed
MAR 14 2022

売上日 / 納品書No.

D%

合計金額

作業料金内訳	
基本料金	
部品料金	
出張料金	USD $50
作業料金	USD $180
小計	
消費税	
合計金額	USD $230

作業開始時間	10 時 00 分
作業終了時間	14 時 00 分
作業外時間	▲1 時間 00 分
作業時間	03 時間 00 分

22.3.14

通知No.
指図No.
受注No.

YUSHIN 株式会社ユーシン精機

YUSHIN

YUSHIN PRECISION EQUIPMENT CO.,LTD.
555 Kuzetonoshiro-cho, Minami-ku, Kyoto, 601-8205 JAPAN
TEL: +81-75-933-9555 FAX: +81-75-933-9590

Date:March 14,2022

Pricon Micro Electronics Inc.
Attn:Mr. Aljhon Anonuevo

YPEP-QSC-220314-02A

Quotation

Subject: Service for Yushin Take-out Robot

1 Amount USD $ 230
2 Time of Delivery : Work already done (22.03.14)
3 Place of Delivery : At your factory in Philippines.
4 Terms of Payment : Full payment by T/T within 30 days after shipping out.
5 Delivery duty : Import duty and or any tax shall be borne by buyer.
6 Validity : 60 days.
7 Specification : As below described.

Item	Part No.	Description	Qty	Unit Price (Usd)	Amount (Usd)
1		Supervise Fee including transportation Troubleshooting /Fixing	1 lot	$ 230	$ 230
	Total :		1 lot		$ 230

Note :

a. Any other specification which is not described in the above to be extra.

b. **For TWINHOP-G 550 SN.3607616001 Mfg.2009.03.02**

c. Service Report No.2-77251

Yushin Precision Equipment Co., Ltd.

Rosalio Rañola

for T. INANO
General Manager, Southern Asia Sales Department