② ご請求明細

サービス作業報告書

2022 年 03 月 30 日

No. 2-82283

作業区分	1	出張作業	2	出張納品	3	社内作業
有無区分	1	受注	2	有償	3	無償

指図書No・対策No

下記の通り、作業した事を認める。(フルネーム)

御担当者 氏名 (印)

訪問先会社名 (コードNo)		所属部署		出張区域	都道府県 PHILIPPINES / 市 CABUYAO / 郡区町 LAGUNA
PRICON MICROELECTRONICS, INC 殿		御担当者	JEOMART ABUAN 様		
請求先会社名 (コードNo)		所属部署		コードNo	作業担当 / 営業担当
Ditto 殿		御担当者	様	00124	H.ESCOBIN / K-YAMASHITA

機種	製造番号	製造年月日
① RA-α-70DL	33296101	2005 年 07 月 26 日

作業内容 / 再訪問 / 機種区分 / 機種

- TROUBLESHOOTING

- 1313

- REPLACE SERVO DRIVER FOR MAIN KICK AND SUB ARM ASC/DSC, HOME POSITION SET-OK, TRIAL CHECK-OK, ONE CYCLE CHECK-OK

② ATB-150D SN: 3405359001 MFG: 2006.08.11
- HAVE AN AIR LEAK ON SUB ARM ASC/DSC AND DROP HOLDING CYLINDER, NEED TO REPLACE PARTS AND SPEED CONTROLLER FOR SUB ARM ASC/DSC.

結果 FINISHED

見積No. / 無償理由

MEMO

使用部品内訳 払出部門 001980

受払	No.	部品コードNo	品名	型式	数量	単価	金額
無	1						
無	2						
無	3						
無	4						
無	5						
無	6						
無	7						
無	8						
無	9						
無	10						
無	11						
無	12						
無	13						
無	14						
無	15						

Emailed MAR 3 2022

売上日	納品書No.	D%	合計金額

作業料金内訳

基本料金	
部品料金	
出張料金	USD $ 50
作業料金	USD $ 60
小計	
消費税	
合計金額	USD $ 110

作業開始時間	9 時 30 分
作業終了時間	10 時 30 分
作業外時間	▲ — 時間 — 分
作業時間	1 時間 00 分

				通知No.
				指図No.
				受注No.

223.31

YUSHIN 株式会社ユーシン精機

YUSHIN PRECISION EQUIPMENT CO.,LTD.
555 Kuzetonoshiro-cho, Minami-ku, Kyoto, 601-8205 JAPAN
TEL: +81-75-933-9555 FAX: +81-75-933-9590

Pricon Micro Electronics Inc.
Attn:Mr. Arnold Martinez

Date:March 31,2022

YPEP-QSC-220331-02A

Quotation

Subject: Service for Yushin Take-out Robot

1	Amount	USD $ 110
2	Time of Delivery	Work already done (22.03.30)
3	Place of Delivery	: At your factory in Philippines.
4	Terms of Payment	: Full payment by T/T within 30 days after shipping out.
5	Delivery duty	: Import duty and or any tax shall be borne by buyer.
6	Validity	: 60 days.
7	Specification	: As below described.

Item	Part No.	Description	Qty	Unit Price (Usd)	Amount (Usd)
1		Supervise Fee including transportation Troubleshooting	1 lot	$ 110	$ 110
	Total :		1 lot		$ 110

Note :

a. Any other specification which is not described in the above to be extra.
b. **For RA-a-70DL SN.33296101 Mfg.2005.07.26**
c. Service Report No.2-82253

Yushin Precision Equipment Co., Ltd.

Rosalio Rañola

for T. INANO
General Manager, Southern Asia Sales Department