② ご請求明細

サービス作業報告書

No. 2-84810

2023 年 07 月 20 日

下記の通り、作業した事を認める。(フルネーム)

御担当者 氏名 JEXART ABUAN ㊞

作業区分	1 出張作業	2 出張納品	3 社内作業
有無区分	1 受注	2 有償	3 無償

指図書No.・対策No. ～

訪問先会社名 (コードNo.)	PRICON MICROELECTRONICS, INC 殿	所属部署	
		御担当者	MR. JOE MARK ABUAN 様
請求先会社名 (コードNo.)	Ditto 殿	所属部署	
		御担当者	様

出張区域: PHILIPPINES 都道府県 CABUYAO, 市 LAGUNA 郡市区町

コードNo.	作業担当	営業担当
00124	H. ESCOBIN M.K. LINA C. LAGAN	

機種	製造番号	製造年月日
① SC-70DL	4306148001	2016 年 02 月 26 日

作業内容 | 再訪問 | 機種区分 | 機種

ROBOT CHECKING

CHECKING AIR LEAK

CHECKING OF SOLENOID VALVE, CLEANING OF RUBBER THEN TIGHTENING OF VALVE

NO MORE AIR LEAK, TRIAL CHECK OK

② ATB-150D Sn. 3405359002 MFG 2006.08.11

CHECKING AIRLEAK

CHECKING DROPHOLDING CYLINDER, NEED TO REPLACE
TEMPORARILY REMOVE DROPHOLDING CYUNDER TO STOP THE NOISE

結果 FINISH

見積りNo. 無償理由

MEMO NEED QUOTATION FOR DROPHOLDING CYLINDER OF SUB ARM

使用部品内訳 払出部門 001980

受払	No.	部品コードNo.	品名	型式	数量	単価	金額
無	1						
無	2						
無	3						
無	4						
無	5						
無	6						
無	7						
無	8						
無	9						
無	10						
無	11						
無	12						
無	13						
無	14						
無	15						

売上日	納品書No.	D%	合計金額

作業料金内訳

基本料金	
部品料金	
出張料金	USD 50
作業料金	USD 60
小計	
消費税	
合計金額	USD 110

作業開始時間	13 時 00 分
作業終了時間	14 時 00 分
作業外時間	▲ 0 時間 00 分
作業時間	1 時間 00 分

通知No.	
指図No.	
受注No.	

YUSHIN 株式会社ユーシン精機

YUSHIN PRECISION EQUIPMENT CO.,LTD.
555 Kuzetonoshiro-cho, Minami-ku, Kyoto, 601-8205 JAPAN
TEL: +81-75-933-9555 FAX: +81-75-933-9590

Pricon Micro Electronics Inc.
Attn:Mr.Joemart Abuan

Date:July 25,2023

YPEP-QSC-230725-02A

Quotation

Subject: Service for Yushin Take-out Robot

1	Amount	USD $ 110
2	Time of Delivery	Work already done (23.07.20)
3	Place of Delivery	: At your factory in Philippines.
4	Terms of Payment	: Full payment by T/T within 30 days after shipping out.
5	Delivery duty	: Import duty and or any tax shall be borne by buyer.
6	Validity	: 60 days.
7	Specification	: As below described.

Item	Part No.	Description	Qty	Unit Price (Usd)	Amount (Usd)
1		Supervise Fee including transportation Robot Checking	1 lot	$ 110	$ 110
	Total :		1 lot		$ 110

Note :

a. Any other specification which is not described in the above to be extra.
b. **For SC-70DL SN.4306148001 Mfg.2016.02.26**
c. Service Report No.2-84810

Yushin Precision Equipment Co.,Ltd

Camille Suarez

T. INANO
General Manager, Southern Asia Sales Department