② ご請求明細

サービス作業報告書

No. 2-84999

2023年 06月 14日

下記の通り、作業した事を認める。(フルネーム)

御担当者 氏名 ㊞

作業区分	1 出張作業	2 出張納品	3 社内作業
有無区分	1 受注	2 有償	3 無償

指図書No.・対策No. ~

訪問先会社名 (コードNo.)		所属部署	
PRICON MICROELECTRONICS, INC. 殿		御担当者	MR. JOEMART ABUAN 様
請求先会社名 (コードNo.)		所属部署	
Ditto 殿		御担当者	様

出張区域: PHILIPPINES 都道府県 CABUYAO 市 LAGUNA 郡市区町

コードNo.	作業担当	営業担当
00124	H. ESCOBIN	K. YAMASHITA

機種	製造番号	製造年月日
① RA-α-70DL MC. 20	33296102	2005年 07月 26日

作業内容 | 再訪問 | 機種区分 | 機種

- ROIBOT CHECKING

- VACUUM AND BLOW NO FUNICTION
- CHECK CONNECTION AND SOLENOID VALVE,
- FOUND OUT THAT VACUUM SENSOR 1 AND 4 ARE DEFECTIVE AND CONVUM 1 AND 3 ARE DEFECTIVE, AND BLOW SPEED CONTROLLER DEFFECTIVE.

② RA-α-70DL SN: 33296101 MFG: 2005.07.26 MC. 7C
- CONVUM 3 HAVE DEFFECTIVE

結果 | THE APPEARANCE IS SEEN

見積りNo. | 無償理由

MEMO | NOTE: NEED QUOTATION FOR CHANGING OF PARTS

使用部品内訳 払出部門 001980

受払	No.	部品コードNo.	品名	型式	数量	単価	金額
無	1						
無	2						
無	3						
無	4						
無	5						
無	6						
無	7						
無	8						
無	9						
無	10						
無	11						
無	12						
無	13						
無	14						
無	15						

売上日	納品書No.	D%	合計金額

作業料金内訳

基本料金	
部品料金	
出張料金	USD $ 50
作業料金	USD $ 120
小計	
消費税	
合計金額	USD $ 170

作業開始時間	9 時 30 分
作業終了時間	11 時 30 分
作業外時間	▲ — 時間 — 分
作業時間	2 時間 00 分

通知No.	
指図No.	
受注No.	

YUSHIN 株式会社ユーシン精機

YUSHIN PRECISION EQUIPMENT CO.,LTD.
555 Kuzetonoshiro-cho, Minami-ku, Kyoto, 601-8205 JAPAN
TEL: +81-75-933-9555 FAX: +81-75-933-9590

Pricon Micro Electronics Inc.
Attn:Mr.Joemart Abuan

Date:June 15,2023

YPEP-QSC-230615-02A

Quotation

Subject: Service for Yushin Take-out Robot

1	Amount	USD $ 170
2	Time of Delivery	Work already done (23.06.14)
3	Place of Delivery	: At your factory in Philippines.
4	Terms of Payment	: Full payment by T/T within 30 days after shipping out.
5	Delivery duty	: Import duty and or any tax shall be borne by buyer.
6	Validity	: 60 days.
7	Specification	: As below described.

Item	Part No.	Description	Qty	Unit Price (Usd)	Amount (Usd)
1		Supervise Fee including transportation Robot Checking	1 lot	$ 170	$ 170
	Total :		1 lot		$ 170

Note :

a. Any other specification which is not described in the above to be extra.
b. **For RA-a- 70DL MC .20 SN.33296102 Mfg.2005.07.26**
c. Service Report No.2-84999

Yushin Precision Equipment Co., Ltd.

Rosalie Rañola

for T. INANO
General Manager, Southern Asia Sales Department