To : Y E C	From : PPS-TS Grinding	Priority (A) B C
Attn : Mr. Nozaki	Edison Jr. Valencia	

PMI-LISP PLANT
MACHINE PARTS RENEWAL
PROCEDURE REQUEST LIST
設備修理費用依頼書

Issue No. 発行No.	PPS-TS-230303-124	
Date 発行日	3-Mar-2023	
APP. BY 承認		PREP. BY 作成
Edison Jr. Valencia PPS Manager		Nolasco Mendoza PPS Sr. Engr.

1. Equipment Details

Machine Number 号機	CNC Machine # 5	メーカー Machine Maker	TSUGAMI	
Model No. 形式	VA1-2	機番 Serial No.	10113A	
Machine Tons 成形機大きさ	n/a	No. of Years	9 years and 3 months	YRS
Machine Arrived 購入年日	2014/12/11	Total Utilization hrs	52,569	HRS

2. Equipment Condition 設備状況

2-1. Equipment /Maintenance Inspection Result

Replaced X- axis bearing

Affected Machine Parts:

No.	Machine Parts	Last Date Installed	Remarks
1	Ballscrew(R25-10K4-FSC-432-543-0.05)	First time replacement	No history of parts replacement
2	Ballscrew support bearing		
3	Deep groove ball bearing 60022LLU		
4	Installations charges		

SIGN: N. Mendoza

2-2. Machine problem summary

PROBLEM ENCOUNTERED :

Backlash on X-axis 0.025mm error

SIGN: E. Valencia

2-3. Machine assessment

- [x] MACHINE STATUS : Machine still Ok to use but limited product only
- [x] RECOMMENDATION: Replacement of Ballscrew
- [x] ATTACHMENT:

SIGN: Mr. Joel C. Padullo

3. YEC IN-CHARGE (YEC担当)

SIGN(承認): Mr. Satoshi Iizumi

YEC ANSWER COLUMN 国内回答欄	製造部		佐倉事業所	
Equipment repair cost 1st judgment date 設備修理費1次判定日( )	IN-CHARGE 担当	☑ 1st Approval 承認 ☐ Disapproved未承認	☑ Final Approval 承認	☐ Disapproved 未承認
ROUTE ルート PMI LISP ~~YEC~~ PMI ~~LISP~~	Mr. Nozaki	Mr. Itou	Mr. Tsuchiya	Mr. Tsuchiya