SERVICE REPORT

JOB NO : 2727 0 1 - 0 0 1 4 8

Customer PRICON MICROELECTRONICS INC.	Date 01-AUGUST-2016
Person-In Charge MR. GAMBOA Dept ENGG.	P.O. No
Tel Fax	Remark SV-1608002

Job Title MACHINE CHECKING

Model NCI-45(2) S/No 10204-7197 Instal/Date 1994 (MFD.)

Problem 1. MACHINE CAN'T OPERATIONAL RUNNING.

NOTE:
1. THIS AIDA SPARED PART THAT CUSTOMER BORROWED, CUSTOMER NEED TO SEND PURCHASE ORDER (P.O.) ON OR BEFORE ONE WEEK AFTER QUOTATION SEND TO CUSTOMER.

Measures
1. DUE TO AUXILIARY RELAY OR IO STUCK-UP.
2. REPLACEMENT OF THE AUXILIARY RELAY (AIDA SPARED PART).
3. MACHINE TEST RUNNING, CHECKING THE OPERATIONAL AND SAFETY INTERLOCKS ALL-FUNCTIONING.

Date	Man	Dep	AIDA	Arv	Cus	Dep	Cus	Arv	AIDA	Normal	1½	2	Job Done by
01 AUG		10	30	11	30	17	30	19	00	6			GEORGE

SPARE PART	Qty	U/Price	Amount	Remark
				1. CUSTOMER NEED TO BUY SPARED PARTS TO AVOID LONGTIME BREAKAGES OF MACHINE.
LABOUR CHARGES [NORMAL]	6	USD 25	USD 150	
[1½]				Authorised / Confirm / Incharge
[2]				
TRANSPORT	1	USD 25	USD 25	
PACKING & DELIVERY CHARGE				
VAT				
TOTAL			USD 175	

Work carried out to our complete satisfaction

CHARGEABLE

Checked & confirmed by
Name ERICK GAMBOA
Post SR. ENGINEER
Sign
Date 08-01-16

Company Name/Stamp

G. ANIPE, JR. M.

AIDA GREATER ASIA PHILIPPINES, INC.

CUSTOMER COPY