SERVICE REPORT

JOB NO : 2727 01-00498

Customer PRICON MICROELECTRONICS INC.	Date SEPTEMBER 28, 2018
Person-In Charge MR. E. GAMBOA Dept ENG'G.	P.O. No 12124
Tel (02) 643-0870 Fax (049) 549-3164	Remark SV-180901GR1

Job Title MACHINE CHECKING

Model NCI-80(2) S/No 10208-8797 Instal/Date 1994 (MFD)

Problem 1. OVER RUN FAULT CAN'T RESET.

Measures
1. DR4 UNIT ALREADY BROKEN NEED TO CHANGE.
2. THE AOP CONTROLLER AND GREASE PUMP NEED TO CHANGE DUE TO MALFUNCTIONING.
3. THE EMERGENCY STOP BUTTON BROKEN NEED TO CHANGE.
4. NOW PRESS MACHINE CONDITION CAN'T OPERATION RUNNING DUE TO BROKEN PARTS NEED TO CHANGE.

Date	Man	Dep	AIDA	Arv	Cus	Dep	Cus	Arv	AIDA	Normal	1½	2	Job Done by
Friday 28 SEPT.		07	00	08	30	14	30	15	30	10			GEORGE, RENAN

SPARE PART	Qty	U/Price	Amount
LABOUR CHARGES [NORMAL]	10	USD 25	USD 250
[1½]			
[2]			
TRANSPORT	1	USD 25	USD 25
PACKING & DELIVERY CHARGE			
VAT			
TOTAL			USD 275

Remark
1. ALMOST ALL AUXILIARY RELAY NEED TO CHANGE.
2. TIMER'S AND MAGNETIC CONTACTORS, ROTARY LIMIT SWITCH I RECOMMENDE TO CHANGE DUE TO POOR CONDITION OF THE SAID PARTS.

Authorised	Confirm	Incharge
		GEORGE

Work carried out to our complete satisfaction

CHARGEABLE

Checked & confirmed by
Name ERICK GAMBOA
Post SR ENGINEER
Sign
Date 09-28-18

Company Name/Stamp

AIDA GREATER ASIA PHILIPPINES, INC.

CUSTOMER COPY